

# PROPERTY

#### Prepared Exclusively For: Garrett Brown



Property Located At: Railway Ave Kayville, SK

**Inspection Date:** 19/08/2020

Inspected By: Scott Mackay

Report #: 190820



# **CONTRACT / RECEIPT**

		File #: 1908	820		
Inspection Address:	Railway Ave Kayville, SK				
Date: Weather conditions at time	19/08/2020 of inspection: 29 degrees	Start Time:	8:00am	Finish time:	10:00am
Type of house/residence; gr Client(s) Name(s):	rain elevator <b>Garrett Brown</b>	Approx. Age:			
Mailing Address:		A			
City:		Postal (	Code:		
Phone # Home:		Busine	ess #:		
Phone # Cell:		E-mail Add	dress:		

CONTRACT

I/we, the above named client(s) request an inspection of the inspection address noted above. The inspection is to be performed by the below noted inspection company (firm) in accordance with industry accepted Standards of Practice.

It is important for the client(s) to understand that the inspection is based on the limited visual inspection of the readily accessible aspects of the building. The report is representative of the inspector's opinion of the observable conditions on the day of the inspection. While this inspection may reduce your risks of home ownership, it is not an insurance policy, warranty or guarantee on the home. Neither the inspector nor the inspection firm will assume any risks related to this home's future performance, or lack thereof. This report is for the exclusive use of the contracted parties and may not be used by third parties without the prior written permission from the inspector/inspection firm.

#### I / we have read, understand and accept the terms & conditions as outlined here and on the page entitled "What You Should Expect from Your Inspection". Please initial here

The Client(s), by signing below, agree to have read, understand and accept the terms of this contract.

Client(s)/Representative Signature(s) \_\_\_\_\_ Date: 19/08/2020

If Client(s) is (are) represented, please print name of representative.

			RECEIPT
Base Fee	\$800.00	Inspection Firm	Admiral Home Inspections Ltd.
Other		Inspectors Name	
Тах	\$40.00	Inspector Number (if applicable)	
Total Fee	\$840.00	Payment Form	
		Received By	
		(Signature)	



# WHAT TO EXPECT FROM YOUR HOME INSPECTION

1. **Purpose**: The purpose of the inspection is to attempt to detect the presence of home defects by performing a visual inspection of the property and it is a snapshot of the condition of the home today at the time of inspection. This report will not address environmental concerns or provide cost estimates.

2. **Scope**: The scope of the inspection is limited to the readily accessible areas of the property and is based on the condition of the property at the precise time and date of the inspection. Things can and do change and a home inspection will not stop these changes from occurring. Furthermore, as such, the report is not a guarantee or warranty that hidden defects do or do not exist. As a courtesy the INSPECTION COMPANY may point out conditions that contribute to possible home problems/defects but such comments are not part of the final report.

3. **Report**: The CLIENT will be provided with a written report of the INSPECTION COMPANY'S visual observations. The INSPECTION COMPANY is not able to determine all deficiencies from visual observations alone. Some deficiencies may go unnoted in the report and the client accepts this. The report is not intended to comply with any legal obligations to disclosure. The Home Inspector is a Generalist, not a specialist in all disciplines.

4. **Exclusivity**: The report is intended for the sole, confidential and exclusive use and benefit of the CLIENT and the INSPECTION COMPANY has no obligation or duty to any other party. The INSPECTION COMPANY accepts no responsibility for use by third parties. There are no third party beneficiaries to this agreement. This Agreement is not transferable or assignable. Notwithstanding the foregoing, the CLIENT understands that the INSPECTION COMPANY may notify the homeowner, occupant, or appropriate public agency of any condition(s) discovered that may pose a safety or health concern. Inspection is not Building code or By-Law compliance.

5. **Limitation of Liability**: It is understood the INSPECTION COMPANY and its associates are not insurers and that the inspection report shall not be construed as a guarantee or warranty of any kind. The CLIENT agrees to hold the INSPECTION COMPANY and their respective officers, agents and employees harmless from and against any and all liabilities, demands, claims, and expenses incident thereto for injuries to persons and for loss of, damage to, destruction of property, cost of repairing or replacing, or consequential damage arising out of or in connection with this inspection.

6. **Major Problems**: The purpose of the Home Inspection is to find and identify visible existing major problems apparent on the visual inspection of the home. Home Inspectors can greatly reduce the risk of a home purchase but it is impossible to totally eliminate the risk.

7. **Litigation:** The parties agree that any litigation arising out of this Agreement shall be filed only in the Court having jurisdiction in the Province in which the INSPECTION COMPANY has its principal place of business. If the INSPECTION COMPANY is the substantially prevailing party in any such litigation, the CLIENT shall pay all legal costs, expenses and attorney's fees of the INSPECTION COMPANY in defending said claims.

8. **Environmental Concerns**: The inspection will NOT address environmental concerns including, but not limited to: air quality, water quality/quantity, sealed/underground fuel storage tanks, UFFI, asbestos, radon gas, molds, toxins, etc. The inspection report will also NOT address infestation by wood boring insects, rodents or other vermin. The CLIENT understands and acknowledges that it may be necessary to call on specialists in these areas to identify and evaluate these risks.

Entire Agreement: This Agreement represents the entire agreement between the PARTIES. No statement or promise made by the INSPECTION COMPANY or its respective officers, agents or employees shall be binding.
 Standards of Practice: The inspection shall be completed in accordance within the CanNACHI Standards of Practice and Codes of Ethics.

#### The client is strongly advised to clarify anything that they don't understand.



			1. ROOFING
#	SOP	>	COMPONENTS: DESCRIPTION & COMMENTS
101	•	>	Main Roof:       □ shingles       □ asphalt       □ wood       □ clay       □ slate       □ concrete       ✓ metal       □ rubber         approx. age of roof covering ?? years - according to       □ roof tune-up recommended
102	•	~	Lower Roof: □ shingles □ asphalt □ wood □ clay □ slate □ concrete ✓ metal □ rubber approx. age of roof covering ?? years - according to □ roof tune-up recommended
103	•	_	Flat Roof:
104	•	~	Flashings:
105	•	_	Roof Penetrations:
106	•	_	Skylights:
107	•	_	Chimneys:
108	•	~	Gutters & Downspouts: discharge method: ✓ on ground □ below ground □ recommend downspout extension 4 to 6 feet away from house
109	•	~	Evidence of water penetration <pre></pre>
			COMMENTS:  See ADDITIONAL COMMENTS Sheet



## **ROOFING PHOTOGRAPHS**



Metal roofing on lower office roof





Main upper elevator roof



Roofing from interior-main upper roof

#### South lower roof

Roofing Conditions & Limitations: Roof inspected by: I ladder at edge ✓ binoculars walking on ✓ visual

□ Restricted/No access to:

Inspection restricted due to
 Height
 Slope
 Snow / Ice
 Rain/Wet
 Trees
 Potential danger / damage

☑ This report is an opinion of the general quality and condition of the roofing. As such the inspector cannot and does not offer an opinion or warranty as to whether the roof has leaked in the past, leaks now or is subject to future leakage. ☑ Gutters, downspouts and subsurface drains are not water tested for leakage or blockage. These components require regular maintenance to avoid water problems at the roof and foundation.

SOP	Standards of Practice: CanNACHI		Inspected	Date: 19/08/2020
•	<ul> <li>Observe and Report on Systems &amp; Components</li> </ul>		Not Inspected	Inspector Initials:
	Perform Tasks noted in SOP	-	Not Applicable	Client Initials:



			2. EXTERIOR
#	SOP	~	<b>COMPONENTS: DESCRIPTION &amp; COMMENTS</b>
201	•	*	Wall Surfaces: Dirick vinyl aluminum wood stone stucco fibre board missing
202	•	~	Exterior Foundation Wall: cracks:
203	•	~	Eaves, Soffits & Fascia:
204	•	~	Entryway Doors, Flashing & Trim: main door: □ metal ✓ wood other door(s): □ metal ✓ wood □ sliding glass damage
205	•	~	Windows, Flashing & Trim: frames: □ metal □ vinyl ✓ wood panes: □ single ✓ double damage -
206	•	_	Window Wells: <ul> <li>recommend window well covers</li> </ul>
207	•	-	<b>Garages:</b> main door(s):
208	•	—	Carports:
209	•	_	Porches: Concrete wood other
210	•	-	Decks: Concrete wood other
211	•	-	Balconies:
212	•	~	Stairs: damage-deterioration
213	•	~	Guard Rails & Hand Railings:
214	•	-	Grading:
215	•	-	Vegetation:
216	•	~	Retaining Walls: leaning - damage
217	•	—	Patios / Walkways: Concrete Casphalt paving/patio stones
218	•	_	<b>Driveways:</b> Concrete asphalt paving/patio stones other
			COMMENTS:   See ADDITIONAL COMMENTS Sheet
#204 #05- #212 #216	- damage 2 broken ( - damage/ - broken/le	to larg office deteri eaning	nissing siding near overhead door, recommend repair to prevent deterioration to wood. ge overhead door track at top and bottom, recommend repair for safety and intended operation. window, recommend repair for safety. ioration to steps and landing structure at south side entrance to office, recommend repair for safety. g retaining wall on north side of main driveway to elevator, recommend monitor and contractor to address vent further movement.



## **EXTERIOR PHOTOGRAPHS**



Leaning driveway retaining wall



Damage/deterioration to wood steps structure/landing at entrance to office



Damage to steps off driveway from leaning retaining wall

Exterior Conditions & Limitations: 
Restricted / No access to:



#### Damaged large door track

□ Snow covering over:

☑ This

□ Restricted inspection due to trees / vines / shrubs. □ Grading not visible due to: report does not include geological or soil conditions. For this information a Geotechnical Engineer should be consulted.

☑ Outbuildings such as storage sheds etc. not related to the house are not included in the inspection. I This inspection does not verify or certify the safe operation on any automatic garage door opening mechanism.

SOP	SOP Standards of Practice: CanNACHI		Inspected	Date: 19/08/2020
•	Observe and Report on Systems &     Components		Not Inspected	Inspector Initials:
	Perform Tasks noted in SOP		Not Applicable	Client Initials:



			3. STRUCTURE						
#	SOP	~	COMPONENTS: DESCRIPTION & COMMENTS						
301	•	~	FOUNDATION: type: ✓ formed concrete       □ concrete block       □ stone masonry       □ ICF         □ wood       □ other         interior wall cracks:       □ minor       □ moderate       □ extensive       □ not visible						
302	•	~	FLOORS:						
303	•	-	-Beams: 🗌 masonry 🗋 metal 🖌 wood 🛛 🗋 not visible						
304	*	~	-Columns: 🗆 masonry 🔲 metal ✔ wood 🛛 not visible						
305	•	~	-Joists: 🗸 wood 🗆 engineered 🔹 not visible						
306	•	~	WALLS:						
307	•	~	-Concrete: 🗸 formed 🗆 block						
308	•	~	-Wood Frame:						
309	•	-	-Brick:						
310	•	-	Arches / Lintels / Headers:						
311	•	~	<b>ROOF:</b> No attic access						
312	•	~	-Sheathing: OSB  v planks plywood  missing						
313	*	~	-Structure: 🗸 rafters 🗆 trusses						
314	•	_	Chimney(s): as seen inside the house						
315	•	_	Evidence of deterioration from insects / fire: <pre> </pre> <pre> none found today</pre>						
316	•	•	LOWEST LEVEL:       ✓ Basement       □ Crawl Space         - Evidence of abnormal condensation:       □ none       □ slight       □ moderate       □ extensive         - Evidence of prior moisture seepage:       □ none       ✓ slight       □ moderate       □ extensive         - Anticipated moisture seepage:       □ low       ✓ typical       □ high						
			COMMENTS: See ADDITIONAL COMMENTS Sheet						
for int #312- neces	ended sup missing v sary for o ng in stee	oport a vood p ptimal :	concrete plies for grain bins lower support structure (3). Recommend contractor to address as necessary nd structure. lank sheathing in some areas under metal roofing, recommend monitor and blocking be installed as support. bin structure under grade at the bottom the elevator leg, recommend monitor and reinforcement if						



## STRUCTURE PHOTOGRAPHS



Deterioration to concrete piles





Deterioration to pile



#### Deterioration to pile

Structure Conditions & Limitations

Restricted/No access to:

□ Attic Space inspected from access hatch

Concealed and or obstructed structural components not inspected.

☑ No engineering or structural analysis is performed during this inspection. A Structural Engineer should be consulted if necessary.

☑ This inspection does not verify the adequacy of any structural system or component.

SOP	Standards of Practice: CanNACHI	~	Inspected	Date: 19/08/2020
•	Observe and Report on Systems &     Components		Not Inspected	Inspector Initials:
	Perform Tasks noted in SOP		Not Applicable	Client Initials:

Bowing in bottom of below grade grain bin

□ Crawl Space inspected from access hatch.

approx. 0 % of foundation wall <u>not</u> visible



			4. INSULATION & VENTILATION
#	SOP	~	COMPONENTS: DESCRIPTION & COMMENTS
401	•	_	ATTIC:  no attic access
402		_	-Upper venting: $\Box$ mushroom $\Box$ turbine $\Box$ gable $\Box$ ridge $\Box$ powered $\Box$ none visible
403	•	—	-Vapour barrier:  plastic  paper  spray foam  other none found
404	•	_	-Insulation:  batt blown/loose spray foam none found approx. thickness inches. recommend a top-up
405	•	_	-Lower Venting:  Soffit  baffles  gable  not visible
406	•	—	-Party Wall: 🔲 masonry 🔲 drywall
407	•	—	-Evidence of insects/rodents/pests:
408	•	~	LOWEST LEVEL: V Basement Crawl Space
409	•	-	-Vapour barrier:  none not visible due to finished basement
410	•	_	-Insulation:  none not visible due to finished basement
411	•	_	-Ventilation: ✔ basement windows 🗆 crawl space vents 🗆 none
412	•	—	Wall insulation main & upper levels: <ul> <li>not visible</li> </ul>
413	•	_	Pipes in unheated areas: □ Exterior Hose Bibs □ garage □ crawl space □ attic □ cold room
414	•	—	Ducts in unheated areas: □ garage □ crawl space □ attic □ cold room
415	•	—	EXHAUST FAN VENTILATION:
416	•	_	-Kitchen(s):  none  recirculating  exhausting
417	+ ■	—	-Bathroom(s):
418	•	_	-Other(s): HRV laundry room
419	*	_	-Dryer Vent: Delastic demote metal recommend cleaning regularly
			COMMENTS:   See ADDITIONAL COMMENTS Sheet



## **INSULATION & VENTILATION PHOTOGRAPHS**

Insulation & Ventilation Conditions & Limitations: 
Attic Space viewed from hatch 
Crawl Space viewed from hatch

Restricted / No access to:

☑ Concealed insulation not inspected.

Air / Vapour barrier continuity not inspected. Determining the presence of asbestos or other hazardous materials is beyond the scope of this inspection. ☑ Determining the adequacy of insulation and/or ventilation is beyond the scope of this inspection.

SOP	Standards of Practice: CanNACHI 🖌 Inspected			Date: 19/08/2020
•	Observe and Report on Systems & Components	×	Not Inspected	Inspector Initials:
	Perform Tasks noted in SOP	-	Not Applicable	Client Initials:



	5. ELECTRICAL
~	COMPONENTS: DESCRIPTION & COMMENTS
~	Service Entrance: 🗆 underground 🖌 overhead
~	Service (Meter) Box 400 Amps. Voltage: □ 120 🖌 240 □ not accessible
~	Service Panel 200 Amps. Location: ✓ breakers □ fuses □ not accessible
~	-Wires:
~	- 🗆 Fuses ✔ Breakers 🗋 GFCI breakers 🗋 AFCI breakers
_	-Dedicated Circuits:
_	Grounding: □ water pipe □ grounding rods ✓ not visible □ wire continuity not determined
~	Branch Circuit Wiring: 🗸 copper 🗆 aluminum 🗆 knob & tube
_	-Knob & Tube:   recommend qualified electrician to inspect and maintain
_	-Aluminum:
~	Junction Boxes:
~	<b>Receptacles:</b> ✓ grounded □ ungrounded □ upgraded grounded □ upgraded ungrounded □ TR
_	-Ground Fault Circuit Interrupter Receptacles:
~	Switches:
~	Lights:
~	Cover plates:
	COMMENTS: See ADDITIONAL COMMENTS Sheet
	ly done for electrical, no operation of elevator mechanical parts done at time of inspection (scale, dust ect.)



## **ELECTRICAL PHOTOGRAPHS**



Main disconnect



Sub panel

**Electrical Conditions & Limitations:** 

□ Restricted/No access to:

☑ Concealed or obstructed electrical components not inspected.

☑ Aluminum wiring connections should be checked by a licensed electrician familiar with aluminum wire. ☑ Services less than 100 amps may need upgrading for operation of larger electrical appliances. ☑ Newer homes have "Ground fault circuit interrupter" (GFCI) protection for safety in wet areas, an upgrade is recommended for older homes not equipped with these devices.

S	SOP Standards of Practice: CanNACHI			Inspected	Date: 19/08/2020
	Observe and Report on Systems & Components		×	Not Inspected	Inspector Initials:
		Perform Tasks noted in SOP	-	Not Applicable	Client Initials:





**Electrical service** 

Main service panel



Admiral Home Inspections Ltd., 5410 Blake Cres., Regina, SK S4X 0G6 www.admiralhomeinspections.com



			6. HEATING & COOLING					
#	SOP	~	COMPONENTS: DESCRIPTION & COMMENTS					
601	•	_	Description:       Furnace       Boiler       Electric Heating         Efficiency:       conv.       medium       high         Fuel:       Capacity: output       Btu's.       Approx. age:       yrs according to:         Failure Probability:       Iow       medium       high       (based on typical life cycle)					
602	• ■	_	FURNACE:       Forced Air       Gravity       Manufacturer:         Image:       recommend servicing by a licensed technician       Image:       Image:					
603	•	_	BOILER: D Hot Water Manufacturer:					
604	• •	~	ELECTRIC HEATERS: Convection Radiant  Baseboard Other					
605	•	_	<b>Burnt gases exhaust method:</b> Metal flue piping  Chimney  Plastic vent pipes  Shared with :					
606	•	_	<b>Fuel Storage:</b> □ Oil □ Liquid Propane ✓ Storage tank not inspected					
607	•	_	Presence of emergency shut-off safety controls:					
608	•	_	Presence of permanent heat source / return air in each room:					
609	•	_	Thermostat: D programmable					
610	•	_	Heat / Energy Recovery Ventilator:					
611	•	_	Electronic Air Filter:					
612	• ■	_	<b>COOLING:</b> Air Conditioner  Heat Pump Manufacturer: Approx. age: yrs according to: Failure Probability: I low medium high (based on typical life cycle)					
	•		COMMENTS:  See ADDITIONAL COMMENTS Sheet					



### **HEATING & COOLING PHOTOGRAPHS**



Electric heat in office operational

Heating & Cooling Conditions & Limitations:

 $\Box$  Heating not tested.  $\Box$  A/C not tested.

□ Chimneys clean out not opened.

 $\ensuremath{\boxtimes}$  Automatic safety controls not tested.

Zone valves not tested or adjusted. Inspection of the furnace heat exchanger for evidence of cracks or holes can only be done by dismantling the unit. This is beyond the scope of this inspection. If Thermostats are not checked for calibration or timed functions. If Underground fuel storage tanks are not part of this inspection. If No pressure tests are performed on coolant systems and no representation is made regarding coolant charge or line integrity.

□ Gas was shut off to house. □ Power disconnected / shut off.

□ Fuel storage is not visible. □ Circulating pump not tested.

SOP	Standards of Practice: CanNACHI	<ul> <li>✓</li> </ul>	Inspected	Date: 19/08/2020
•	Observe and Report on Systems & Components		Not Inspected	Inspector Initials:
	Perform Tasks noted in SOP	_	Not Applicable	Client Initials:



			7. PLUMBING			
#	SOP	<	COMPONENTS: DESCRIPTION & COMMENTS			
			SUPPLY PIPING:         Public         Private         Choose pipe size.         access Location:			
701	•	-	(into house) 🔲 Copper 🔲 Plastic 🔲 Galv. Steel 🔲 Lead			
702	•	_	Pump / Pressure tank / Expansion tank :			
703	•	_	DISTRIBUTION PIPING: (in house) Copper Plastic Galv. Steel Lead Piping			
704	•	_	Water flow / Pressure:  above average average below average			
705	•	_	WASTE PIPING: (in house) Galv. Steel Plastic Copper Cast Iron Lead			
706	•	—	-P traps:			
707	•	_	-Plumbing cleanout(s) location:  Basement  crawl space  Garage  other none found			
708	•	-	-  Private (septic system)  recommend professional septic inspection			
709	- Floor Drains:  Basement  crawl space  Garage  other					
705	•		none found accessibility			
710	•	~	Sump Pit / Sump Pumps:  pit dry  not plugged in  not tested			
711	•	~	WATER HEATER: Electric Oil Gas Approx. age yrs. Capacity 20 gal.			
712	•	—	-Automatic safety controls			
713	•	—	-Burnt gases exhaust method:  Metal flue piping Chimney Plastic vent pipes shared with:			
714	•	_	-Fuel storage: Oil C LP VFuel tank not inspected			
			· · · · · · · · · · · · · · · · · · ·			
715	•	-	Laundry Tub:  washing machine discharge			
716	• • ■	—	Valves:			
717	• ■ • ■	_	Faucets:			
718 719	• ■ • ■	_	-Exterior hose bibs: frost free interior shut off anti-syphon not tested			
719	• <b>•</b>	—	Sinks:			
720	•	_	Bathtub(s) and Enclosure:			
721	•	_	Toilet(s): Shower Stall(s):			
723	•	_	Bidet:			
725						
*plum	COMMENTS :       See ADDITIONAL COMMENTS Sheet         *plumbing to building is shut off at time of inspection, no devices were tested for operation, water pressure, leaks or drainage.					
prom	promoting to building to shar on at time of inspection, no devices were tested for operation, water pressure, reals of dialitage.					



### **PLUMBING PHOTOGRAPHS**



Septic tank

Plumbing Conditions & Limitations: 
Gas was shut off. 
Water was shut off. 
Fixtures not tested:

#### □ Restricted / No access to:

☑Concealed / Underground plumbing not inspected or judged for leaks or deterioration. ☑Water treatment systems not inspected. ☑Isolating / Relief and main valves not tested. ☑Testing for water quality, lead and other hazardous materials is not part of t is inspection. ☑ Integrity of septic tanks and leaching bed is of part of this inspection. A licensed installer should be consulted. ☑Integrity and capacity of well water supply installations is not part of this inspection. A licensed well driller should be consulted. ☑Solar heating systems are not part of this inspection.

SOP	Standards of Practic	ce: CanNACHI	~	Inspected	Date: 19/08/2020
•	Observe and Report Components	t on Systems &	×	Not Inspected	Inspector Initials:
	Perform Tasks noted	d in SOP	_	Not Applicable	Client Initials:



			8. INTERIOR			
#	SOP	<	<b>COMPONENTS: DESCRIPTION &amp; COMMENTS</b>			
801	•	_	Floors: wood ceramics carpet vinyl laminate stone			
802	*	~	Walls: 🗆 drywall 🗆 plaster ✔ wood			
803	•	~	Ceilings: drywall plaster wood staining			
804	•	—	Trim:			
805	•	_	Stairways:			
806	•	—	Guards:			
807	•	—	Railings:			
808	•		Doors:			
809	•	—	Windows: not opened due to season			
810 811	• •	_	Counters: Cabinets			
811	•	_				
	•	—	Separation Wall between garage & dwelling: gas			
813	*	—	Party Walls: Concrete Dock Dbrick Ddrywall not visible			
814	*	—	Smoke Detectors:			
815	•	—	<b>Gas Fireplace:</b> Dilot not on Dinot tested Diclean system before using			
816	•	—	□ Wood Burning Fireplace □ Wood Stove □ recommend W.E.T.T. Inspection			
817	*	—	Evidence of water penetration:			
818	•	_	Evidence of abnormal condensation:			
			COMMENTS: See ADDITIONAL COMMENTS Sheet			



### **INTERIOR PHOTOGRAPHS**

Interior Conditions & Limitations: 
Restricted/No access to:
Restricted access due to storage /
furnishings.
There is a lack of historical clues due to new finishes and/or recent construction.


□ Suggest installing Carbon Monoxide Detector.

☑Cosmetic finishes not commented on.
 ☑Chimney efficiency is not commented on or judged.
 ☑Condition of walls behind wall paper, paneling and furnishings cannot be judged.
 ☑Determining odours or a stain is not included.
 ☑Condition of flooring hidden by furniture, carpet or other covering is not inspected.
 ☑Determining the rating of fire walls is beyond the scope of this inspection.

☑The inspection does not address compliance of basement apartments and accessory units. Consult local Town/City regulatory requirements.

SOP	Standards of Practice: CanNACHI	~	Inspected	Date: 19/08/2020
•	Observe and Report on Systems & Components		Not Inspected	Inspector Initials:
	Perform Tasks noted in SOP		Not Applicable	Client Initials:





Main level wall/roof structure

Main /lower level structure

Admiral Home Inspections Ltd., 5410 Blake Cres., Regina, SK S4X 0G6 www.admiralhomeinspections.com







Office foundation structure



Office floor joist structure

Upper roof structure



Office roof structure



Lower office main bam-support columns



Elevator shaft structure

Admiral Home Inspections Ltd., 5410 Blake Cres., Regina, SK S4X 0G6 www.admiralhomeinspections.com

10. SUMMARY

#### ture



Areas to focus on are:

#201- small area of missing siding near overhead door, recommend repair to prevent deterioration to wood. #204- damage to large overhead door track at top and bottom, recommend repair for safety and intended operation. #05- 2 broken office window, recommend repair for safety.

#212- damage/deterioration to steps and landing structure at south side entrance to office, recommend repair for safety. #216- broken/leaning retaining wall on north side of main driveway to elevator, recommend monitor and contractor to address repair/support to prevent further movement.

#307- deterioration to concrete plies for grain bins lower support structure (3). Recommend contractor to address as necessary for intended support and structure.

#312- missing wood plank sheathing in some areas under metal roofing, recommend monitor and blocking be installed as necessary for optimal support.

\*bowing in steel grain bin structure under grade at the bottom the elevator leg, recommend monitor and reinforcement if necessary.

\*visual inspection only done for electrical, no operation of elevator mechanical parts done at time of inspection (scale, dust collectors, cleaners ect.)

\*plumbing to building is shut off at time of inspection, no devices were tested for operation, water pressure, leaks or drainage.

Inspector's Initials:

Date: 19/08/2020

**Clients Initials:**