

	Unit Number	Serial	License	Date Out	Internal Parts	Grand Total	Internal Description
Lot#130	ER27	1D92BGG89LG791012	YBV5865	2-14-2024	11,930.79	11,930.79	replaced valve two time and set up new valve and test adjust pressures set up arm
	ER27	1D92BGG89LG791012	YBV5865	2-16-2024	1,808.85	1,808.85	replaced manifold valve
	ER27	1D92BGG89LG791012	YBV5865	2-14-2024	0.00	1,184.00	replaced valve two time and set up new valve and test adjust pressures set up arm
	ER27	1D92BGG89LG791012	YBV5865	1-27-2025	1,007.87	1,007.87	REPLACED HYDRO COOLER
	ER27	1D92BGG89LG791012	YBV5865	2-14-2024	0.00	992.00	replaced valve two time and set up new valve and test adjust pressures set up arm
	ER27	1D92BGG89LG791012	YBV5865	2-14-2024	987.60	987.60	replaced valve two time and set up new valve and test adjust pressures set up arm
	ER27	1D92BGG89LG791012	YBV5865	8-14-2024	748.16	748.16	8/12 REPLACE TROLLY MOTOR 8/14 REWIRED REACH SENSOR
	ER27	1D92BGG89LG791012	YBV5865	12-19-2023	520.39	520.39	INSTALL MISSING BATTERY BOX COVER
	ER27	1D92BGG89LG791012	YBV5865	12-19-2024	0.00	520.00	COULDN'T GET TO DUMP ON TIP FLOOR
	ER27	1D92BGG89LG791012	YBV5865	7-8-2025	475.00	475.00	INSTALL PEDLE AND MESS WITH WINDOW FINISH DOT
	ER27	1D92BGG89LG791012	YBV5865	2-10-2026	472.43	472.43	DID A QUICK INSPECTION OF THE TRUCK REINSTALLED FLEET MIND
	ER27	1D92BGG89LG791012	YBV5865	12-9-2024	413.98	413.98	replaced starter on truck and drained and filled coolant
	ER27	1D92BGG89LG791012	YBV5865	8-2-2024	338.85	338.85	Remove mirror and glass, didn't have part numbers
	ER27	1D92BGG89LG791012	YBV5865	5-28-2024	329.20	329.20	5/23 Tighten and replace bolts on finger bushing pins. 5/24 Replace o ring on leaking HP hydro filter, clean threads,
	ER27	1D92BGG89LG791012	YBV5865	3-27-2024	320.28	320.28	FLEETMIND DIDN'T BOOT UP SHUT TRUCK OFF AND TURNED BACK ON FLEETMIND BOOTED UP inventory bill out
	ER27	1D92BGG89LG791012	YBV5865	1-3-2024	0.00	320.00	PULL L90 VALVE, SWAP COMPONENTS, VALVE HAD EXTRA BANK, REMOVED TO MATCH UP. REINSTALLED VALVE, VALVING WRONG, NEED TO REMOVE VALVE AND REPLACE WITH CORRECT VALVE WHEN ARRIVES.
	ER27	1D92BGG89LG791012	YBV5865	1-3-2024	0.00	320.00	PULL L90 VALVE, SWAP COMPONENTS, VALVE HAD EXTRA BANK, REMOVED TO MATCH UP. REINSTALLED VALVE, VALVING WRONG, NEED TO REMOVE VALVE AND REPLACE WITH CORRECT VALVE WHEN ARRIVES.
	ER27	1D92BGG89LG791012	YBV5865	2-14-2024	0.00	320.00	replaced valve two time and set up new valve and test adjust pressures set up arm
	ER27	1D92BGG89LG791012	YBV5865	1-3-2024	0.00	308.00	PULL L90 VALVE, SWAP COMPONENTS, VALVE HAD EXTRA BANK, REMOVED TO MATCH UP. REINSTALLED VALVE, VALVING WRONG, NEED TO REMOVE VALVE AND REPLACE WITH CORRECT VALVE WHEN ARRIVES.
	ER27	1D92BGG89LG791012	YBV5865	5-28-2024	305.42	305.42	Did PM and both hydraulic oil filter, added hydro
	ER27	1D92BGG89LG791012	YBV5865	7-8-2025	0.00	252.00	INSTALL PEDLE AND MESS WITH WINDOW FINISH DOT
	ER27	1D92BGG89LG791012	YBV5865	4-1-2022	247.98	247.98	replaced grabber cylinder and put two new cylinder sensors in
	ER27	1D92BGG89LG791012	YBV5865	2-10-2026	0.00	240.00	DID A QUICK INSPECTION OF THE TRUCK REINSTALLED FLEET MIND
	ER27	1D92BGG89LG791012	YBV5865	8-2-2024	0.00	212.00	Remove mirror and glass, didn't have part numbers
	ER27	1D92BGG89LG791012	YBV5865	4-25-2025	0.00	208.80	STARTER REPLACED
	ER27	1D92BGG89LG791012	YBV5865	5-28-2024	206.39	206.39	Did PM and both hydraulic oil filter, added hydro
	ER27	1D92BGG89LG791012	YBV5865	5-1-2025	0.00	189.00	lights
	ER27	1D92BGG89LG791012	YBV5865	11-5-2024	0.00	180.00	REPLACED TROLLY MOTOR AND TROLLY GLIDES
	ER27	1D92BGG89LG791012	YBV5865	5-28-2024	0.00	172.00	Did PM and both hydraulic oil filter, added hydro
	ER27	1D92BGG89LG791012	YBV5865	8-5-2024	0.00	172.00	REPLACED 6X HYDRO ARM HOSES
	ER27	1D92BGG89LG791012	YBV5865	2-15-2024	164.60	164.60	body wont go down went down and lowered body
	ER27	1D92BGG89LG791012	YBV5865	4-11-2024	164.60	164.60	cab alarm going off went out and reset cab locks
	ER27	1D92BGG89LG791012	YBV5865	3-14-2024	164.60	164.60	train how to dump unit
	ER27	1D92BGG89LG791012	YBV5865	4-5-2024	164.60	164.60	charge air pipe blow off reinstalled
	ER27	1D92BGG89LG791012	YBV5865	4-5-2024	164.60	164.60	driver called packer inop talked through no go went out and found that the packer was shut off
	ER27	1D92BGG89LG791012	YBV5865	4-5-2024	164.60	164.60	load test batterys and close tail gate
	ER27	1D92BGG89LG791012	YBV5865	3-14-2024	164.60	164.60	mirror was loose tightened
	ER27	1D92BGG89LG791012	YBV5865	2-22-2024	164.60	164.60	packer inop truck was in true mode
	ER27	1D92BGG89LG791012	YBV5865	4-26-2024	164.60	164.60	rear door open closed
	ER27	1D92BGG89LG791012	YBV5865	2-16-2024	164.60	164.60	train driver
	ER27	1D92BGG89LG791012	YBV5865	4-3-2024	164.60	164.60	replaced manifold valve
	ER27	1D92BGG89LG791012	YBV5865	4-3-2024	164.60	164.60	teach driver how to dump and open rear door
	ER27	1D92BGG89LG791012	YBV5865	12-16-2024	0.00	160.00	MULTIPLE CODES ERROR IN MULTIPLE SETTING PULLED SETTINGS FROM 28 COPIED TO 27 CLEARED CODES PREFORMED REGEN
	ER27	1D92BGG89LG791012	YBV5865	2-16-2024	0.00	160.00	replaced manifold valve
	ER27	1D92BGG89LG791012	YBV5865	4-8-2025	158.99	158.99	REPLACED FILTERS
	ER27	1D92BGG89LG791012	YBV5865	6-4-2025	0.00	157.50	fix a/c vents fix throttle pedal torque drive shaft
	ER27	1D92BGG89LG791012	YBV5865	8-5-2024	149.10	149.10	PART INSTALLED BY JOSH
	ER27	1D92BGG89LG791012	YBV5865	4-1-2022	148.58	148.58	replaced grabber cylinder and put two new cylinder sensors in
	ER27	1D92BGG89LG791012	YBV5865	8-14-2024	0.00	140.00	8/12 REPLACE TROLLY MOTOR 8/14 REWIRED REACH SENSOR
	ER27	1D92BGG89LG791012	YBV5865	2-13-2024	0.00	140.00	Engine Hours and tabs
	ER27	1D92BGG89LG791012	YBV5865	10-30-2024	0.00	140.00	FINDWHY MC43 ANT NO CONTACT BLOWN FUSE REPLACED LOOK AND REWIRED FUSE HOLDER FOUND SHORT OUT INSTALED SCREENAND WIRE FOR FLEETMIND PUT CAB AND CONTROLSBACK TOGETHER PUT PANELS AND TESTED
	ER27	1D92BGG89LG791012	YBV5865	2-14-2024	129.00	129.00	replaced valve two time and set up new valve and test adjust pressures set up arm

	ER27	1D92BGGB9LG791012	YBV5865	4-4-2025	0.00	126.00	PM SERVICE
	ER27	1D92BGGB9LG791012	YBV5865	4-25-2025	0.00	126.00	starter motor replaced used
	ER27	1D92BGGB9LG791012	YBV5865	4-8-2025	123.99	123.99	REPLACED FILTERS
	ER27	1D92BGGB9LG791012	YBV5865	5-28-2024	0.00	120.00	5/23 Tighten and replace bolts on finger bushing pins.
	ER27	1D92BGGB9LG791012	YBV5865	3-14-2024	0.00	120.00	5/24 Replace o ring on leaking HP hydro filter, clean threads,
	ER27	1D92BGGB9LG791012	YBV5865	3-14-2024	0.00	120.00	charge air pipe blow off reinstalled
	ER27	1D92BGGB9LG791012	YBV5865	3-14-2024	0.00	120.00	charge air pipe blow off reinstalled
	ER27	1D92BGGB9LG791012	YBV5865	4-26-2024	0.00	120.00	rear door open closed
	ER27	1D92BGGB9LG791012	YBV5865	4-26-2024	0.00	120.00	train driver
	ER27	1D92BGGB9LG791012	YBV5865	11-13-2024	0.00	120.00	REPLACED BLOWER MOTOR SWITCH INSPECT BLOWER MOTOR
	ER27	1D92BGGB9LG791012	YBV5865	8-29-2024	0.00	120.00	SERVICE CALL ARM STUCK
	ER27	1D92BGGB9LG791012	YBV5865	11-1-2024	111.76	111.76	REPLACED GRABBER HARNESS AND TIGHTED STEERING WHEEL
	ER27	1D92BGGB9LG791012	YBV5865	4-4-2025	102.65	102.65	PM SERVICE
	ER27	1D92BGGB9LG791012	YBV5865	8-29-2024	0.00	100.00	SERVICE CALL ARM INOP CART STUCK FREED CART HEAD IN REMOVE SHIRT
Lot#131	ER28	SEG1AKBC1KW025349	YBY6566	12-19-2023	10,567.00	10,567.00	R&R BODY VALVE, OVER PRESSURIZING TROLLEY MOTOR
	ER28	SEG1AKBC1KW025349	YBY6566	2-26-2024	3,292.00	3,292.00	replaced all arm hoses and o-rings replaced tip sensor rewrapped hoses dot fire ex mount installed fire ex replaced fuel leak fixed oil leak fixed fixed finger play
	ER28	SEG1AKBC1KW025349	YBY6566	5-28-2024	1,808.85	1,808.85	body not coming down replaced lift block
	ER28	SEG1AKBC1KW025349	YBY6566	10-22-2024	1,804.43	1,804.43	DEF TANK EMPTY RUN TO KEENDY GET DEF FILL GAUGE SHOWS EMPTY
	ER28	SEG1AKBC1KW025349	YBY6566	4-12-2024	823.00	823.00	Replaced return hydro hose near D1L brake hoses and help Scott with replacing a main hydro hose
	ER28	SEG1AKBC1KW025349	YBY6566	3-14-2024	658.40	658.40	fixed finger bushings and welded braces for straps
	ER28	SEG1AKBC1KW025349	YBY6566	4-26-2024	658.40	658.40	fixed grabber loose and not holding small carts grinder and prep for welding make gussets to fix cracks in arm weld in supports
	ER28	SEG1AKBC1KW025349	YBY6566	12-30-2024	646.66	646.66	arm inop broken cam lever bushing gone
	ER28	SEG1AKBC1KW025349	YBY6566	12-19-2023	573.52	573.52	R&R BODY VALVE, OVER PRESSURIZING TROLLEY MOTOR
	ER28	SEG1AKBC1KW025349	YBY6566	12-19-2023	520.39	520.39	INSTALL MISSING BATTERY BOX COVER
	ER28	SEG1AKBC1KW025349	YBY6566	4-12-2024	329.20	329.20	4/9 Replace zeros on reab body lift hinges
	ER28	SEG1AKBC1KW025349	YBY6566	4-12-2024	329.20	329.20	4/10 tighten chain for trolley, bring outside and raise body so I can check trans fluid and shield hoses from rubbing on body
	ER28	SEG1AKBC1KW025349	YBY6566	2-26-2024	0.00	320.00	replaced all arm hoses and orings replaced tip sensor rewrapped hoses dot fire ex mount installed fire ex replaced fuel leak fixed oil leak fixed fixed finger play
	ER28	SEG1AKBC1KW025349	YBY6566	8-20-2024	305.42	305.42	HYDRO FLUID 170 QTS
	ER28	SEG1AKBC1KW025349	YBY6566	8-16-2024	0.00	260.00	rerouted cooler hoses not installed correctly
	ER28	SEG1AKBC1KW025349	YBY6566	7-10-2025	0.00	252.00	checked wire harness for damage to proxy sensor reconnected harness welded lower hose bracket back onto tro;y josh assisted with prep and staging note looks like driver hit something bracket was bent and fingers bent
	ER28	SEG1AKBC1KW025349	YBY6566	6-30-2025	0.00	252.00	REWIRE ASL HARNESS
	ER28	SEG1AKBC1KW025349	YBY6566	12-31-2024	218.22	218.22	TROUBLE SHOOT REPLACED CLEANED PARTS OUT REPLACED DIFF SENSORS
	ER28	SEG1AKBC1KW025349	YBY6566	10-22-2024	0.00	212.00	DEF TANK EMPTY RUN TO KEENDY GET DEF FILL GAUGE SHOWS EMPTY
	ER28	SEG1AKBC1KW025349	YBY6566	4-9-2024	206.39	206.39	PM Service JE - jumpstart in AM GS- fuel, oil, & hydro filters + oil sample. 19qts 15w40 *needs oil level check* JS - Looked over everything PM -
	ER28	SEG1AKBC1KW025349	YBY6566	11-11-2024	206.39	206.39	TEST FOUND PUMP FALED NEEDS TO BE REPLACED NEED INVOICE FOR WARRENTY
	ER28	SEG1AKBC1KW025349	YBY6566	4-12-2024	0.00	200.00	4/9 Did a pm except George did wet portion. 1st drive diff output seal leaks despite clear breather and no shaft play, topped up, needs to be watched. Windows wont go up 100% but josh says it cant be fixed. needs top of arm greased, hydro checked, trans fluid checked. looked over 4/10 Finished up PM by greasing top of arm, checked hydron fluid, checked trans fluid
	ER28	SEG1AKBC1KW025349	YBY6566	8-16-2024	0.00	200.00	PULL PUMP OUT MOVE WIRING TO GET AT BOLTS
	ER28	SEG1AKBC1KW025349	YBY6566	11-22-2024	0.00	200.00	REPLACED WARRENTY PUMP
	ER28	SEG1AKBC1KW025349	YBY6566	5-21-2025	0.00	189.00	FIX TILT AND PIN LOOSE AND FINGERS
	ER28	SEG1AKBC1KW025349	YBY6566	8-6-2024	0.00	180.00	BUILT HYDRO COOLER FRAME