

Remit To: Edmonton Kenworth Ltd.

17335 118 Avenue

Edmonton, AB

T5S 2P5

Tel: 780-453-3431 Fax: 780-454-6124

Purchased From:

Kenworth Lloydminster

6101 - 63 Avenue

Lloydminster, Alberta T9V 3T6

Phone: 780-871-0950

Invoice: **04LS126137**

Date / Hour: 6/11/2024 10:43:02AM

Repair Order: 126137

Branch: Lloyd

Total Invoice: \$11,277.62

Mastercard-M - 9731

Page 1 of 3

Open Date: 06/06/2024

Completion Date: 06/10/2024

Salesperson:

Unit Number: 260-2068

Model Year: 2020

Make/Model: KENWORTH T680

Type: Class 8

VIN: 1XKYD40X1LJ956151

Meter: 740013 Kilometers

In-Service Date: 03/26/2019

ECM Reading: 10659

CASH ACCOUNT PLEASE MAKE SURE PAYMENT HAS BEEN RECEIVED PRIOR TO DELIVERY

Task: 1	27-370000	Transmission - Automatic - Diagnosis			Department: Service	
Complaint: CUSTOMER COMPLAINT OF TRANSMISSION WONT GO INTO GEAR AND TRANSMISSION LIGHT ON - STOP ENGINE						
Correction: FAULT CODE ACTIVE CODE 27 FMI 7 - CLUTCH DISENGAGEMENT - 13 COUNTS. PERFORMED TROUBLE SHOOTING STEPS. INERTIA BRAKE TP DELTA OUT OF SPEC - READING 2.391 DEG - FOR FAULT CODE TO BE INACTIVE IT HAS TO BE READING ABOVE 16 DEG. INSIDE BELL HOUSING IS DRY - LACK OF LUBRICATION. INSPECTED FOR METAL - FOUND METAL PIECE FROM CLUTCH - UNIT HAS NO MORE EATON WARRANTY - 3 MONTHS OUT OF WARRANTY. TURN OVER ENGINE AND INSTALL/ TORQUE CLUTCH BOLTS, REMOVED CAGING BOLTS, CLEAN SURFACE, AND INSTALL NEW ECA/ ECA SHIELD- TORQUED TO SPEC, PLUG IN ECA HARNESS AND SECURE IT BACK WITH ZIP TIES, REINSTALL BATTERY CABLE HANGERS BACK, DRAINED TRANNY OIL, REMOVED COOLANT LINES FROM TRANNY COOLER, DISCONNECTED WIRE HARNESS, REMOVED TRANNY HOLD DOWN STRAP, CAGED AND UNBOLTED CLUTCH, PUT JACK UNDERNEATH TRANNY, REMOVED ALL TRANNY BOLTS, REMOVED TRANSMISSION FROM UNIT, REPLACED COMPRESSOR DISCHARGE LINE, REMOVED FLYWHEEL FOR RESURFACING, WASHED TRANNY, OPENED UP TOP OF TRANNY AND INSPECTED ALL GEARS, NO VISIBLE DAMAGE FOUND, CLEANED GASKET SURFACE AND PUT SHIFTER PLATE BACK ON, REMOVED CLUTCH BRAKE, REPLACED TRANNY INPUT SHAFT, PUT NEW CLUTCH BRAKE ON, REPLACED CLUTCH FORK, SHAFT AND BUSHINGS, PUT NEW CLUTCH ON, PUT FLYWHEEL BACK ON, PUT TRANSMISSION BACK IN, TIGHTENED ALL TRANNY BOLTS, PUT TRANNY HOLD DOWN STRAP ON, BOLTED UP CLUTCH, PUT COOLANT LINES ON TRANNY COOLER, CONNECTED WIRE HARNESS, TIED UP LINES AND WIRES, PUT DRIVELINE BACK ON, TIGHTENED UP STEADY BEARING, FILLED UP TRANNY WITH OIL, HOOKED UP COMPUTER, CLEARED ALL FAULT CODES, AND ADJUSTED CLUTCH, TOOK UNIT FOR TEST DRIVE WAS WORKING GOOD, CHECKED FOR LEAKS - NO LEAKS FOUND.						
Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
E0160	122002-35A	CLUTCH ULTRAShift PLUS 2 IN 14 SPLINE 36/MM Serial Number: KM2311062181	EA	1.0	\$3,694.21	\$3,694.21
PACCAR: Loyalty Card Program Y245770 40						
647	24710N-610WHD	FITTING-SAE45 STL FSTRSWV	EA	2.0	\$27.02	\$54.04
S2420	250-70-18X	KIT-BEARING RETAINER	EA	1.0	\$32.15	\$32.15
P0100	CORE 325	KIT-ECA KIT NO HARNESS OR SHEILD-Core	EA	-1.0	\$560.63	\$(560.63)
P0100	4302676	GASKET	EA	1.0	\$7.03	\$7.03
P0100	4305452	GASKET HOUSING SHIFT TOWER	EA	1.0	\$16.77	\$16.77
P0100	75320	TUBING B1G50	EA	1.0	\$2.20	\$2.20
D1650	AP3172	ADAPTER-SAE45 BRS UNION 7/8MNF-7/8M	EA	1.0	\$5.98	\$5.98
P0100	CORE 325	KIT-ECA KIT NO HARNESS OR SHEILD-Core	EA	1.0	\$560.63	\$560.63
P0100	CT04311	TIE-CABLE 50LB 11.75" BLK	EA	10.0	\$0.21	\$2.10
P0100	CT05512	TIE-CABLE 120LB, 15.25" BLK	EA	20.0	\$0.55	\$11.00

** See Last Page for Invoice Total **

**** See Last Page for Invoice Total ****

Remit To: Edmonton Kenworth Ltd.

17335 118 Avenue

Edmonton, AB

T5S 2P5

Tel: 780-453-3431 Fax: 780-454-6124

Purchased From:

Kenworth Lloydminster

6101 - 63 Avenue

Lloydminster, Alberta T9V 3T6

Phone: 780-871-0950

Invoice: **04LS126137**

Date / Hour: 6/11/2024 10:43:02AM

Repair Order: 126137

Customer: 28054

Branch: Lloyd

Total Invoice: \$11,277.62

Mastercard-M - 9731

Page 3 of 3

Customer P/O:

Open Date: 06/06/2024

Completion Date: 06/10/2024

Add User: Evandewetering

Salesperson:

Invoice Subtotal: \$10,740.59

Total Tax: \$537.03

Total Invoice: \$11,277.62

Payment Method

Terms

Due Date

Due Immediately

6/12/2024

I/WE HEREBY ACKNOWLEDGE INDEBTEDNESS IN THE AMOUNT OF \$ _____
FOR THE PARTS AND LABOUR ON THIS WORK ORDER AND IT IS ACKNOWLEDGED
THAT THE SAID AMOUNT MAY BE ADJUSTED ON FINAL PRICING. IF THE BALANCE
DUE ISN'T PAID WITHIN EDMONTON KENWORTH'S CREDIT TERMS. I AGREE TO PAY
INTEREST AT THE RATE OF 2% PER MONTH (24% ANNUM) PLUS \$30.00 PER DAY
STORAGE FEE.

SIGNATURE _____ DATE/TIME _____

PRINT NAME: _____