HIGH TECH automotive

927 Winnipeg Street
Regina, Saskatchewan S4R 1J1
Phone: (306) 546-3730
GST# BN 87165 5114

№ 23855

QTY.	PART NUMBER / SUPPLIER	PARTS DESCRIPTION	AMOUNT
1	Rt & Ft Brake Hose		48 70
2	Replace Lady Kits		174 30
2	Upper Control Arms		991 15
2	Lower Ball Joints		226 60
2	Drivers Tie Rods		242 36
2	Outer Tie Rods		192 00
1	Rdl Arm		226 40
1	Pitman Arm		204 10
1	Steering Stab Shock		110 60
1	OPAX Steering Box		554 60
	P/S Flush		125
	P/S Fluid		20 00
1	Set Rear Brake Pads		107 00
2	Ft Brake Rotors		361 80
1	Set Ft Brake Pads		107 00
2	Ft Brake Rotors		342 14
1	Set Ft Brake Calipers		138 70
	Brake Fluid		22 00
4	Valve Stems		12 00
			2592 36
	Less 10%		359 23
			3233 12
4	LT 315/75/16 Hankook		1314 60
	RPlace Tires		
	Less 749 = K		
	2000 = Cash		

DATE	Jan 3/22
SERIAL NUMBER	1GTHK [illegible]
NAME	Ryan Eckel
PHONE BUS.	537 6257
MAKE	GMC
YEAR	96
ADDRESS	
PHONE RES.	
MODEL	
CITY OR TOWN	
POSTAL CODE	
LICENSE NO.	
PROMISED FOR A.M. P.M.	
TERMS CASH ☐ CREDIT ☐	
CREDIT CARD NO.	
ORDER WRITTEN BY	
MILEAGE	[illegible]

TECHNICIAN	INSTRUCTIONS	AMOUNT
	OIL CHANGE ☐ TYPE FILTER ☐	
	CAR CARE INSPECTION ☐ LUBRICATION ☐	
	ALIGNMENT ☑	119 25
	Replace Upper Control Arms & Lower Ball Jt	672 00
	Replace 2 LLB Arms & Outer Tie Rods	224 00
	Replace Rdl Arm	112 00
	Replace Steering Box & Pitman Arm	248 00
	Replace Steering Stabilizer	89 60
	Replace Ft Brake Pads & Rotors	139 85
	Replace Rear Brake Pads & Rotors	139 85
	Replace LF Brake Hose & Caliper	89 60
	Rmove 204 Tires	120 00
	Dispose of Hazardous Waste Rtn	112 00
	MISCELLANEOUS SHOP SUPPLIES	185 77

I hereby authorize you to do the above work and to supply the necessary materials. I agree that you will not be responsible for loss, damage or theft of my vehicle or its contents, however caused, while being stored for the purpose of repair. In the event of non-payment of the total charge, you are authorized to repossess the vehicle and retain it until that charge has been paid.

SIGNATURE _____

TOTAL LABOUR	2064 25
(1) TOTAL MERCHANDISE	4547 23
SUB TOTAL	6817 85
PST	409 06
GST	340 88
SSTS	20 00
PLEASE PAY THIS AMOUNT	7567 49

ADDITIONAL REPAIRS REQUIRED:
- ABS, SES, AT O.V - P/S PUMP WEAK
- MAY Require HVAC Unit to be Removed for Overhaul