



SOUTH COUNTRY
EQUIPMENT

Box 400
Highway 6
Raymore, SK S0A 3J0
Phone: 306-746-2110
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 5196

Deliver To:

Internal Used Stock No. 134897	Internal Used Stock No. 134897	Invoice Number: 598490
		Invoice Date: 11/17/2022
		Location: 07
		Work Order Number: 208898
		Payment Type: Account
Bus Phone:	Bus Phone:	Page: 1 of 5
Prv Phone:	Prv Phone:	

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 2016 JD S690 COMBINE	1776	1H0S690SAG0785243	1H0S690SAG0785243	

Service Reminders:

/GLOPCLEANS690 F Internal

COMPLAINT:

02 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CAUSE:

CORRECTION:

WASH COMPLETE MACHINE(OPEN & WASH BEHIND ALL SHIELDS) WAX IF REQUIRED REMOVE ANY OTHER DEALER DECALS INSTALL SCE DEALERSHIP DECALS ALL FACTORY SAFETY AND MODEL DECALS IN GOOD CONDITION REMOVE CAB FLOORMAT AND CLEAN MAT AND FLOOR CLEAN SEAT AND REMOVE STAINS IF NECESSARY VACUUM CAB THOROUGHLY CLEAN INSTRUMENT PANEL, OPERATOR CONTROLS, UPHOLSTERY, AND AIR DELIVERY LOUVERS CLEAN WINDOWS AND MOLDINGS(OPEN WINDOWS TO CLEAN EDGES WHERE APPLICABLE) ELIMINATE ANY CAB ODORS AND INSTALL AIR FRESHENER IF REQUIRED PAINT AREAS THAT ARE BADLY SCRATCHED/DAMAGED-INCLUDING BUCKETS, GRAPPLES, WHEELS, EXHAUST, PLATFORM AUGERS(COMPLETE AUGER), CHOPPER FINS, FEEDERHOUSE DRUMS, BALER PICKUPS

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$89.00	\$89.00	N
Labor: \$3,270.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$89.00	Sub-Total: \$3,359.00	

/101712500S690 F Internal

COMPLAINT:

03 FEEDER HOUSE CHAIN, ADJUST

CAUSE:

CORRECTION:

Remove shield. Loosen nuts and adjust eyebolts. Check tension and reassemble.

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$2.93	\$2.93	N
Labor: \$48.90	Parts: \$0.00	OL&M: \$0.00	Misc: \$2.93	Sub-Total: \$51.83	

/110014S690 F Internal

COMPLAINT:

04 ADJUST FEEDERHOUSE DRIVE CHAIN



SOUTH COUNTRY
EQUIPMENT

Box 400
Highway 6
Raymore, SK S0A 3J0
Phone: 306-746-2110
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 5196

Deliver To:

Internal Used	Stock No. 134897
Bus Phone:	
Prv Phone:	

Internal Used	Stock No. 134897
Bus Phone:	
Prv Phone:	

Invoice Number:	598490
Invoice Date:	11/17/2022
Location:	07
Work Order Number:	208898
Payment Type:	Account
Page:	2 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 2016 JD S690 COMBINE	1776	1H0S690SAG0785243	1H0S690SAG0785243	

Service Reminders:

CAUSE:

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$1.96	\$1.96	N
Labor: \$32.60	Parts: \$0.00	OL&M: \$0.00	Misc: \$1.96	Sub-Total: \$34.56	

/140338S690 F Internal

COMPLAINT:

08 REPLACE SHOE DRIVE BELT
- SHOE AUGER DRIVE BELT IS SEPARATING ON BACK SIDE.

CAUSE:

CORRECTION:

Replaced shoe supply drive belt.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
HXE102288	V-Belt	1.00	\$965.74	\$965.74	N
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$14.67	\$14.67	N
Labor: \$244.50	Parts: \$965.74	OL&M: \$0.00	Misc: \$14.67	Sub-Total: \$1,224.91	

/120565S690 F Internal

COMPLAINT:

09 REPLACE VACUUM DRIVE BELT

CAUSE:

CORRECTION:

Replaced vacuum drive belt.



SOUTH COUNTRY EQUIPMENT

Box 400
Highway 6
Raymore, SK S0A 3J0
Phone: 306-746-2110
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 5196

Deliver To:

Internal Used Stock No. 134897	Internal Used Stock No. 134897	Invoice Number: 598490
Bus Phone:	Bus Phone:	Invoice Date: 11/17/2022
Prv Phone:	Prv Phone:	Location: 07
		Work Order Number: 208898
		Payment Type: Account
		Page: 3 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 2016 JD S690 COMBINE	1776	1H0S690SAG0785243	1H0S690SAG0785243	

Service Reminders:		Quantity	Net Price	Extended Price	Taxed Ind
<u>PartNumber</u>	<u>Description</u>				
HXE38073	V-Belt	1.00	\$40.99	\$40.99	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$3.91	\$3.91	N
Labor: \$65.20	Parts: \$40.99	OL&M: \$0.00	Misc: \$3.91	Sub-Total: \$110.10	

/170287S690 F Internal

COMPLAINT:

10 REPLACE RADIATOR PROPELLER BEARING
- CAN HEAR ROUGH NOISE AFTER SHUTTING ENGINE OFF

CAUSE:

CORRECTION:

Replaced bearings and flanges in rad propeller.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
JD29980	BALL BEARI	2.00	\$7.71	\$15.42	N
Z33854	PRESSED FL	2.00	\$18.71	\$37.42	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$9.78	\$9.78	N
Labor: \$163.00	Parts: \$52.84	OL&M: \$0.00	Misc: \$9.78	Sub-Total: \$225.62	

/12020AS690 F Internal

COMPLAINT:

12 STRAW CHOPPER UPPER BELT, REPLACE

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
HXE124868	V-BELT, 3 BAND (3HC)	1.00	\$769.91	\$769.91	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$21.52	\$21.52	N



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 5196

Deliver To:

Internal Used Stock No. 134897	Internal Used Stock No. 134897	Invoice Number: 598490
Bus Phone:	Bus Phone:	Invoice Date: 11/17/2022
Prv Phone:	Prv Phone:	Location: 07
		Work Order Number: 208898
		Payment Type: Account
		Page: 4 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 2016 JD S690 COMBINE	1776	1H0S690SAG0785243	1H0S690SAG0785243	

Service Reminders:

Labor: \$358.60	Parts: \$769.91	OL&M: \$0.00	Misc: \$21.52	Sub-Total: \$1,150.03
------------------------	------------------------	---------------------	----------------------	------------------------------

/1502569S690 Internal

COMPLAINT:

26 RH PRIMARY COUNTERSHAFT BEARING AND HOUSING, R&R

CAUSE:

CORRECTION:

Replaced right hand bearing support for primary counter shaft it was broken. Bearing was ok reused it.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H214619	BRACKET	1.00	\$381.74	\$381.74	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$27.38	\$27.38	N
Labor: \$456.40	Parts: \$381.74	OL&M: \$0.00	Misc: \$27.38	Sub-Total: \$865.52	

/170046S690 F Internal

COMPLAINT:

27 REPLACE/TURN FEEDER HOUSE TOP SPROCKETS(FEEDER HOUSE ON)
 REPLACE TOP SHAFT

CAUSE:

CORRECTION:

Removed top feederhouse cover. Removed feed plate. Needed to torch off bolts for feedplate mounting brackets were bent. Removed top seal split feeder chain. Removed top shaft. Replaced bearings on top shaft. Installed new shaft hooked up feeder chain mounted slip clutch and torqued aligned top sprockets and adjusted. Feeder chain tension. Installed feederhouse drive chain and tightened.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
HXE42567	Shaft	1.00	\$1,454.10	\$1,454.10	N
JD10020	BALL BEARIN	1.00	\$65.40	\$65.40	N
JD9373	BALL BEARIN	1.00	\$62.85	\$62.85	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$34.23	\$34.23	N
Labor: \$570.50	Parts: \$1,582.35	OL&M: \$0.00	Misc: \$34.23	Sub-Total: \$2,187.08	



SOUTH COUNTRY
EQUIPMENT

Box 400
Highway 6
Raymore, SK S0A 3J0
Phone: 306-746-2110
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 5196

Deliver To:

Internal Used Stock No. 134897
Bus Phone:
Prv Phone:

Internal Used Stock No. 134897
Bus Phone:
Prv Phone:

Invoice Number:	598490
Invoice Date	11/17/2022
Location:	07
Work Order Number:	208898
Payment Type:	Account
Page:	5 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 2016 JD S690 COMBINE	1776	1H0S690SAG0785243	1H0S690SAG0785243	

Service Reminders:

Customer PO No:
Tax Exempt No:
Advisor: JORDAN CZERNIAK

GST Registration No: 897357802

Labor: \$5,209.70
Parts: \$3,793.57
OL&M: \$0.00
Misc: \$205.38
GST: \$0.00
PST: \$0.00

Total: \$9,208.65

Sundry G/L Entries

Br	Dpt	Acct	Sub	Ref	Description
00	00	160	1	134897	

TERMS AND CONDITIONS

Received by:

Date: