



**Balcarres Tire Ltd.**  
 103 Hwy 10 BOX 1127 BALCARRES SK S0G 0C0

PH: 306-334-2638  
 FX: 306-334-2633

*Honestly driven.*

**Invoice B14944**

DATE: 25 Dec 12

BALCARRES

SK

TEL:

FAX:

PAGE: 1

YEAR	MAKE	MODEL	ENGINE		
2010	DODGE	CARAVAN			
PLATE NO	VIN	ODOMETER	UNIT NO.		
333-KGK		243153			
TIME IN	PROMISED	TERMS	P.O.		
2:45 PM		Cash			
QTY	ITEM/DESCRIPTION	SIZE	TAX	NET	EXT.PRICE
2	0TI50121	225/65R17	GP	178.00	356.00
2	TRIANGLE ICELYNX TI501 STUDDABLE 106T		G	6.50	13.00
2	Envrio levy pass & lt (imp & ft up to 16")		GP	63.00	126.00
	SENSOR				
	AUTEL TPMS SENSOR				
	LF CV AXLE BOOT OPEN, INNER TIE RODS HAVE PLAY, FRONT BRAKES STICKING				
	DOT 01PVLFPET 2825 (2)				
1	SHP SHOP SUPPLIES		GP	N/C	N/C
	Loyalty Plan Number:				
	GST Registration# 740515002RT0001				

**MAINTENANCE**

**RECOMMENDATIONS:**

RETORQUE WHEEL NUTS AFTER 100 KM  
 ROTATE TIRES EVERY 10,000KM  
 CHECK AIR PRESSURE REGULARLY

**TERMS:**

NET 30 DAYS  
 INTEREST 1.5% PER MONTH (19.56 PER ANNUM)  
 WILL BE CHARGED ON OVERDUE ACCOUNTS

I hereby acknowledge my indebtedness of being the total amount of the balance owing of: \_\_\_\_\_

**SIGNATURE X:** \_\_\_\_\_

PARTS:	482.00
LABOUR:	N/C
OTHER:	13.00
SUB-TOTAL:	495.00
GST:	24.75
PST:	28.92
<b>TOTAL:</b>	<b>548.67</b>



**Balcarres Tire Ltd.**  
103 Hwy 10 BOX 1127 BALCARRES SK S0G 0C0

PH: 306-334-2638  
FX: 306-334-2633

*Honestly driven.*

**Invoice B14951**

DATE: 25 Dec 13

BALCARRES

SK

TEL:

FAX:

PAGE: 1

YEAR	MAKE	MODEL	ENGINE		
2010	DODGE	CARAVAN			
PLATE NO	VIN	ODOMETER	UNIT NO.		
333-KGK		243205			
TIME IN	PROMISED	TERMS	P.O.		
9:45 AM		Cash			
QTY	ITEM/DESCRIPTION	SIZE	TAX	NET	EXT.PRICE
1	RTN REPAIR TIRE ON VEHICLE (PASS/LT) MS LEFT REAR <i>SCREW IN TIRE DUG INTO SIDEWALL, INNER LINER CRACKING BAD, TIRE NOT REPAIRABLE - CUSTOMER ADVISED</i>		GP	N/C	N/C
2	0Ti50121 225/65R17 TRIANGLE ICELYNX TI501 STUDDABLE 106T		GP	178.00	356.00
2	EL Envrio levy pass & lt (imp & ft up to 16")		G	6.50	13.00
1	SHP SHOP SUPPLIES Loyalty Plan Number: GST Registration# 740515002RT0001		GP	N/C	N/C

**MAINTENANCE**

**RECOMMENDATIONS:**

RETORQUE WHEEL NUTS AFTER 100 KM  
ROTATE TIRES EVERY 10,000KM  
CHECK AIR PRESSURE REGULARLY

**TERMS:**

NET 30 DAYS  
INTEREST 1.5% PER MONTH (19.56 PER ANNUM)  
WILL BE CHARGED ON OVERDUE ACCOUNTS  
I herby acknowledge my indebtness of being the total  
amount of the balance owing of: \_\_\_\_\_

**SIGNATURE X:** \_\_\_\_\_

PARTS:	356.00
LABOUR:	N/C
OTHER:	13.00
<b>SUB-TOTAL:</b>	<b>369.00</b>
GST:	18.45
PST:	21.36
<b>TOTAL:</b>	<b>408.81</b>



# Indian Head Chrysler Dodge Jeep Ram Ltd.

P.O. Box 1015—501 Johnston Avenue  
 Indian Head, SK S0G 2K0  
 Phone: (306) 695-2254 | Fax: (306) 695-2445  
 Toll Free: 1-888-239-4140 | service@ihchrysler.ca  
 www.ihchrysler.ca




## SO# 224296

## SERVICE ORDER CUSTOMER COPY



Printed 12/19/2023 1:43:55 PM

User LoriB Page 1

<b>Customer No</b> 10108	<b>Advisor</b> LoriB	<b>Promised</b> 12/19/2023 5:00 PM
	<b>Shop</b> S1	<b>Opened</b> 12/19/2023 12:55 PM
	<b>Priority</b>	<b>Cashiered</b>
		<b>Location PO #</b>

<b>License</b>	<b>Odom In</b> 216159	<b>Odom Out</b>	<b>In Service Date</b>	<b>Stock No</b>
<b>Year</b> 2010	<b>Make</b> DODGE	<b>Model</b> GRAND CARAVAN	<b>Model Number</b> RTKH53	<b>Colour</b>
<b>Vehicle ID No</b> 2D4RN4DE0AR485546	<b>Selling Dealer</b>	<b>Extended Warranty</b>	<b>Delivery Date</b>	
<b>Engine</b> 3.3L OHV V6 FLEX-FUEL ENGINE				

**Term CASH**

Request	Description	Job	CSR	Status
MIL	Driveability/Check Engine/General Warning Light Concern: Customer has noticed the Malfunctioning Indicator Lamp is on and/or Performance has changed - there is an associated diagnostic time with this service.	1	LORIB	Original

Labour	Description	Type	Amount
MIL	Driveability/Check Engine/General Warning Light Concern: Customer has noticed the Malfunctioning Indicator Lamp is on and/or Performance has changed - there is an associated diagnostic time with this service.	CHIGH	89.98
Technician	GL,3 -	Labour Total	89.98
Cause	VERIFIED THE CUSTOMER'S CONCERN OF CHECK ENGINE LIGHT. ACCESSED THE DIAGNOSTIC PORT AND PERFORMED A SCAN TO FIND STORED CODE(S) P0456 - EVAP SYSTEM SMALL LEAK. PERFORMED A VISUAL INSPECTION AND FOUND EVAP FILTER AND PUMP HAS DIRT IN THEM. FURTHER EXAMINATION FOUND THE EVAPORATIVE CHARCOAL CANISTER PURGE PUMP PLUGGED EVAP FILTER AND PUMP.	<b>Request Sub-total</b>	<b>89.98</b>
Correction	ACCESSED, REMOVED AND REPLACED THE EVAPORATIVE CHARCOAL CANISTER PURGE PUMP. AND EVAP PUMP. CLEARED ALL DIAGNOSTIC TROUBLE CODES. THE SYSTEM IS NOW OPERATING AS DESIGNED.		

Request	Description	Job	CSR	Status
9	Customer has noticed that the key fob is not working and vehicle only runs short n shuts off when use cammand start.	2	LORIB	Original

Labour	Description	Type	Amount
9	Customer has noticed that the key fob is not working and vehicle only runs short n shuts off use cammand start.	CHIGH	89.98
Technician	GL,3 -	Labour Total	89.98
Cause	REPAIR FOR Customer has noticed that the key fob is not working and vehicle only runs short n shuts off when use cammand start WAS PERFORMED ON JOB #1	<b>Request Sub-total</b>	<b>89.98</b>
Correction	THE SYSTEM IS NOW OPERATING AS DESIGNED		

Request	Description	Job	CSR	Status
19W09182	Safety Recall W09 Transport Canada 2020-311 Driver Air Bag Emblem	3	LORIB	Approved

Labour	Description	Type	Amount
19W09182	Safety Recall W09 Transport Canada 2020-311 Driver Air Bag Emblem	W	

<b>OUT</b>	Indebtedness is hereby acknowledged for the "total charges" being all or the balance owing for repairs, parts & accessories described in this work order.	
	if your wheels were removed during this service appointment, it is important to have your wheels re-torqued after 100 kilometers	
	TEXTING DISCLAIMER: Indian Head has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.	
	EMAIL: If you would like to receive emails from us for updates, offers and much more please provide your email address here: _____	
	if you do not want to be contacted, please check here <input type="checkbox"/>	
	DATE: _____	CUSTOMER SIGNATURE: _____

G.S.T # 828345132 RT 0001



# Indian Head Chrysler Dodge Jeep Ram Ltd.

P.O. Box 1015—501 Johnston Avenue  
Indian Head, SK S0G 2K0  
Phone: (306) 695-2254 | Fax: (306) 695-2445  
Toll Free: 1-888-239-4140 | service@ihchrysler.ca  
www.ihchrysler.ca



## SO# 224296

## SERVICE ORDER CUSTOMER COPY



Printed 12/19/2023 1:43:55 PM

User LoriB Page 2

<b>Customer No</b> 10108	<b>Advisor</b> LoriB	<b>Promised</b> 12/19/2023 5:00 PM
	<b>Shop</b> S1	<b>Opened</b> 12/19/2023 12:55 PM
	<b>Priority</b>	<b>Cashiered</b>
		<b>Location</b> PO #

<b>License</b>	<b>Odom In</b> 216159	<b>Odom Out</b>	<b>In Service Date</b>	<b>Stock No</b>
<b>Year</b> 2010	<b>Make</b> DODGE	<b>Model</b> GRAND CARAVAN	<b>Model Number</b> RTKH53	<b>Colour</b>
<b>Vehicle ID No</b> 2D4RN4DE0AR485546	<b>Selling Dealer</b>	<b>Extended Warranty</b>	<b>Delivery Date</b>	
<b>Engine</b> 3.3L OHV V6 FLEX-FUEL ENGINE				

**Term** CASH

**Cause** CUSTOMER REQUESTED CAMPAIGN NUMBER W09 BE PERFORMED. PERFORMED A COMPLETE VEHICLE IDENTIFICATION NUMBER STATUS INQUIRY TO FIND AND VERIFY AN OPEN CAMPAIGN. THE VEHICLE MAY HAVE A LOOSE OR MISSING BRAND EMBLEM IN THE CENTER OF THE STEERING WHEEL AND THE LOOSE EMBLEM OR THE SECURING NUTS FOR THE EMBLEM WITHIN THE DRIVER AIRBAG MODULE MAY BECOME PROJECTILES IN THE EVENT OF A DRIVER AIRBAG DEPLOYMENT.

**Correction** THE PARTS HAVE NOW BEEN ORDERED AS PER RECALL INSTRUCTIONS.

Request	Description	Job	CSR	Status			
10C	During Inspection Found EVAP PUMP AND FILTER NEEDS TO BE REPLACED	4	LORIB	Approved			
Labour	Description	Type	Amount				
10C	During Inspection Found EVAP PUMP AND FILTER NEEDS TO BE REPLACED	C	169.95				
Part	Description	Shp	Bin	Type	Price	Amount	
4861962AD	DETECTOR	1	L05	CSO	117.02	117.02	
52129436AB	SEAL	1	K07	CSO	26.93	26.93	
4627332AB	FILTER	1	L05	CSO	70.89	70.89	
Technician	GL,3 -	Parts Total				214.84	
Cause	REPLACE EVAP PUMP AND FILTER	Labour Total				169.95	
Correction	REPLACED EVAP PUMP AND FILTER	<b>Request Sub-total</b>				<b>384.79</b>	
						Labour	349.91
						Parts	214.84
						Supplies	41.43
						<b>Sub-Total</b>	<b>606.18</b>
						GST	30.31
						PST	36.37
						<b>Total Invoice</b>	<b>672.86</b>

### Moved Services

Code	Description
19W09182	Safety Recall W09 Transport Canada 2020-311 Driver Air Bag Emblem

Transferred to  
Est 108181

Indebtedness is hereby acknowledged for the "total charges" being all or the balance owing for repairs, parts & accessories described in this work order.  
If your wheels were removed during this service appointment, it is important to have your wheels re-torqued after 100 kilometers.

**TEXTING DISCLAIMER:** Indian Head has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

EMAIL: If you would like to receive emails from us for updates, offers and much more please provide your email address here: \_\_\_\_\_

If you do not want to be contacted, please check here

DATE: \_\_\_\_\_ CUSTOMER SIGNATURE: \_\_\_\_\_

G.S.T # 828345132 RT 0001



**SERVICE & PARTS**  
MOPAR PEOPLE. MOPAR PARTS.

# VEHICLE CHECKUP

Repair Order No.: **219604**

Metreage: **94391**

Dealer rep: **LoriB** Customer: [REDACTED]

CUSTOMER NAME AND ADDRESS VERIFIED AND UPDATED

SERVICE HISTORY CHECK




RECALL CHECK

CHECKED AND OK

MAY REQUIRE FURTHER ATTENTION

REQUIRES IMMEDIATE ATTENTION

GREEN SERVICE



**COURTESY INSPECTION**

Lights		Reverse lights		Windshield	
High/low beam lights	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	License plate light	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Inspect for cracks or stone chips	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
Parking lights	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Horn	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Under Hood	
Right front signal light	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Functional	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Washer fluid	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
High rear signal light	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Wipers		Coolant level & condition	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
Left front signal light	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Left wiper arm & blade	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Brake fluid level & condition	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
Left rear signal light	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Right wiper arm & blade	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Power steering fluid level & condition	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
Left brake lights	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Rear wiper arm & blade	N/A	Transmission fluid level & condition	N/A <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
Centre brake lights	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Windshield washer operation	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	Air filter	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
Right brake lights	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			Diesel Exhaust Fluid (DEF)	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>

Tires - Size:		Condition		PSI		Condition	
Left Front		<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>		Right Front		<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
Left Rear		<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>		Right Rear		<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
		7 mm / 9/32 in. or more		3 mm to 6 mm / 4/32 in. to 9/32 in.		2 mm / 3/32 in. or less	

**SERVICE MAINTENANCE 1**

<input checked="" type="checkbox"/> Engine Oil Change	<input checked="" type="checkbox"/> Under Vehicle	<input checked="" type="checkbox"/> Reset oil change indicator	N/A
<input checked="" type="checkbox"/> Install Mopar oil filter	<input checked="" type="checkbox"/> Chassis lubrication	<input checked="" type="checkbox"/> Lubrication of door latches, locks and weatherstrips	
<input checked="" type="checkbox"/> Install Mopar motor oil	<input checked="" type="checkbox"/> Courtesy inspection	<input checked="" type="checkbox"/> Inspect for any fluid or fuel leaks	
<input checked="" type="checkbox"/> Under Vehicle	<input checked="" type="checkbox"/> Inspect belts & hoses	<input checked="" type="checkbox"/> Battery inspection & test	
<input checked="" type="checkbox"/> Exhaust system	<input checked="" type="checkbox"/> Inspect brake lines and hoses		

**SERVICE MAINTENANCE 2 - SEMI-ANNUAL PEACE OF MIND (INCLUDES ITEMS IN SERVICE MAINTENANCE 1 PLUS THE FOLLOWING)**

<input checked="" type="checkbox"/> Tire rotation	<input checked="" type="checkbox"/> Reset Tire Pressure Monitor	N/A	<input checked="" type="checkbox"/> Check spare
---	---	-----	---

Brakes	LF	RF	LR	RR
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	7 mm / 9/32 in. or more			7 mm / 9/32 in. or more
	3 mm to 6 mm / 4/32 in. to 9/32 in.			3 mm to 6 mm / 4/32 in. to 9/32 in.
	2 mm / 3/32 in. or less			2 mm / 3/32 in. or less

Suspension/Steering	Performance
Constant force by joints and boots	Restraint system
Front suspension	Road test
Rear suspension	
Steering system and linkage	Lubricate front driveshaft fittings
	<input checked="" type="checkbox"/> N/A

**SERVICE MAINTENANCE 3 - ANNUAL PEACE OF MIND (INCLUDES PACKAGE 1 AND 2 PLUS THE FOLLOWING)**

Suspension/Steering	Drivetrain
Alignment	Differential fluid
	(Change if vehicle used for police, taxi fleet, off-road or trailer towing)
Performance	Transfer case fluid
Replace cabin air filter	N/A
Under Hood	
Clean & tighten battery connections	
Replace air filter (diesel engines)	


**SCHEDULED MAINTENANCE SERVICES**

Services vary by application, consult owner's manual for recommended intervals

Flush and replace engine coolant	Replace timing belt	Change automatic transmission fluid and filter
Replace spark plugs	Inspect and replace PCV valve	Change manual transmission fluid and filter
Replace spark plugs and ignition cables	Replace fuel filter/water separator unit (diesel engines)	Change transfer case fluid
Replace accessory drive belts		

Next appointment date: \_\_\_\_\_ Service required: \_\_\_\_\_ \$ \_\_\_\_\_

NOTES





# Indian Head Chrysler Dodge Jeep Ram Ltd.

P.O. Box 1015—501 Johnston Avenue  
Indian Head, SK S0G 2K0  
Phone: (306) 695-2254 | Fax: (306) 695-2445  
Toll Free: 1-888-239-4140 | service@ihchrysler.ca  
www.ihchrysler.ca



## SO # 219600

## SERVICE ORDER CUSTOMER COPY



Printed 10/13/2022 3:27:11 PM

User Holly Page 1

Customer No 10108

Advisor Holly Promised 10/13/2022 5:00 PM Tag  
Shop S1 Opened 10/13/2022 9:51 AM Location  
Priority Cashiered 10/13/2022 3:27 PM PO #

License No Odometer In Odometer Out InServ Date Stock No  
199405 199406  
Year Make Model Model No Colour  
2010 DODGE GRAND CARAVAN RTKH53  
Vehicle ID No Selling Dealer Extended Warranty Delivery Date  
2D4RN4DE0AR485546  
Engine Size 3.3L OHV V6 FLEX-FUEL ENGINE Fleet #

Term CASH

Request	Description	Job	CSR	Status
MIL	Driveability/Check Engine/General Warning Light Concern: Customer has noticed the Malfunctioning Indicator Lamp is on and/or Performance has changed - there is an associated diagnostic time with this service.	1	HOLLY	Original
Labour	Description	Type	Amount	
MIL	Driveability/Check Engine/General Warning Light Concern: Customer has noticed the Malfunctioning Indicator Lamp is on and/or Performance has changed - there is an associated diagnostic time with this service.	C	79.98	
Technician	LG,2 -	Parts Total	0.00	
Cause	Checked dtc's and found active tipm dtc p0073 Ambient air temperature sensor circuit high. Inspected ambient air temperature sensor on front bumper. Inspected connector and has no damage or corrosion. Wiring from harness to connector is good. Used a jumper wire across connector to check if wiring is working correct and showed circuit low dtc and that wiring is working correct. Ambient air temp sensor is faulty and will need to be replaced.	Labour Total	79.98	
		<b>Request Sub-total</b>	<b>79.98</b>	

Request	Description	Job	CSR	Status
CT-95370251	The customer has been offered courtesy transportation in the form of a shuttle to/from downtown and/or a Service Rental Vehicle.	2	HOLLY	Original
Labour	Description	Type	Amount	
CT-95370251	The customer has been offered courtesy transportation in the form of a shuttle to/from downtown and/or a Service Rental Vehicle.	C	0.00	
Technician	HF -	Parts Total	0.00	
Cause	The customer has been offered courtesy transportation in the form of a shuttle to/from downtown and/or a Service Rental Vehicle.	Labour Total	0.00	
		<b>Request Sub-total</b>	<b>0.00</b>	

Request	Description	Job	CSR	Status
19W09182	Safety Recall W09 Transport Canada 2020-311 Driver Air Bag Emblem	3	HOLLY	Original
Labour	Description	Type	Amount	
19W09182	Safety Recall W09 Transport Canada 2020-311 Driver Air Bag Emblem	W		

Part	Description	Shp	Bin	Type	Price	Amount
CSZCW095AA	COVER	0	S11	W		

Indebtedness is hereby acknowledged for the "total charges" being all or the balance owing for repairs, parts & accessories described in this work order.  
If your wheels were removed during this service appointment, it is important to have your wheels re-torqued after 100 kilometers.

**TEXTING DISCLAIMER:** Indian Head has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

**EMAIL:** If you would like to receive emails from us for updates, offers and much more please provide your email address here: \_\_\_\_\_

If you do not want to be contacted, please check here

DATE: \_\_\_\_\_ CUSTOMER SIGNATURE: \_\_\_\_\_

G.S.T # S28345132 RT 0001



# Indian Head Chrysler Dodge Jeep Ram Ltd.

P.O. Box 1015—501 Johnston Avenue  
 Indian Head, SK S0G 2K0  
 Phone: (306) 695-2254 | Fax: (306) 695-2445  
 Toll Free: 1-888-239-4140 | service@ihchrysler.ca  
 www.ihchrysler.ca




## SO # 219600

## SERVICE ORDER CUSTOMER COPY



Printed 10/13/2022 3:27:11 PM

User Holly Page 2

<b>Customer No</b> 10108	<b>Advisor</b> Holly	<b>Promised</b> 10/13/2022 5:00 PM	<b>Tag</b>
	<b>Shop</b> S1	<b>Opened</b> 10/13/2022 9:51 AM	<b>Location</b>
	<b>Priority</b>	<b>Cashiered</b> 10/13/2022 3:27 PM	<b>PO #</b>

<b>License No</b>	<b>Odometer In</b> 199405	<b>Odometer Out</b> 199406	<b>InServ Date</b>	<b>Stock No</b>
<b>Year</b> 2010	<b>Make</b> DODGE	<b>Model</b> GRAND CARAVAN	<b>Model No</b> RTKH53	<b>Colour</b>
<b>Vehicle ID No</b> 2D4RN4DE0AR485546	<b>Selling Dealer</b>	<b>Extended Warranty</b>	<b>Delivery Date</b>	
<b>Engine Size</b> 3.3L OHV V6 FLEX-FUEL ENGINE	<b>Fleet #</b>			

CSZAW099AA	TAPE	1	K05	W	
Correction	parts are needing to be ordered	Parts Total			0.00
		Labour Total			0.00
		<b>Request Sub-total</b>			<b>0.00</b>

Request	Description	Job	CSR	Status		
9	Remove and replace ambient air temp sensor.	4	HOLLY	Approved		
Labour	Description	Type	Amount			
9	Remove and replace ambient air temp sensor.	C	84.98			
Sublet	Description	Type	CSR	Amount		
		CSUB	SV	0.00		
Part	Description	Shp	Bin	Type	Price	Amount
68518243AA	SENSOR	1	L07	CSO	47.97	47.97
oh						
Technician	LG,2 -	Parts Total				47.97
Cause	VERIFIED THE CUSTOMER'S CONCERN. ACCESSED THE DIAGNOSTIC PORT AND PERFORMED A SCAN. FOUND THE EXTERIOR AIR TEMPERATURE SENSOR IS THE POINT OF CONCERN. FURTHER EXAMINATION FOUND THE EXTERIOR AIR TEMPERATURE SENSOR HAS AN OPEN CIRCUIT.	Labour Total				84.98
Correction	ACCESSED, REMOVED AND REPLACED THE EXTERIOR AIR TEMPERATURE SENSOR. CLEARED ALL DIAGNOSTIC TROUBLE CODES. THE SYSTEM IS NOW OPERATING AS DESIGNED.	<b>Request Sub-total</b>				<b>132.95</b>

Indebtedness is hereby acknowledged for the "total charges" being all or the balance owing for repairs, parts & accessories described in this work order.

If your wheels were removed during this service appointment, it is important to have your wheels re-torqued after 100 kilometers.

**TEXTING DISCLAIMER:** Indian Head has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

EMAIL: if you would like to receive emails from us for updates, offers and much more please provide your email address here: \_\_\_\_\_

if you do not want to be contacted, please check here

DATE \_\_\_\_\_ CUSTOMER SIGNATURE \_\_\_\_\_

G.S.T # 828345132 RT 00G1



Indian Head Chrysler Dodge Jeep Ram Ltd.

P.O. Box 1015—501 Johnston Avenue
Indian Head, SK S0G 2K0
Phone: (306) 695-2254 | Fax: (306) 695-2445
Toll Free: 1-888-239-4140 | service@ihchrysler.ca
www.ihchrysler.ca



SO # 219600

SERVICE ORDER
CUSTOMER COPY



Printed 10/13/2022 3:27:11 PM

User Holly Page 3

Customer No 10108
Advisor Holly Promised 10/13/2022 5:00 PM Tag
Shop S1 Opened 10/13/2022 9:51 AM Location
Priority Cashiered 10/13/2022 3:27 PM PO #
License No Odometer In Odometer Out InServ Date Stock No
Year Make Model Model No Colour
2010 DODGE GRAND CARAVAN RTKH53
Vehicle ID No Selling Dealer Extended Warranty Delivery Date
2D4RN4DE0AR485546
Engine Size 3.3L OHV V6 FLEX-FUEL ENGINE Fleet #
Term CASH

Table with 2 columns: Description and Amount. Rows include Labour (164.96), Parts (47.97), Supplies (19.53), SUB-TOTAL (232.46), GST (11.62), PST (13.95), TOTAL INVOICE (258.03), Debit (258.03), Less Deposit Received (258.03), and Balance Due (0.00).

OUT
I hereby acknowledge for the "total charges" being all or the balance owing for repairs, parts & accessories described in this work order.
if your wheels were removed during this service appointment, it is important to have your wheels re-torqued after 100 kilometers.
TEXTING DISCLAIMER: Indian Head has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.
EMAIL: if you would like to receive emails from us for updates, offers and much more please provide your email address here:
if you do not want to be contacted, please check here [ ]
DATE CUSTOMER SIGNATURE
G.S.T # 828345132 RT 0001



# Indian Head Chrysler Dodge Jeep Ram Ltd.

P.O. Box 1015—501 Johnston Avenue  
Indian Head, SK S0G 2K0  
Phone: (306) 695-2254 | Fax: (306) 695-2445  
www.ihchrysler.ca | service@ihchrysler.ca



## SO# 225142

## SERVICE ORDER CUSTOMER COPY




Printed 03/20/2024 12:17:25 PM

User LoriB Page 1

Customer No 10108

<b>Advisor</b> Holly	<b>Promised</b> 03/20/2024 5:00 PM	<b>Tag#</b>
<b>Shop</b> S1	<b>Opened</b> 03/20/2024 10:53 AM	<b>Location</b>
<b>Priority</b>	<b>Cashiered</b>	<b>PO #</b>



Term Cash

<b>License</b>	<b>Odom In</b> 222218	<b>Odom Out</b> 222219	<b>In Service Date</b>	<b>Stock No</b>
<b>Year</b> 2010	<b>Make</b> DODGE	<b>Model</b> GRAND CARAVAN	<b>Model Number</b> RTKH53	<b>Colour</b>
<b>Vehicle ID No</b> 2D4RN4DE0AR485546	<b>Selling Dealer</b>	<b>Extended Warranty</b>	<b>Delivery Date</b>	
<b>Engine</b> 3.3L OHV V6 FLEX-FUEL ENGINE				

Request	Description	Job	CSR	Status
MIL	Driveability/Check Engine/General Warning Light Concern: Customer has noticed the Malfunctioning Indicator Lamp is on and/or Performance has changed - there is an associated diagnostic time with this service.	1	HOLLY	Original
Labour	Description	Type	Amount	
MIL	Driveability/Check Engine/General Warning Light Concern: Customer has noticed the Malfunctioning Indicator Lamp is on and/or Performance has changed - there is an associated diagnostic time with this service.	CHIGH	179.95	
Technician	DT,3 -	Labour Total	179.95	
Cause	Mil lamp is on, checked for codes, found p0456 Evap small leak, performed leak test, only test available is a large leak test, passes large leak test. lifted vehicle, LDP and filter have been previously replaced, inspected EVAP lines, lines all good, removed leak detection pump from charcoal canister, charcoal canister has lots of dust inside, checked gascap, seal on gascap looks like it may be leaking, cleaned off gascap and lubed to seal.	<b>Request Sub-total</b>	<b>179.95</b>	
Correction	Cleared codes, if code returns, suggest replacing gascap.			

Labour	179.95
Parts	0.00
Supplies	21.31
<b>Sub-Total</b>	<b>201.26</b>
GST	10.06
PST	12.08
<b>Total Invoice</b>	<b>223.40</b>

Indebtedness is hereby acknowledged for the "total charges" being all or the balance owing for repairs, parts & accessories described in this work order.  
 If your wheels were removed during this service appointment, it is important to have your wheels re-torqued after 100 kilometers.  
**TEXTING DISCLAIMER:** Indian Head has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.  
**EMAIL:** If you would like to receive emails from us for updates, offers and much more please provide your email address here: \_\_\_\_\_  
 If you do not want to be contacted, please check here

DATE: \_\_\_\_\_ CUSTOMER SIGNATURE: \_\_\_\_\_

G.S.T # 828345132 RT 0001



# Indian Head Chrysler Dodge Jeep Ram Ltd.

P.O. Box 1015—501 Johnston Avenue  
 Indian Head, SK S0G 2K0  
 Phone: (306) 695-2254 | Fax: (306) 695-2445  
 Toll Free: 1-888-239-4140 | service@ihchrysler.ca  
 www.ihchrysler.ca



## SO # 215940

## SERVICE ORDER CUSTOMER COPY



Printed 11/16/2021 12:27:59 PM

User Howard Page 1

<b>Customer No</b> 10108	<b>Advisor</b> Holly	<b>Promised</b> 11/16/2021 5:00 PM	<b>Tag</b>
	<b>Shop</b> S1	<b>Opened</b> 11/16/2021 10:57 AM	<b>Location</b>
	<b>Priority</b>	<b>Cashiered</b>	<b>PO #</b>

<b>License No</b>	<b>Odometer In</b> 186203	<b>Odometer Out</b> 186203	<b>InServ Date</b>	<b>Stock No</b>
<b>Year</b> 2010	<b>Make</b> DODGE	<b>Model</b> GRAND CARAVAN	<b>Model No</b> RTKH53	<b>Colour</b>
<b>Vehicle ID No</b> 2D4RN4DE0AR485546	<b>Selling Dealer</b>	<b>Extended Warranty</b>	<b>Delivery Date</b>	
<b>Engine Size</b> 3.3L OHV V6 FLEX-FUEL ENGINE	<b>Fleet #</b>			

Term CASH

Request	Description	Job	CSR	Status		
9	Supplly and program key per estimate#106442	1	HOLLY	Original		
Labour	Description	Type	Amount			
9	Supplly and program key per estimate#106442	C	74.98			
Part	Description	Shp	Bin	Type	Price	Amount
56046709AG	TRANSMTR	1	S14	CSO	205.35	205.35
Technician	JT,3 -	Parts Total				205.35
Cause	Customer requested replace and program new key fob.	Labour Total				74.98
Correction	Replaced and programmed new key fob.	<b>Request Sub-total</b>				<b>280.33</b>

Request	Description	Job	CSR	Status		
9	Customer has noticed that there is steam coming from engine an leaking	2	HOLLY	Original		
Labour	Description	Type	Amount			
9	Customer has noticed that there is steam coming from engine an leaking	C	149.95			
Part	Description	Shp	Bin	Type	Price	Amount
05163620Q	fittings	1		CSO	8.55	8.55
VU01524AC	COOLANT	1	SHIPPING	CSO	24.90	24.90
Technician	JT,3 -	Parts Total				33.45
Cause	Checked for leaks. Found that the coolant supply/return bundle plastic Y pipe has cracked and spraying coolant everywhere. Will need to replace the coolant hose bundle and fill with coolant.	Labour Total				149.95
Correction	Talked to customer, he asked if we could get the vehicle driveable to get it back home. Went to the Co-op and bought some plastic fittings. Cut out failed part and installed plastic fittings and hose. Filled cooling system with coolant and rinsed off engine. Checked for leaks, no leaks.	<b>Request Sub-total</b>				<b>183.40</b>

Indebtedness is hereby acknowledged for the "total charges" being all or the balance owing for repairs, parts & accessories described in this work order.  
 If your wheels were removed during this service appointment, it is important to have your wheels re-torqued after 100 kilometers.

**TEXTING DISCLAIMER:** Indian Head has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

**EMAIL:** If you would like to receive emails from us for updates, offers and much more please provide your email address here: \_\_\_\_\_

If you do not want to be contacted, please check here

DATE \_\_\_\_\_ CUSTOMER SIGNATURE: \_\_\_\_\_

G.S.T # S28345137 FT



# Indian Head Chrysler Dodge Jeep Ram Ltd.

P.O. Box 1015—501 Johnston Avenue  
Indian Head, SK S0G 2K0  
Phone: (306) 695-2254 | Fax: (306) 695-2445  
Toll Free: 1-888-239-4140 | service@ihchrysler.ca  
www.ihchrysler.ca



## SO # 215940

## SERVICE ORDER CUSTOMER COPY



Printed 11/16/2021 12:27:59 PM

User Howard Page 2

<b>Customer No</b> 10108	<b>Advisor</b> Holly	<b>Promised</b> 11/16/2021 5:00 PM	<b>Tag</b>
<b>Shop</b> S1	<b>Priority</b>	<b>Opened</b> 11/16/2021 10:57 AM	<b>Location</b>
		<b>Cashiered</b>	<b>PO #</b>

<b>License No</b>	<b>Odometer In</b> 186203	<b>Odometer Out</b> 186203	<b>InServ Date</b>	<b>Stock No</b>
<b>Year</b> 2010	<b>Make</b> DODGE	<b>Model</b> GRAND CARAVAN	<b>Model No</b> RTKH53	<b>Colour</b>
<b>Vehicle ID No</b> 2D4RN4DE0AR485546	<b>Selling Dealer</b>	<b>Extended Warranty</b>	<b>Delivery Date</b>	
<b>Engine Size</b> 3.3L OHV V6 FLEX-FUEL ENGINE	<b>Fleet #</b>			

Term CASH

Labour	224.93
Parts	238.80
Supplies	26.63
<b>SUB-TOTAL</b>	<b>490.36</b>
GST	24.52
PST	29.42
<b>TOTAL INVOICE</b>	<b>544.30</b>

### Recommended/Deferred Services

Code	Description	Amount
9	Replace the front heater core supply/return hose bundle. The plastic Y fitting has cracked.	\$526.20

\*\* Deferred Services prices are subject to change

Indebtedness is hereby acknowledged for the "total charges" being all or the balance owing for repairs, parts & accessories described in this work order.

If your wheels were removed during this service appointment, it is important to have your wheels re-torqued after 100 kilometers.

TEXTING DISCLAIMER: Indian Head has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

EMAIL: If you would like to receive emails from us for updates, offers and much more please provide your email address here: \_\_\_\_\_

If you do not want to be contacted, please check here

DATE: \_\_\_\_\_ CUSTOMER SIGNATURE: \_\_\_\_\_

G.S.T # 82834513.2 RT 0001

**FORT TOWING AND SERVICE**  
**BOX 1096**  
**FORT QU'APPELLE, SK S0G 1S0**  
**PH: (306) 332-5625**

B017

DATE

NOV 5/01

NAME NOM	[REDACTED]
ADDRESS ADRESSE	[REDACTED]

SOLD BY VENDU PAR	COD C.R.	CHARGE FACTURE	ON ACCOUNT A CREDIT	AMOUNT FWD. MONTANT REPORTE
----------------------	-------------	-------------------	------------------------	--------------------------------

1		COOPER Eviction winter		
2				
3		H-225/6-5/17	150.94	723.80
4				
5		H-5500	5.00	20.00
6		INSTALL Mass Plans		72.00
7		R/R Calpa Product & Clean		
8		Calpa Pens		
9				815.80
10				
			TVH/HST TPS/GST	40.79
			PST/TPV	47.75
			TOTAL	904.34

*Put in  
account with 10/21*

42

**FORT TOWING AND SERVICE**  
**BOX 1096**  
**FORT QU'APPELLE, SK S0G 1S0**  
**PH: (306) 332-5625**

B019

DATE

DEC 22/01

NAME NOM	[REDACTED]
ADDRESS ADRESSE	[REDACTED]

SOLD BY VENDU PAR	COD C.R.	CHARGE FACTURE	ON ACCOUNT A CREDIT	AMOUNT FWD. MONTANT REPORTE
----------------------	-------------	-------------------	------------------------	--------------------------------

		2010 Dodge Durango - 3.3L		
1		Oil, Filter, Gas		16.00
2		4.7L 5-20 spv.		46.71
3		1- Oil Filter 51348		13.95
4		Emulsion		1.80
5		R/R Power Steering hoses 2.5h		245.00
6		1- EMH/92565 Power		
7		Shocks Pass. W/steer		186.95
8		Power steering fluid		9.00
9		Freight		20.00
10				539.47
			TVH/HST TPS/GST	26.97
			PST/TPV	32.37
			TOTAL	598.81

9

# SOLVEY MOTORS LTD. & AUTOBODY SHOP

P.O. BOX 9  
FORT QU'APPELLE, SASK. SOG 1S0  
PHONE 332-5240

4731

2% Interest per Month Charged on All Overdue Accounts.

QUAN	PART NO.	DESCRIPTION	AMT. PARTS
	ENVURO FEE		100
1	PA 3614	oil filter	995
47	LN FULL SYN. OIL		5147
	WW FLU 10		300
1	MT 34	BATTERY	16695
	INSTALL	2 YEAR WARRANTY	
1	A/C DYE		1995
2.5	LIBS 12-134	coolant	4738
	SHOP MAT		600
			30570

M [REDACTED] DATE JULY 22 21  
ADDRESS [REDACTED]

MAKE & MODEL 2010 VOLVO C30	ODOMETER 162364	SERIAL NO.	LICENSE 333 K6K
-----------------------------------	--------------------	------------	--------------------

DESCRIPTION OF WORK	AMOUNT
SERVICE	20.00
LOAD TEST BATTERY FAILS REPLACE BATTERY. OVA TEST CHARGING OIL	55.00
CHECK A/C NOT BLOWING COOL. CHECK FUSES O.K. EVACUATE SYSTEM	110.00
RECHARGE SYSTEM WITH A/C DYE	

I HEREBY AUTHORIZE THE ABOVE WORK TO BE DONE TOGETHER WITH NECESSARY MATERIALS.

SIGNATURE \_\_\_\_\_

I HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE AMOUNT OF \$ \_\_\_\_\_ BEING, THE TOTAL AMOUNT OWING, OR BALANCE OWING AS SHOWN HEREON.

DATE \_\_\_\_\_ SIGNATURE \_\_\_\_\_

TOTAL LABOUR	185.00
TOTAL PARTS	30570
GST	2454
PST	2944
<b>TOTAL</b>	<b>544 68</b>

ALL ESTIMATES ARE FOR LABOUR ONLY. MATERIALS ADDITIONAL. THIS COMPANY DOES NOT ASSUME ANY RESPONSIBILITY WHATSOEVER FOR UNITS LEFT FOR REPAIRS, STORAGE OR OTHER PURPOSES OR FOR ARTICLES LEFT IN UNITS, UNITS DRIVEN BY OUR EMPLOYEES AT OWNER'S RISK.

PAID DEBIT

R121720429

306 332 4162

# SOLVEY MOTORS LTD. & AUTOBODY SHOP

P.O. BOX 9  
FORT QU'APPELLE, SASK. SOG 1S0  
PHONE 332-5240

5178

2% Interest per Month Charged on All Overdue Accounts.

QUAN	PART NO.	DESCRIPTION	AMT. PARTS
1	20 1326	Brake Pads	780
2	900 526	Rotor 75-9	150.00
1	89X 17731A	Caliper	195.00
1	89X 17731B	Caliper	195.00
	SHOP MAT / BRK FLUID		150.00
			633.00

M [REDACTED] DATE DEC 14 21  
ADDRESS [REDACTED]

MAKE & MODEL 2010 VOLVO C30	ODOMETER 188756	SERIAL NO.	LICENSE 333 K6K
-----------------------------------	--------------------	------------	--------------------

DESCRIPTION OF WORK	AMOUNT
LOCATE BRAKE FLUID LEAK.	
REMOVE AND REPLACE REAR BRAKE PADS AND ROTORS. INSTALL NEW REAR	330.00
BRAKE CALIPERS. BLEED BRAKE SYSTEM	
ROAD TEST O.K. 3.0	

I HEREBY AUTHORIZE THE ABOVE WORK TO BE DONE TOGETHER WITH NECESSARY MATERIALS.

SIGNATURE \_\_\_\_\_

I HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE AMOUNT OF \$ \_\_\_\_\_ BEING, THE TOTAL AMOUNT OWING, OR BALANCE OWING AS SHOWN HEREON.

DATE \_\_\_\_\_ SIGNATURE \_\_\_\_\_

TOTAL LABOUR	330.00
TOTAL PARTS	633.00
GST	4815
PST	5778
<b>TOTAL</b>	<b>1068 93</b>

ALL ESTIMATES ARE FOR LABOUR ONLY. MATERIALS ADDITIONAL. THIS COMPANY DOES NOT ASSUME ANY RESPONSIBILITY WHATSOEVER FOR UNITS LEFT FOR REPAIRS, STORAGE OR OTHER PURPOSES OR FOR ARTICLES LEFT IN UNITS, UNITS DRIVEN BY OUR EMPLOYEES AT OWNER'S RISK.

PAID DEBIT

R121720429