

Dean & Daughters Repair Shop Ltd.  
 116 Hwy #47 South  
 Box 1504  
 Estevan, SK S4A 2L7  
 (306) 634-5114

# Invoice

Date	Invoice #
11/09/2023	8568

Invoice To
102168648 Saskatchewan Ltd.
[Redacted]

Vehicle Mileage	VIN	Unit #/Vehicle Info.
235697	1FT8W3BT5JEB78176	'18 F350 4x4 6.7L

Description	Amount
Remove & Replace Both Side Front Axle U-Joints, Both Side Front Outer Axle Seals and Dust Seals. Remove & Replace Both Front and Rear Driveshafts to Check - All Good. Remove & Replace Rear Brake Pads and Both Side Rear Rotors to Resurface. Remove & Replace Driver's Side Rear E-Brake Shoes. Unseize Rear Caliper Bolts. Remove & Replace Fuel Filter	1,932.00
U-Joint	282.28
Front Axle Seal	342.24
Front Axle Spindle Seal	65.38
Brake Pad Set	170.67
Resurface Brake Rotors	110.00
Fuel Filter	168.51
<b>SUBTOTAL</b>	<b>3,071.08</b>
Shop Supplies & Environmental Waste/Disposal	129.99
GST on sales	160.05

<p>ALL INVOICES DUE UPON COMPLETION OF SERVICES AND BEFORE THE VEHICLE LEAVES OUR SHOP!!! Thank-you          ***REMEMBER TO RETORQUE WHEELS AFTER 100 KM'S***</p>	<p><b>Total</b> \$3,361.12</p>
---	--------------------------------