

	ER28	SEG1AKBC1KW025349	YBY6566	11-7-2024	0.00	100.00	FINISH WIRING
	ER28	SEG1AKBC1KW025349	YBY6566	6-4-2024	0.00	100.00	Replace all 3 batteries. Had to pick them up at fleet pride
	ER28	SEG1AKBC1KW025349	YBY6566	4-12-2024	0.00	100.00	Replaced return hydro hose near D1L brake hoses and help Scott with replacing a main hydro hose
	ER28	SEG1AKBC1KW025349	YBY6566	11-11-2024	0.00	100.00	TEST FOUND PUMP FALED NEEDS TO BE REPLACED NEED INVOICE FOR WARRENTY
Lot#120	ER32	1FVACYFE2LHLC2951	YBY3874	4-26-2024	8,230.00	8,230.00	Replaced hydraulic hoses on arm 4/12 GS - replaced hydraulic hoses on upper arm. 12 fittings, 6 hoses, & 1 o-ring. 4/17 GS - Replaced 1 broken snapped finger, bent other finger back in place. Replaced 2 backing bars. (1 missing, one snapped off) hopper cover not open
	ER32	1FVACYFE2LHLC2951	YBY3874	3-4-2026	1,991.77	1,991.77	installed reach cylinder
	ER32	1FVACYFE2LHLC2951	YBY3874	3-25-2026	1,737.28	1,737.28	DIAG REACH CYLINDER
	ER32	1FVACYFE2LHLC2951	YBY3874	1-23-2025	1,690.16	1,690.16	R&R REACH CYLINDER
	ER32	1FVACYFE2LHLC2951	YBY3874	3-19-2025	1,690.16	1,690.16	REINSTALL HARNESS
	ER32	1FVACYFE2LHLC2951	YBY3874	5-2-2022	1,562.70	1,562.70	replaced sensor and trolley motor transducer
	ER32	1FVACYFE2LHLC2951	YBY3874	4-23-2024	1,562.70	1,562.70	Trolley position sensor, replace
	ER32	1FVACYFE2LHLC2951	YBY3874	4-27-2022	1,389.64	1,389.64	replaced all drives. torqued lug nuts to 500ft-lbs
	ER32	1FVACYFE2LHLC2951	YBY3874	3-12-2024	1,152.20	1,152.20	resealed valve body cleaned drained side tank part parker seal kit 393000k871
	ER32	1FVACYFE2LHLC2951	YBY3874	1-20-2025	1,149.99	1,149.99	arm banging and jerky replaced reach harness upon running radiator decide to burst R&R radiator
	ER32	1FVACYFE2LHLC2951	YBY3874	11-1-2021	915.70	915.70	replaced steer tires.
	ER32	1FVACYFE2LHLC2951	YBY3874	3-22-2024	908.58	908.58	parts bill out and drop off at boyer
	ER32	1FVACYFE2LHLC2951	YBY3874	4-26-2024	823.00	823.00	find short and fix wires to side marker light 4/11 headlight high-beam replacement. Used 1 part. 4/17 - Bubble work light replacement. 4 SS parts used for deutsche plug
	ER32	1FVACYFE2LHLC2951	YBY3874	4-29-2025	0.00	622.80	INSTALL PRESSURE REILF VALVE
	ER32	1FVACYFE2LHLC2951	YBY3874	2-22-2024	559.98	559.98	filled tranny filled hyro adjusted brakes Replaced trans cooler lines
	ER32	1FVACYFE2LHLC2951	YBY3874	1-22-2025	469.56	469.56	ARM LOSING CALAIBRATION RANGE LOW ERROR REPLACED HARNESS ARM REACH ON RETRACT GOES TO ZERO 2 FEET AWAY BODY THEN LOSS UPTIGHT NEED REACH CYLINDER PART ORDERED
	ER32	1FVACYFE2LHLC2951	YBY3874	3-14-2025	469.56	469.56	BACK OFF PACKER PRESSURE WAS OVER HEATING
	ER32	1FVACYFE2LHLC2951	YBY3874	3-19-2025	469.56	469.56	REINSTALL HARNESS
	ER32	1FVACYFE2LHLC2951	YBY3874	2-5-2025	469.56	469.56	Replaced Arm Harness
	ER32	1FVACYFE2LHLC2951	YBY3874	12-24-2024	460.11	460.11	arm harness pulled apart and replaced
	ER32	1FVACYFE2LHLC2951	YBY3874	12-24-2024	460.11	460.11	harness RIPPED APART
	ER32	1FVACYFE2LHLC2951	YBY3874	3-7-2024	453.02	453.02	arm inop went and found broken wires stowed it came to the shop replaced arm harness
	ER32	1FVACYFE2LHLC2951	YBY3874	4-23-2024	453.02	453.02	replaced fingers 4/23 replaced tilt sensor cable, test drive, checked codes, replaced arm wire harness.
	ER32	1FVACYFE2LHLC2951	YBY3874	4-26-2024	453.02	453.02	Replaced hydraulic hoses on arm 4/12 GS - replaced hydraulic hoses on upper arm. 12 fittings, 6 hoses, & 1 o-ring. 4/17 GS - Replaced 1 broken snapped finger, bent other finger back in place. Replaced 2 backing bars. (1 missing, one snapped off) hopper cover not open
	ER32	1FVACYFE2LHLC2951	YBY3874	4-16-2025	432.23	432.23	tubes cpr water pump fuel transfer
	ER32	1FVACYFE2LHLC2951	YBY3874	11-5-2024	425.35	425.35	REWIRED
	ER32	1FVACYFE2LHLC2951	YBY3874	4-16-2024	329.20	329.20	seal trans crack inside casing filled
	ER32	1FVACYFE2LHLC2951	YBY3874	3-21-2022	322.87	322.87	replaced hose and bracket that holds both side of the claws together. I don't know the part#
	ER32	1FVACYFE2LHLC2951	YBY3874	1-20-2025	0.00	320.00	arm banging and jerky replaced reach harness upon running radiator decide to burst R&R radiator
	ER32	1FVACYFE2LHLC2951	YBY3874	4-7-2026	0.00	315.00	WIRE HARNESS DIAG.
	ER32	1FVACYFE2LHLC2951	YBY3874	3-27-2025	0.00	300.00	REMOVE FUEL LINES AND GRID HATER ANFD THE OLD GASKET
	ER32	1FVACYFE2LHLC2951	YBY3874	4-26-2024	298.96	298.96	Replaced hydraulic hoses on arm 4/12 GS - replaced hydraulic hoses on upper arm. 12 fittings, 6 hoses, & 1 o-ring. 4/17 GS - Replaced 1 broken snapped finger, bent other finger back in place. Replaced 2 backing bars. (1 missing, one snapped off) hopper cover not open
	ER32	1FVACYFE2LHLC2951	YBY3874	3-4-2026	0.00	288.00	installed reach cylinder
	ER32	1FVACYFE2LHLC2951	YBY3874	12-30-2021	286.11	286.11	driver bent double fingers. I replaced assembly
	ER32	1FVACYFE2LHLC2951	YBY3874	4-16-2025	0.00	280.80	tubes cpr water pump fuel transfer
	ER32	1FVACYFE2LHLC2951	YBY3874	5-1-2025	0.00	270.00	LOOK FOR LEAKS IN THE FUEL LINES
	ER32	1FVACYFE2LHLC2951	YBY3874	2-22-2024	258.00	258.00	filled tranny filled hyro adjusted brakes Replaced trans cooler lines
	ER32	1FVACYFE2LHLC2951	YBY3874	4-13-2026	0.00	252.00	wiring
	ER32	1FVACYFE2LHLC2951	YBY3874	2-16-2024	0.00	240.00	Patched floor of ER32
	ER32	1FVACYFE2LHLC2951	YBY3874	2-16-2024	0.00	240.00	Patched floor of ER32
	ER32	1FVACYFE2LHLC2951	YBY3874	4-26-2024	0.00	240.00	replaced both engine speed sensors
	ER32	1FVACYFE2LHLC2951	YBY3874	6-25-2024	238.14	238.14	TROLLEY TIP WAS OFF, RECALIBRATED SETTINGS. JE REPLACED ROLLERS, AND TIGHTEN UP CHAIN

	ER32	1FVACYFE2LHLC2951	YBY3874	1-13-2022	237.00	237.00	unit came in with a hydro leak coming from the packer replaced hose and ran arm I didn't see any leaks . sent unit out to route
	ER32	1FVACYFE2LHLC2951	YBY3874	4-26-2024	0.00	232.00	4/11 GS - Began PM service 4/15 finished PM.
	ER32	1FVACYFE2LHLC2951	YBY3874	3-28-2025	0.00	232.00	NEW FUEL LINES AND GRID HEATERS PARTS ON NEXT WORK ORDER
	ER32	1FVACYFE2LHLC2951	YBY3874	2-10-2025	223.65	223.65	HOSE CYLINDER
	ER32	1FVACYFE2LHLC2951	YBY3874	4-29-2025	221.82	221.82	INSTALL PRESSURE REILF VALVE
	ER32	1FVACYFE2LHLC2951	YBY3874	3-21-2026	0.00	220.50	REWIRE ARM HARNESS
	ER32	1FVACYFE2LHLC2951	YBY3874	3-22-2024	205.32	205.32	parts bill out and drop off at boyer
	ER32	1FVACYFE2LHLC2951	YBY3874	3-6-2025	203.72	203.72	R&R REAR BUMPER
	ER32	1FVACYFE2LHLC2951	YBY3874	4-16-2024	0.00	200.00	4/15 Lower hydraulic hoses on grabber arm replaced 4/16 Add hydro fluid, Adjust grabber harness, swap hoses to grabber and tilt
	ER32	1FVACYFE2LHLC2951	YBY3874	3-14-2024	0.00	200.00	Fluid cleanup 211 Exeter Pl TRUCK SNAPPED CHAIN ON ROUTE
	ER32	1FVACYFE2LHLC2951	YBY3874	4-26-2024	0.00	200.00	Replaced hydraulic hoses on arm 4/12 GS - replaced hydraulic hoses on upper arm. 12 fittings, 6 hoses, & 1 o-ring. 4/17 GS - Replaced 1 broken snapped finger, bent other finger back in place. Replaced 2 backing bars. (1 missing, one snapped off) hopper cover not open
	ER32	1FVACYFE2LHLC2951	YBY3874	4-23-2024	198.53	198.53	replaced fingers 4/23 replaced tilt sensor cable, test drive, checked codes, replaced arm wire harness.
	ER32	1FVACYFE2LHLC2951	YBY3874	4-16-2024	193.50	193.50	4/15 Lower hydraulic hoses on grabber arm replaced 4/16 Add hydro fluid, Adjust grabber harness, swap hoses to grabber and tilt
	ER32	1FVACYFE2LHLC2951	YBY3874	12-3-2024	193.47	193.47	REPLACED WHEEL AND WELD STOP ON REACH ARM
	ER32	1FVACYFE2LHLC2951	YBY3874	4-23-2024	0.00	192.00	replaced fingers 4/23 replaced tilt sensor cable, test drive, checked codes, replaced arm wire harness.
	ER32	1FVACYFE2LHLC2951	YBY3874	5-2-2025	0.00	189.00	DOT
	ER32	1FVACYFE2LHLC2951	YBY3874	3-22-2024	0.00	180.00	not shifting normally went out test drove need out put senser came in and replaced it
	ER32	1FVACYFE2LHLC2951	YBY3874	8-22-2024	0.00	180.00	R&R PTO
	ER32	1FVACYFE2LHLC2951	YBY3874	3-19-2026	0.00	176.40	WORKED ON WIRE HARNESS W/JOSH
	ER32	1FVACYFE2LHLC2951	YBY3874	4-15-2025	0.00	172.80	FUEL LINES REMOVE AND INTAKE
	ER32	1FVACYFE2LHLC2951	YBY3874	8-22-2024	0.00	172.00	PULLED DRIVE SHAFT FOR PTO AND PULLED OUT MOST MOUNTING BELT MOVE TRANS COVER TO GET PTO OUT HELP MOVE AND INSTALL
	ER32	1FVACYFE2LHLC2951	YBY3874	8-13-2024	0.00	172.00	REPLACE PTO HARNESS STILL NEEDS A SOLENOID
	ER32	1FVACYFE2LHLC2951	YBY3874	4-23-2025	0.00	168.00	replaced fuel filters
	ER32	1FVACYFE2LHLC2951	YBY3874	1-3-2022	166.60	166.60	unit came in with loose hydro line I re tightened the fitting filled hydro tank didn't see any leaks repaired(2) hub cap was smashed and water was detected .replaced the wheel seal on driver side repairer (3) tail gate proxy was not reading I moved it closer to the tail gate. proxy read great .
	ER32	1FVACYFE2LHLC2951	YBY3874	4-2-2024	164.60	164.60	4/1 GS - Service call to ER32 with grabber pin missing. Replaced. Regreased both sides of grabber cylinder points.
	ER32	1FVACYFE2LHLC2951	YBY3874	4-16-2024	164.60	164.60	4/15 Lower hydraulic hoses on grabber arm replaced 4/16 Add hydro fluid, Adjust grabber harness, swap hoses to grabber and tilt
	ER32	1FVACYFE2LHLC2951	YBY3874	3-7-2024	164.60	164.60	arm inop went and found broken wires stowed it came to the shop replaced arm harness
	ER32	1FVACYFE2LHLC2951	YBY3874	4-16-2024	164.60	164.60	Checked rear diff and added 3 qts fluid
	ER32	1FVACYFE2LHLC2951	YBY3874	4-2-2024	164.60	164.60	check engine lights fixed my need def heater replaced not at this time regen
	ER32	1FVACYFE2LHLC2951	YBY3874	3-27-2024	164.60	164.60	clean ice out and readjusted sensor and fixed wires to it
	ER32	1FVACYFE2LHLC2951	YBY3874	2-22-2024	164.60	164.60	filled tranny filled hyro adjusted brakes Replaced trans cooler lines
	ER32	1FVACYFE2LHLC2951	YBY3874	3-22-2024	164.60	164.60	not shifting normally went out test drove need out put senser came in and replaced it
	ER32	1FVACYFE2LHLC2951	YBY3874	1-25-2024	164.60	164.60	pack assist pin came out replaced it and put on new tail gate hoses need to be added pirtek
	ER32	1FVACYFE2LHLC2951	YBY3874	3-22-2024	164.60	164.60	parts bill out and drop off at boyer
	ER32	1FVACYFE2LHLC2951	YBY3874	2-16-2024	164.60	164.60	Patched floor of ER32
	ER32	1FVACYFE2LHLC2951	YBY3874	4-16-2024	164.60	164.60	put on filter and primed but battery is dead finish putting front cover on
	ER32	1FVACYFE2LHLC2951	YBY3874	3-12-2024	164.60	164.60	Removed pto shaft adjusted both ends, replaced with new hardware.; Tightened pto gearbox to trans.
	ER32	1FVACYFE2LHLC2951	YBY3874	4-26-2024	164.60	164.60	replaced both engine speed sensors
	ER32	1FVACYFE2LHLC2951	YBY3874	2-22-2024	164.60	164.60	service call found unplugged wire
	ER32	1FVACYFE2LHLC2951	YBY3874	6-25-2024	164.60	164.60	TROLLEY TIP WAS OFF, RECALIBRATED SETTINGS. JE REPLACED ROLLERS, AND TIGHTEN UP CHAIN
	ER32	1FVACYFE2LHLC2951	YBY3874	2-13-2024	164.60	164.60	Welded ladder handle back to body. Was broken off at top
	ER32	1FVACYFE2LHLC2951	YBY3874	3-19-2025	0.00	160.00	REINSTALL HARNESS

	ER32	1FVACYFE2LHLC2951	YBY3874	4-26-2024	0.00	160.00	Replaced hydraulic hoses on arm 4/12 GS - replaced hydraulic hoses on upper arm. 12 fittings, 6 hoses, & 1 o-ring. 4/17 GS - Replaced 1 broken snapped finger, bent other finger back in place. Replaced 2 backing bars. (1 missing, one snapped off) hopper cover not open
	ER32	1FVACYFE2LHLC2951	YBY3874	3-12-2024	0.00	160.00	resealed valve body cleaned drained side tank part parker seal kit 393000k871
	ER32	1FVACYFE2LHLC2951	YBY3874	4-16-2024	0.00	160.00	seal trans crack inside casing filled
	ER32	1FVACYFE2LHLC2951	YBY3874	4-16-2025	156.50	156.50	tubes cpr water pump fuel transfer
	ER32	1FVACYFE2LHLC2951	YBY3874	3-12-2024	154.80	154.80	resealed valve body cleaned drained side tank part parker seal kit 393000k871
	ER32	1FVACYFE2LHLC2951	YBY3874	5-5-2025	154.41	154.41	BEARING OLLIE FLANGE BEARING GRIP LINK
	ER32	1FVACYFE2LHLC2951	YBY3874	12-16-2021	149.50	149.50	unit came in low on hydro filled hydro tank . unit ran great sent out to route
	ER32	1FVACYFE2LHLC2951	YBY3874	4-23-2025	0.00	144.00	hose replacement
	ER32	1FVACYFE2LHLC2951	YBY3874	11-1-2024	0.00	140.00	PTO INOP LOOK INTO PTO SHORT ALWAYS HAS POWER
	ER32	1FVACYFE2LHLC2951	YBY3874	12-7-2021	131.52	131.52	unite cam in with hydro lines no longer held or attached to head of trolley I I took off all hydro hose on bracket . I cleaned and welded on a new piece . I reattached hydro hose's ran arm worked great sent to route
	ER32	1FVACYFE2LHLC2951	YBY3874	4-16-2025	130.71	130.71	tubes cpr water pump fuel transfer
	ER32	1FVACYFE2LHLC2951	YBY3874	4-30-2025	0.00	126.00	no start found loose injector hold down
	ER32	1FVACYFE2LHLC2951	YBY3874	4-2-2025	0.00	126.00	test fuel system
	ER32	1FVACYFE2LHLC2951	YBY3874	5-20-2025	0.00	126.00	WIRE HARNESS FOR PAC TECH
	ER32	1FVACYFE2LHLC2951	YBY3874	1-20-2025	124.84	124.84	arm banging and jerky replaced reach harness upon running radiator decied to burst R&R raditaor
	ER32	1FVACYFE2LHLC2951	YBY3874	3-7-2024	0.00	120.00	arm inop went and found broken wires stowed it came to the shop replaced arm harness
	ER32	1FVACYFE2LHLC2951	YBY3874	4-2-2024	0.00	120.00	ckcek engine lights fixed my need def heater replaced not at this time regen
	ER32	1FVACYFE2LHLC2951	YBY3874	3-25-2025	0.00	120.00	DOT FOUND BRAKES AND ABS IGHIT AND LEAK
	ER32	1FVACYFE2LHLC2951	YBY3874	3-14-2024	0.00	120.00	Filuid cleanup 211 Exeter Pl TRUCK SNAPPED CHAIN ON ROUTE
	ER32	1FVACYFE2LHLC2951	YBY3874	3-25-2025	0.00	120.00	STARTED PM CHANGED AND GREASED AND DID PAPERWORK
	ER32	1FVACYFE2LHLC2951	YBY3874	4-28-2025	0.00	115.20	CONTINUE WORK ON ENGINE
	ER32	1FVACYFE2LHLC2951	YBY3874	3-19-2025	113.28	113.28	REINSTALL HARNESS
	ER32	1FVACYFE2LHLC2951	YBY3874	4-23-2024	0.00	112.00	replaced fingers 4/23 replaced tilt sensor cable, test drive, checked codes, replaced arm wire harness.
	ER32	1FVACYFE2LHLC2951	YBY3874	3-19-2026	0.00	112.00	WORKED ON WIRE HARNESS W/JOSH
	ER32	1FVACYFE2LHLC2951	YBY3874	1-20-2025	111.76	111.76	arm banging and jerky replaced reach harness upon running radiator decied to burst R&R raditaor
	ER32	1FVACYFE2LHLC2951	YBY3874	1-22-2025	111.76	111.76	ARM LOSING CALAIBRATION RANGE LOW ERROR REPLACED HARNESS ARM REACH ON RETRACT GOES TO ZERO 2 FEET AWAY BODY THEN LOSS UPTIGHT NEED REACH CYLINDER PART ORDERED
	ER32	1FVACYFE2LHLC2951	YBY3874	5-2-2025	0.00	108.00	FIXED A FUEL LEAK
	ER32	1FVACYFE2LHLC2951	YBY3874	3-7-2024	103.20	103.20	arm inop went and found broken wires stowed it came to the shop replaced arm harness
	ER32	1FVACYFE2LHLC2951	YBY3874	4-22-2025	0.00	100.80	TUBE FUEL LINE SUPPLY
	ER32	1FVACYFE2LHLC2951	YBY3874	7-1-2024	0.00	100.00	DOOR INOP, R&R DOOR LATCH, PULLED FROM ER33 TO GET TRUCK ON THE ROAD.
	ER32	1FVACYFE2LHLC2951	YBY3874	3-31-2025	0.00	100.00	NEEDS PARTS NOT BUILDING PRESURE
	ER32	1FVACYFE2LHLC2951	YBY3874	1-25-2024	0.00	100.00	pack assist pin came out replaced it and put on new tail gate hoses need to be added pirtek
	ER32	1FVACYFE2LHLC2951	YBY3874	3-26-2025	0.00	100.00	PULL FUEL LINES
	ER32	1FVACYFE2LHLC2951	YBY3874	4-26-2024	0.00	100.00	Replaced hydraulic hoses on arm 4/12 GS - replaced hydraulic hoses on upper arm. 12 fittings, 6 hoses, & 1 o-ring. 4/17 GS - Replaced 1 broken snapped finger, bent other finger back in place. Replaced 2 backing bars. (1 missing, one snapped off) hopper cover not open
	ER32	1FVACYFE2LHLC2951	YBY3874	1-23-2025	0.00	100.00	REPLACED REACH CYLINDER AND WIRE HARNESS
	ER32	1FVACYFE2LHLC2951	YBY3874	11-5-2024	0.00	100.00	REWIRED
Lot#124	ER33	1FVACYFE6LHLC2953	YBY3877	3-21-2024	2,098.84	2,098.84	replaced hood mirror replaced rear drums and shoes fixed air leak fixed lights
	ER33	1FVACYFE6LHLC2953	YBY3877	5-29-2025	1,872.64	1,872.64	R&R GRABBER CYLINDER
	ER33	1FVACYFE6LHLC2953	YBY3877	4-5-2024	1,562.70	1,562.70	4/3 GS - grabber cylinder hydro hose had a bad/bent fitting. Replaced with new one. stopped leak. Didn't get engine hours. 4/4 GS - Replaced trolley sensor. Calibrated. Replaced three mounting screws. 4/5 GS - belt plate on double finger snapped. Replaced 1 part.
	ER33	1FVACYFE6LHLC2953	YBY3877	7-3-2024	1,562.70	1,562.70	Replaced missing pin cover and collar. Scraped broken collar pieces. Bearing was fine. Tightened loose hydro hose on grabber cylinder. 4/1 Trolley sensor + harness replace, replace 2x hoses for tilt cylinder on trolley, weld bracket on lower hose bracket, replace 2x missing bolts on finger pin plate (counted as 1x shop supply), 20 qts hydro fluid 7/3 tightened and replaced roller on trolley, tightened chain.
	ER33	1FVACYFE6LHLC2953	YBY3877	4-20-2022	1,389.64	1,389.64	replaced all drive tires on truck.