



Howden Country Services Ltd
PO BOX 250
FORT QUAPPELLE SK S0G 1S0
3063315116
tammy@howdencountry.com
shawn@howdencountry.com
www.howdencountry.com
GST/HST Registration No.: 859624355RT0001

Invoice

BILL TO

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
9430	20-10-2023	\$0.00	19-11-2023	Net 30	

EQUIPMENT TYPE	HOURS	SERIAL #
s680	2847E/1948S	1h0s680sveo767329

DESCRIPTION	QTY	RATE	TAX	AMOUNT
1. COMBINE CHECKOVER	1	980.00	G	980.00
2. Check cause of vibration into tailboard	0	110.00	G	0.00
3. Check engine cranks slow- Clean battery connections to shut off and ground points. Retest batteries 1 failed replace battery- warranty	2	110.00	G	220.00
4. Change engine oil (customer oil) and oil filter, change air filter, fuel filters, clean fuel sediment screen , cab filter	2.50	110.00	G	275.00
WIX 10098 Cabin Air Filter	1	85.95	G	85.95
WIX-57777 Oil Filter	1	89.45	G	89.45
33969 Filter	1	158.90	G	158.90
WIX-33979 Filter	1	173.27	G	173.27
WA10117 Air Filter	1	313.88	G	313.88
5. Repl feederhouse top chain guide	1	110.00	G	110.00
Stewart Steel (H234587) Chain Support	1	273.00	G	273.00
6. Tighten feederhouse slip clutch nut	0.30	110.00	G	33.00
7. Replace reverser gearbox oil - use recommended	0.75	110.00	G	82.50

DESCRIPTION	QTY	RATE	TAX	AMOUNT
TY26408 HD460 Synthetic	4	49.08	G	196.32
Enviro Fee	4	0.15	G	0.60
8. Replace feederhouse centre floor plastic	1.40	110.00	G	154.00
Strip Upper Return Wear	1	18.54	G	18.54
9. Repl primary gearcase oil	0.80	110.00	G	88.00
75/90 traxton synthetic	2.40	9.16	G	21.98
10. Repl straw chopper bearings and check runout	4.27	110.00	G	469.70
AXE12177 Bearing	2	157.99	G	315.98
11. Repl chopper tailboard Lh support and missing bolt	0.75	110.00	G	82.50
HXE25684 Rocker Arm	1	229.69	G	229.69
HXE20030 Bushing	1	21.68	G	21.68
M12x50 Carr	1	4.20	G	4.20
H143731 Nut	1	2.20	G	2.20
03M7202 M12x50	1	4.20	G	4.20
H143731 Nut	1	2.20	G	2.20
12. Repl tailboard centre waggle arm	2.60	110.00	G	286.00
JD10181 Ball Bearing	2	21.77	G	43.54
13. Repl rotary screen side door front seal	1.50	110.00	G	165.00
HXE69203 Seal	1	118.58	G	118.58
14. Check and tighten coolant hoses dripping at rear of head	0.75	110.00	G	82.50
15. Repl alternator belt	1.40	110.00	G	154.00
H238831 V-belt	1	68.48	G	68.48
HXE129502 Guage	1	67.18	G	67.18
16. Repl rotor gearbox oil & replaced gearbox oil drain	4.50	110.00	G	495.00
75/90 traxton synthetic	3	9.16	G	27.48
DE19125 Drain Valve	1	155.75	G	155.75
17. Install j-hook in tailings 1/2 link	0.70	110.00	G	77.00

DESCRIPTION	QTY	RATE	TAX	AMOUNT
18. Repl 2 tensioner rod plastic guides on Rh tensioners	0.50	110.00	G	55.00
A-H129207 Pivot , Idler Spring 12mm	2	4.61	G	9.22
19. Repl cleaning fan lower inside sheave , top cleaning fan sheaves / and pins	3.75	110.00	G	412.50
H161051 Inner Sheave - Cleaning Fan Drive	1	724.50	G	724.50
R1964R Dowel Pin	3	28.17	G	84.51
AH233509 Cleaning Fan - Inner Sheave	1	413.47	G	413.47
AH14080 Seal	2	14.15	G	28.30
20 Install bolts in cleaning fan end rh divider	0.75	110.00	G	82.50
Hardware	1	5.00	G	5.00
21. Repl feed accelerator idlers	1.25	110.00	G	137.50
AH150900 Idler	2	131.97	G	263.94
Shop supplies	0.02	3,460.70	G	69.21
Shipping	1	35.00	G	35.00
Split Invoice 50%	-0.50	8,950.38	G	-4,475.19
SUBTOTAL				3,992.71
GST/HST @ 5%				199.68
TOTAL				4,192.39
PAYMENT				4,192.39
BALANCE DUE				\$0.00

TAX SUMMARY

RATE	TAX	NET
GST/HST @ 5%	199.68	3,992.71



