

Repair Order

Due: \$269.73

Date Printed: 01/08/2026

Date Promised: 01/08/2026

Date In: 01/08/2026

Summary

Approve	Decline	Unit	Job	Job Total
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	ONE WAY ISSUE	\$243.00
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	VEHICLE HEALTH CHECK	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	ONE WAY ASSEMBLY	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	PRIMARY MAINTENANCE	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	SECONDARY MAINTENANCE	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	CLUTCH COVERS	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	GEARBOX INPUT SEAL	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	GEARBOX OUTPUT SHAFT	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	GEARBOX / ENGINE SEAL	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	ENGINE FRONT OUTPUT SEAL	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	REAR CYLINDER CHAIN TENSIONER	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	VALVE COVER GASKETS	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	MAGNETO COVER GASKET	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	REAR DIFFERENTIAL AXLE SEAL (RIGHT)	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	AXLE BOOTS	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	FRONT DIFFERENTIAL PINION SEAL / BOOT	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	FRONT LEFT UPPER BALL JOINT	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	REAR WHEEL BEARINGS	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	REAR SWING ARM BEARINGS	\$0.00
<input type="checkbox"/>	<input type="checkbox"/>	2013 CAN-AM OUTLANDER 1000	REAR SWING ARM CUSHIONS	\$0.00
Job Subtotal:				<u>\$243.00</u>
Misc:				<u>\$0.00</u>
Job Labor Subtotal:				<u>\$225.00</u>
Job Misc Item Subtotal:				<u>\$18.00</u>
GST Tax - 5.00%:				<u>\$12.15</u>
PST Tax - 6.00%:				<u>\$14.58</u>
Total:				<u>\$269.73</u>
Less Deposits:				<u>\$0.00</u>
Total Due:				<u><u>\$269.73</u></u>

DISCLAIMER: PowerSports Regina Ltd is not responsible for any damage or loss that may occur to your vehicle or its contents during or after the repair service. By agreeing to use our services, you acknowledge that you have read and understand this disclaimer and agree to release PowerSports Regina Ltd from any liability for damages or losses.

LIMITATION OF LIABILITY: In no event shall PowerSports Regina Ltd be liable for any direct, indirect, incidental, consequential, special, or punitive damages arising out of or in connection with the repair service, whether in contract, tort, strict liability, or any other legal theory.

WARRANTY DISCLAIMER: PowerSports Regina Ltd makes no warranties, express or implied, concerning the repair service, including but not limited to any warranties of merchantability or fitness for a particular purpose.

OTHER TERMS AND CONDITIONS: By agreeing to use our services, you also agree to comply with any additional terms and conditions that may be provided to you by PowerSports Regina Ltd in connection with the repair service.

Signature: _____

Detail

Unit	2013 CAN-AM OUTLANDER 1000 XMR Outlander™ 1000 X mr	Color:	Keyboard:
	VIN/Serial No: 3JBLWLP1XDJ002499	Plate:	Odom/Hrs In: 6,487 Out: 6,487

ONE WAY ISSUE

Description:
CUSTOMER WANTS THE ONE WAY GREASES OR REPLACE IF NEEDED
CHECK AND ADVISE

Resolution:
REMOVED LEFT SIDE PANEL AND CLUTCH COVER

OBSERVED CLUTCH COVER IS MISSING THREE BOLTS, AND HAS HAD A HOLE PATCHED IN THE LOWER FRONT. INNER COVER IS MISSING THREE NUTSETS. CLUTCH COVER IS COVERED WITH GREASE AND OIL

WITHIN THE CLUTCH COVER. OBSERVED A SIGNIFICANT AMOUNT OF SUSPENSION GREASE COVERING THE INSIDE OF THE CLUTCH COVERS. ATTEMPTED TO REMOVE ONE WAY BEARING CARRIER, ONE WAY BEARINGS IN CARRIER HAVE COMPLETELY FAILED.

REMOVED INNER SHEAVE, FOUND GREASE PACKED IN BETWEEN CRANKSHAFT STUB AND CLUTCH SHEAVE

SECONDARY CLUTCH HAS HAD A BELT REMOVAL TOOL BROKEN WITHIN THE FIXED SHEAVE, CANNOT REMOVE BELT PROPERLY OR INSTALL. REMOVED SECONDARY CLUTCH, OBSERVED MAJOR OIL LEAK FROM GEARBOX INPUT SHAFT, GEARBOX OIL IS ENTERING THE CLUTCH COVER

SECONDARY SLIDING SHEAVE IS GROOVED FROM HELIX

PRIMARY CLUTCH SLIDE SHOES ARE WORN OUT, RAMPS HAVE EXCESSIVE AXIAL PLAY. AND ROLLERS ARE FLAT

NEED TO REPLACE ONE WAY BEARINGS, BEARING CARRIER, CLUTCH COVERS, DRIVE BELT. SECONDARY FIXED SHEAVE, PRIMARY INTERNALS, AND GEARBOX INPUT SHAFT

Labor

Description	Technician	Hours	Total
DIAGNOSIS		1.5	\$225.00
			Labor Subtotal \$225.00
			Shop Supplies \$18.00
			Job Subtotal \$243.00
			Approve: <input checked="" type="checkbox"/> Decline: <input type="checkbox"/>

VEHICLE HEALTH CHECK

Description:
COMPLIMENTARY VISUAL SAFETY AND HEALTH INSPECTION
HEALTH FORM COMPLETED FOR CUSTOMER INFORMATION
CHECK VIN FOR ANY RECALLS

Resolution:
COMPLETED VEHICLE HEALTH CHECK

SEE EXTRA JOBS ON REPAIR ORDER

Labor

Description	Technician	Hours	Total
CHECK OVER		0	\$0.00
			Labor Subtotal \$0.00
			Job Subtotal \$0.00
			Approve: <input checked="" type="checkbox"/> Decline: <input type="checkbox"/>

ONE WAY ASSEMBLY

Description:

Description: ONE WAY BEARINGS ARE HEAVILY DAMAGED, NEED TO REPLACE CARRIER

Job Subtotal \$0.00
Approve: Decline:

PRIMARY MAINTENANCE

Description:
PRIMARY CLUTCH NEEDS REBUILT

PRIMARY CLUTCH SLIDE SHOES ARE WORN OUT, RAMPS HAVE EXCESSIVE AXIAL PLAY. AND ROLLERS ARE FLAT

Job Subtotal \$0.00
Approve: Decline:

SECONDARY MAINTENANCE

Description:
SECONDARY CLUTCH HAS HAD A BELT REMOVAL TOOL BROKEN WITHIN THE FIXED SHEAVE,
SLIDING SHEAVE IS GROOVED FROM WEAR ON HELIX
HELIX IS DAMAGED

Job Subtotal \$0.00
Approve: Decline:

CLUTCH COVERS

Description:
OBSERVED CLUTCH COVER IS MISSING THREE BOLTS, AND HAS HAD A HOLE PATCHED IN THE LOWER FRONT. INNER COVER IS MISSING THREE NUTSETS. CLUTCH COVER IS COVERED WITH GREASE AND OIL

Job Subtotal \$0.00
Approve: Decline:

GEARBOX INPUT SEAL

Description:
GEARBOX INPUT SEAL IS LEAKING OIL (BEHIND SECONDARY)

Job Subtotal \$0.00
Approve: Decline:

GEARBOX OUTPUT SHAFT

Description:
GEARBOX OUTPUT SHAFT SEAL TO REAR DIFFERENTIAL IS LEAKING OIL

Job Subtotal \$0.00
Approve: Decline:

GEARBOX / ENGINE SEAL

Description:
O RING BETWEEN GEARBOX AND ENGINE IS LEAKING OIL

Job Subtotal \$0.00

Approve: Decline:

ENGINE FRONT OUTPUT SEAL

Description:

FRONT OUTPUT SHAFT SEAL TO DIFFERENTIAL IS LEAKING OIL

Job Subtotal \$0.00

Approve: Decline:

REAR CYLINDER CHAIN TENSIONER

Description:

REAR CYLINDER CHAIN TENSIONER O RINGS ARE LEAKING OIL

Job Subtotal \$0.00

Approve: Decline:

VALVE COVER GASKETS

Description:

VALVE COVER GASKETS ARE LEAKING OIL

Job Subtotal \$0.00

Approve: Decline:

MAGNETO COVER GASKET

Description:

MAGNETO COVER GASKET IS LEAKING OIL

Job Subtotal \$0.00

Approve: Decline:

REAR DIFFERENTIAL AXLE SEAL (RIGHT)

Description:

REAR DIFFERENTIAL RIGHT AXLE SEAL IS LEAKING

Job Subtotal \$0.00

Approve: Decline:

AXLE BOOTS

Description:

REAR RIGHT INNER AND OUTER AXLE BOOTS ARE TORN
REAR LEFT INNER AXLE BOOT IS TORN

Job Subtotal \$0.00

Approve: Decline:

FRONT DIFFERENTIAL PINION SEAL / BOOT

Description:

Description: FRONT DIFFERENTIAL PINION SEAL IS LEAKING OIL, DRIVE SHAFT BOOT IS TORN

Job Subtotal \$0.00
Approve: Decline:

FRONT LEFT UPPER BALL JOINT

Description:
FRONT LEFT UPPER BALL JOINT IS LOOSE

Job Subtotal \$0.00
Approve: Decline:

REAR WHEEL BEARINGS

Description:
REAR WHEEL BEARINGS ARE EXCESSIVELY LOOSE

Job Subtotal \$0.00
Approve: Decline:

REAR SWING ARM BEARINGS

Description:
REAR SWING ARM BEARINGS ARE EXCESSIVELY LOOSE

Job Subtotal \$0.00
Approve: Decline:

REAR SWING ARM CUSHIONS

Description:
REAR SWING ARM CUSHIONS ARE EXCESSIVELY LOOSE

Job Subtotal \$0.00
Approve: Decline:

All Jobs Subtotal:	<u>\$243.00</u>
GST Tax - 5.00%:	<u>\$12.15</u>
PST Tax - 6.00%:	<u>\$14.58</u>
Total:	<u>\$269.73</u>
Less Deposits:	<u>\$0.00</u>
Total Due:	<u><u>\$269.73</u></u>