



R.C.S Repair Ltd
 815 Railway Ave
 P.O Box 34
 Lipton, Saskatchewan S0G 3B0
 Canada

Lot 301

STATEMENT

Statement Date
05/31/2021

PLEASE RETURN THIS PORTION WITH
 YOUR PAYMENT

Statement Date
05/31/2021

IF PAYING BY INVOICE, CHECK
 INDIVIDUAL INVOICES PAID

AMOUNT REMITTED _____

Page: 1

Transaction Date	Transaction No.	Transaction Type	Amount	Balance	Invoice No.	Amount Due	✓
05/06/2021	5445	Invoice		3,480.12	5445	3,480.12	
05/10/2021	15480	Invoice		384.58	15480	384.58	
				Total			
Age	Current	31-60	Over 60		Balance Due	Total	
Amount	3,864.70	0.00	0.00	3,864.70	< >	3,864.70	



R.C.S. REPAIR LTD.
 GST #R116RR2507
 P.O. BOX 34
 LIPTON, SK S0G 3B0

5445

INVOICE

NO 5445

DATE 05/06/2021

PAGE 1 of 2

(306) 336-2558

SOLD TO

SHIP TO

ITEM NO.	QUANTITY	UNIT	DESCRIPTION	HST GST PST	UNT PRICE	AMOUNT
> R3054204	1.00	1	injector	G	185.00	185.00
M3028673	2.00	2	valve cover gasket	G	62.10	124.20
labour (C)	0.50	hour	Diagnose fuel injectors, cylinder temps on exh manifold, extreme smoke, multiple cylinders have no temp on manifold. Look over tractor to identify oil leaks on steering cylinders/hoses. Exh leaks on manifold flanges, flex pipe & upright stack	G	100.00	50.00
labour (RT)	0.50	hour	same as above	G	100.00	50.00
labour (C)	7.00	hour	R&R injectors, set valve clearance	G	100.00	700.00
labour (RT)	1.25	hour	assist with above	G	100.00	125.00
PS1600-56	2.00	2	piston seal kit	G	39.10	78.20
ST-150	2.00	2	wiper seal	G	10.40	20.80
18-1.50-25	2.00	2	shaft seal	G	27.35	54.70
568-214 90D	2.00	2	o ring	G	3.00	6.00
568-236-90D	2.00	2	o ring	G	3.00	6.00
575-236	2.00	2	back up ring	G	5.20	10.40
612-350-025	4.00	4	wiper seal	G	10.40	41.60
labour (CT)	6.50	hour	R&R steering cylinders, replace all seals internal & external wipers	G	100.00	650.00
labour (RT)	0.50	hour	assist with above	G	100.00	50.00
P206615	1.00	each	5" flared connector 90°	G	49.50	49.50
P207332	1.00	each	5" elbow 90°	G	77.70	77.70
U3105	4.00	each	5" lap clamp	G	12.00	48.00
9607	1.00	each	5" u bolt	G	9.85	9.85
5"	18.00	inch	flexpipe	G	2.86	51.48
561-29382	1.00	1	v Band clamp	G	20.60	20.60
U13751A	1.00	1	flared exhaust	G	18.20	18.20
labour (CT)	3.00	hour	Disassemble exhaust, replace manifold flanges, flexpipe. R&R stack & replace elbows	G	100.00	300.00
0201-12 x 8	2.00	2	3/4 to 1/2 reducer	G	12.35	24.70
4150-5	2.00	2	3/4 female hydraulic coupler	G	69.00	138.00
R74210	8.00	8	pioneer coupler oring	G	3.95	31.60
labour (RT)	1.00	hour	Flow test hydraulic standard stock system 23 gpm@ 1800psi, after market Atom Jet 10 gpm@ 1200psi, set point good condition	G	100.00	100.00

COMMENTS

1978 Steiger Panther PT350

TOTAL ▶

Continued...

5445

05/06/2021

2 of 2

labour (RT)	1.00	hour	Replace coupler hydraulic o rings	G	100.00	100.00
labour (RT)	0.40	hour	Replace Atom Jet block couplers to 3/4 inch Pioneer	G	100.00	40.00
labour (CT)	0.75	hour	Bleed transmission clutch slave cylinder	G	100.00	75.00
labour (RT)	0.25	hour	assist with above	G	100.00	25.00
shop	1.00	Each	supplies 5% labour	G2	50.00	50.00
						3,311.53
			Subtotal:			
			G - GST 5%			
			G2 - GST 5% PST 6%			165.59
			GST			3.00
			PST			

R.C.S Repair Ltd GST: #R116882507

1978 Steiger Panther PT350

3,480.12

RCS REPAIR LTD.

PO Box 34, Lipton, SK
 Tel: 306.336.2558 Fax: 306.336.2585
 GST# 116882507

15480

CUSTOMER _____
 ADDRESS _____
 DATE May 2001
 POSTAL CODE _____

NAME	MODEL	YEAR	ODOMETER	ENGINE	LICENCE	SERIAL #	UNIT PRICE	AMOUNT	
Sciger	350						1140	570	
Qty	Part #	DESCRIPTION							
		Service call to farm 13 miles							100.00
		Remove slave cylinder on clutch assembly, disassemble cylinder, clean parts and reassemble remaining clutch system 2.5 hrs							250.00
		SHOP LABOUR							250.00
		SHOP SUPPLIES							100.00
		PARTS							570
		SSTC FEE							100.00
		EHC FEE							
		SUB TOTAL							3457.00
		GST							185.88
		PST							100.00
		TOTAL							3742.88

I acknowledge my indebtedness in the amount of \$ _____ being in the total amount \$ _____

Customer Signature _____

2% PER MONTH INTEREST CHARGED ON OVERDUE ACCOUNTS