



# Landrys' Service Ltd.

NAPA AutoPro

180 Winnipeg St. North  
Regina, Saskatchewan S4R 2R9  
Phone (306) 543-6290  
E-Mail - Landry7@sasktel.net



## Authorization

Bill To \_\_\_\_\_ ay  
Regina, SK  
Canada

Plate SK 992MES  
Description 1978 FORD E150  
VIN  
Odometer 0 In / 11 Out

Phone  
Phone  
Email

Work Order # \_\_\_\_\_  
Service Advisor \_\_\_\_\_  
Technician C \_\_\_\_\_

Appointment 2021-06-29 4:02 PM  
Promised 2021-06-29 5:30 PM

## Service

### Fan / Drive Belts Adjust

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor		\$49.40 *GP
FAN BELT	1 Unit	\$25.38 GP
	<b>Sub</b>	<b>\$74.78</b>

### Headlight(s)

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Headlight	1 Unit	\$38.07 GP
	<b>Sub</b>	<b>\$38.07</b>

### Mount, Install & Balance 4 Tires

Install tire and new valve stem where applicable, clean and seal tire to wheel seat, set tire pressure to proper inflation. Computer spin balance tire and wheel. Mount and torque wheel lug nuts to manufacturers torque specifications. Perform final road test as required.

TRANSFORCE HT 115/111R 10-E B/W	4 Unit	\$800.00 GPT
	<b>Sub</b>	<b>\$800.00</b>

### Please Note

Some wheels require lug nut re-torque. Ask your Service Consultant for details.  
Keeping your tires properly inflated and rotated will assist in maximizing tire wear life and vehicle handling.

Total Parts		\$863.45
Total Labor		\$49.40
Total Before Taxes & Miscellaneous Charges		\$912.85
(*) Shop Supplies		\$2.47 GPE
(E) Environmental Fee	5.5 %	\$6.64 E
(G) Canadian Goods and Services Tax (GST)	5 %	\$45.77 E
(G2) GST on Scrap Tire	5 %	\$1.00 E
(P) Saskatchewan Provincial Sales Tax (PST)	6 %	\$54.92 E
(T) Tire Disposal Charge	\$5.00 Each	\$20.00 G2E
<b>Grand Total</b>		<b>\$1,043.65</b>

I HEREBY AUTHORIZE THE ABOVE REPAIRS AS STATED

Customer Signature: \_\_\_\_\_