



**Senchuk**  
FORD SALES LTD.

118 SOURIS AVE  
ESTEVAN, SK S4A 1J6  
Ph: (306) 634-3696, (855) 634-3696 Fax: (306) 634-4262

www.senchuk.com

SO# 354632

Status  
Printed 04/25/2025 3:55:19 PM

**SERVICE ORDER**  
**CUSTOMER COPY**



User 5673 Page 1

Customer No 112913  
[REDACTED]  
[REDACTED]  
[REDACTED]  
Home [REDACTED]  
Cell [REDACTED]  
Email [REDACTED]  
Type  
Term MC

Advisor Jenelle  
Shop S1  
Priority  
Promised 01/10/2023 5:30 PM  
Opened 01/10/2023 8:07 AM  
Cashiered 01/26/2023 3:49 PM  
Tag#  
Location  
PO #

License Odom In Odom Out In Service Date Stock No  
207298 207298 07/08/2013 24BS21AA  
Year Make Model Model Number Colour  
2014 FORD ESCAPE SILVER  
Vehicle ID No Selling Dealer Extended Warranty Delivery Date  
1FMCU9GX9EUA08019 SENCHUK FORD 04/25/2025  
Engine 1.6L L4 DIR DO Fleet #

Request	Description	Job	CSR	Status		
96	PERFORM A COMPRESSION TEST -	1	5305	Original		
Labour	Description	Type	Amount			
96	PERFORM A COMPRESSION TEST	CSP	320.00			
Part	Description	Shp	Bin	Type	Price	Amount
CCPZ 3B477 G	RETAINER - NUT	1	FR3	CSO	3.98	3.98
CV6Z 6038 B	BRACKET - ENGINE FRO	0		CSO	141.04	0.00
W708873 S437	STUD	0		CSO	18.10	0.00
W520204 S442	NUT - HEX.	0	RETURN	CSO	0.71	0.00
Technician	4396 -					3.98
Cause	PERFORM A COMPRESSION TEST -, tried to start car but did not start, brought car into shop, hooked up ids and performed relative compression test, all cylinders are very low, performed manual compression test all cylinders read 0psi, removed side cover and inspected timing belt while cranking engine, timing belt moves at this time, timing has slipped possibly hurting engine, engine will have to be removed and dissassembled to inpect for damage					320.00
						323.98

Request	Description	Job	CSR	Status
96	check timing	2	5305	Approved
Labour	Description	Type	Amount	
96	check timing	CSP	1,200.00	
Technician	6495 -			
Cause	check timing			
Correction	checked the timing. found the timmming is out. re timed the engine. the engine now runs. found the engine mount broken, right axel nut is not tight. engine overheats cause the coolant bypass valve doesnt open, wiring for the fornt bumper isnt plugged in. the wiring for the coolant stand tube is just laying under the air box. the wiring for the engine and bumper hanress is routed the wrong way causing the wires to stretch. missing the clip on the bottom rad hose. the heater core coolant line are ran the wrong way. tightened the axel nut. theres a lot of play in the right front hub bearing. plugged in the bumper wiring harness. needs the coolant bypass valve, right front hub bearing, bottom rad hose or clip. fix the wiring underneath the air box. and for the front bumper and engine. route the coolant line properly. new engine mount. needs a new battery as it wont hold a charge.			

TEXTING DISCLAIMER: Senchuk Ford has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply. Reply STOP to opt out.

WE PROVIDE PERSONAL & TRANSACTION INFORMATION TO FORD MOTOR CO. TO ADMINISTER TRANSACTIONS, PROVIDE REQUESTED SERVICES, IMPROVE RELATED PRODUCTS BY CONDUCTING SURVEYS & PROVIDE MARKETING MATERIAL. VISIT WWW.FORD.CA FOR PRIVACY POLICY. CALL 1-800-565-FORD. IF YOU DO NOT WANT MARKETING OR SURVEY MATERIALS.

- ☐ CASH  
☐ CREDIT CARD  
☐ CHEQUE  
☐ DEDUCTIBLE
- TERMS**  
- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.  
- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.  
- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.  
- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.  
- NO REFUNDS WITHOUT THIS INVOICE.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$\_\_\_\_\_ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.  
TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

X \_\_\_\_\_  
CUSTOMER SIGNATURE DATE

G.S.T# 104781737



**Senchuk**  
**FORD SALES LTD.**

306 634-3696

[www.senchuk.com](http://www.senchuk.com)

**SO# 354632**

Status  
Printed 04/25/2025 3:55:19 PM

118 SOURIS AVE  
ESTEVAN, SK S4A 1J6  
Ph: (306) 634-3696, (855) 634-3696 Fax: (306) 634-4262

**SERVICE ORDER**  
**CUSTOMER COPY**



User 5673 Page 2

Customer No 112913

HEATHER WOODHOUSE

521 PRINCE ST

STEVAN SK S4A 1J6

Home 306 634-8178 Bus

Cell 306 421-2457 Today

Email hwood@senchuk.ca

Type  
Term MC

Advisor Jenelle  
Shop S1  
Priority  
Promised 01/10/2023 5:30 PM  
Opened 01/10/2023 8:07 AM  
Cashiered 01/26/2023 3:49 PM  
Tag#  
Location  
PO #

License	Odom In	Odom Out	In Service Date	Stock No
	207298	207298	07/08/2013	24BS21AA
Year	Make	Model	Model Number	Colour
2014	FORD	ESCAPE		SILVER
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FMCU9GX9EUA08019	SENCUK FORD		04/25/2025	
Engine	1.6L L4 DIR DO	Fleet #		

JEROD (SGI) 306 691 4526  
TOM WOODHOUSE 306 421 0054  
USED ENGINE WAS INSTALLED , HAD NO COMPRESSION

Labour	1,520.00
Parts	3.98
Supplies	65.00
<b>Sub-Total</b>	<b>1,588.98</b>
GST	79.45
PST	95.34
<b>Total Invoice</b>	<b>1,763.77</b>
MC	1,763.77

TEXTING DISCLAIMER: Senchuk Ford has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply. Reply STOP to opt out.

WE PROVIDE PERSONAL & TRANSACTION INFORMATION TO FORD MOTOR CO. TO ADMINISTER TRANSACTIONS, PROVIDE REQUESTED SERVICES, IMPROVE RELATED PRODUCTS BY CONDUCTING SURVEYS & PROVIDE MARKETING MATERIAL. VISIT [WWW.FORD.CA](http://WWW.FORD.CA) FOR PRIVACY POLICY. CALL 1-800-565-FORD. IF YOU DO NOT WANT MARKETING OR SURVEY MATERIALS.

- ☐ CASH  
☐ CREDIT CARD  
☐ CHEQUE  
☐ DEDUCTIBLE

**TERMS**

- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.
- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.
- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.
- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.
- NO REFUNDS WITHOUT THIS INVOICE.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.  
TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

X \_\_\_\_\_  
CUSTOMER SIGNATURE DATE

G.S.T# 104781737



**Senchuk**  
**FORD SALES LTD.**

306 634-3696

[www.senchuk.com](http://www.senchuk.com)

118 SOURIS AVE  
ESTEVAN, SK S4A 1J6  
Ph: (306) 634-3696, (855) 634-3696 Fax: (306) 634-4262

**SO# 354923**

Status

Printed 04/25/2025 4:00:45 PM

**SERVICE ORDER**  
**CUSTOMER COPY**

User 5305 Page 1



Customer No 112913

[REDACTED]

[REDACTED]

ESTEVAN, SK

Home [REDACTED]

Cell [REDACTED]

Email [REDACTED]

Type  
Term MC

Advisor Amber Promised 01/27/2023 5:30 PM Tag#  
Shop S1 Opened 01/27/2023 8:34 AM Location  
Priority Cashiered 03/16/2023 1:20 PM PO#

License Odom In Odom Out In Service Date Stock No  
207298 207298 07/08/2013 24BS21AA  
Year Make Model Model Number Colour  
2014 FORD ESCAPE SILVER  
Vehicle ID No Selling Dealer Extended Warranty Delivery Date  
1FMCU9GX9EUA08019 SENCHUK FORD 04/25/2025  
Engine 1.6L L4 DIR DO Fleet #

Request	Description					Job	CSR	Status
96	replace battery					1	5013	Original
Labour	Description						Type	Amount
96	replace battery						CSP	128.00
Part	Description		Shp	Bin	Type		Price	Amount
BXT 96 R590	BATTERY		1	BR2	CSO		200.94	200.94
Technician	6495 -				Parts Total			200.94
Cause	replace battery				Labour Total			128.00
Correction	replaced battery				Request Sub-total			328.94

Request	Description	Job	CSR	Status		
96	replace pass front wheel bearing	2	5013	Original		
Labour	Description	Type	Amount			
96	replace pass front wheel bearing	CSP	384.00			
Part	Description	Shp	Bin	Type	Price	Amount
BRG 147	BEARING ASY - WHEEL	1	RETURN	CSO	162.37	162.37
BRG 147	BEARING ASY - WHEEL	1	RETURN	CSO	162.37	162.37
TX 1169	SHAFT - FRONT AXLE	1		CSO	382.38	382.38
YS4Z 3N324 AA	RETAINER - BEARING	1	FR3	CSO	2.64	2.64
CCPZ 3B477 B	RETAINER - NUT	1	FR3	CSO	2.98	2.98
CN1Z 7H424 B	SEAL	1	FR4	CSO	23.41	23.41
Technician	6495 -	Parts Total				736.15
Cause	found out the front bearing there is play both axle nuts lost	Labour Total				384.00
Correction	replace both front wheel bearing and axle seal rh front axle assmly	Request Sub-total				1,120.15

Request	Description				Job	CSR	Status
96	install rad hose and water valve				3	5013	Original
Labour	Description				Type	Amount	
96	install rad hose and water valve				CSP	624.00	
Part	Description	Shp	Bin	Type	Price	Amount	
KM 5127	HOSE - RADIATOR	1		CSO	215.57	215.57	
WA 11 SBA	STRAP - WIRING	6	FR1	CSO	0.16	0.96	
WA 7 SBA	STRAP - WIRING	10	FR1	CSO	0.10	1.00	
YG 780	VALVE ASY	1	RETURN	CSO	153.78	153.78	
BM5Z 9439 A	GASKET - INTAKE MANI	1		CSO	91.08	91.08	

TEXTING DISCLAIMER: Senchuk Ford has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply. Reply STOP to opt out.

WE PROVIDE PERSONAL & TRANSACTION INFORMATION TO FORD MOTOR CO. TO ADMINISTER TRANSACTIONS, PROVIDE REQUESTED SERVICES, IMPROVE RELATED PRODUCTS BY CONDUCTING SURVEYS & PROVIDE MARKETING MATERIAL. VISIT [WWW.FORD.CA](http://WWW.FORD.CA) FOR PRIVACY POLICY, CALL 1-800-565-FORD. IF YOU DO NOT WANT MARKETING OR SURVEY MATERIALS.

- ☐ CASH  
☐ CREDIT CARD  
☐ CHEQUE  
☐ DEDUCTIBLE

**TERMS**  
- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.  
- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.  
- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.  
- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.  
- NO REFUNDS WITHOUT THIS INVOICE.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.  
TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

X \_\_\_\_\_  
CUSTOMER SIGNATURE DATE

G.S.T # 104781737



# Senchuk

FORD SALES LTD.

306 634-3696

www.senchuk.com

118 SOURIS AVE  
ESTEVAN, SK S4A 1J6  
Ph: (306) 634-3696, (855) 634-3696 Fax: (306) 634-4262

SO# 354923

## SERVICE ORDER CUSTOMER COPY



Status  
Printed 04/25/2025 4:00:45 PM

User 5305 Page 2

Customer No 112913

Advisor Amber Promised 01/27/2023 5:30 PM Tag#  
Shop S1 Opened 01/27/2023 8:34 AM Location  
Priority Cashiered 03/16/2023 1:20 PM PO #

License	Odom In	Odom Out	In Service Date	Stock No
	207298	207298	07/08/2013	24BS21AA
Year Make	Model	Model Number	Colour	
2014 FORD	ESCAPE		SILVER	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FMCU9GX9EUA08019	SENCHUK FORD		04/25/2025	
Engine	1.6L L4 DIR DO	Fleet #		

DY 1194 SENDER ASY 1 CSO 73.90 73.90  
Technician 6495 - Parts Total 536.29  
Cause check coolant system found out the coolant line system is leaking and the  
coolant by-pass plug and coolant hose line he put wrong spot Labour Total 624.00  
Correction remove and replace rad hose line and by-pass valve Request Sub-total 1,160.29

Request	Description	Job	CSR	Status		
96	install new motor mount	4	5013	Original		
Labour	Description	Type	Amount			
96	install new motor mount	CSP	208.00			
Part	Description	Shp	Bin	Type	Price	Amount
CV6Z 6038 B	BRACKET - ENGINE FRO	1		CSO	141.04	141.04
W708873 S437	STUD	3		CSO	18.10	54.30
W520204 S442	NUT - HEX.	4	RETURN	CSO	0.71	2.84
Technician	6495 -	Parts Total				198.18
Cause	install new motor mount	Labour Total				208.00
Correction	install new motor mount	Request Sub-total				406.18

Request	Description	Job	CSR	Status	
96	check out engine wiring	5	5013	Approved	
Labour	Description	Type	Amount		
96	check out engine wiring	CSP	640.00		
Technician	6495 -	Labour Total			640.00
Cause	check out engine wiring	Request Sub-total			640.00
Correction	followed service procedure and drained the cooling system. remove the intake and wiring recover the ac and re installed the wiring harness filled the cooling system. forof the vehicle. checked none found. all okay.				

Request	Description	Job	CSR	Status		
96	replace front driver axle seal	6	5305	Approved		
Labour	Description	Type	Amount			
96	replace front driver axle seal	CSP	352.00			
Part	Description	Shp	Bin	Type	Price	Amount
9L8Z 1177 G	SEAL	1	FR2	CSO	28.00	28.00
Technician	1991 -	Parts Total				28.00
Cause	replace front driver axle seal	Labour Total				352.00

TEXTING DISCLAIMER: Senchuk Ford has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply. Reply STOP to opt out.

WE PROVIDE PERSONAL & TRANSACTION INFORMATION TO FORD MOTOR CO. TO ADMINISTER TRANSACTIONS, PROVIDE REQUESTED SERVICES, IMPROVE RELATED PRODUCTS BY CONDUCTING  
SUREVEYS & PROVIDE MARKETING MATERIAL. VISIT WWW.FORD.CA FOR PRIVACY POLICY. CALL 1-800-565-FORD. IF YOU DO NOT WANT MARKETING OR SURVEY MATERIALS.

- ☐ CASH  
☐ CREDIT CARD  
☐ CHEQUE  
☐ DEDUCTIBLE

TERMS  
- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.  
- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.  
- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.  
- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE  
SUBJECT TO A 15% HANDLING CHARGE.  
- NO REFUNDS WITHOUT THIS INVOICE.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OR THE  
BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.  
TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE  
ACCOUNTS.

X \_\_\_\_\_ DATE  
CUSTOMER SIGNATURE

G.S.T# 104781737



**Senchuk**  
**FORD SALES LTD.**

306 634-3696

[www.senchuk.com](http://www.senchuk.com)

118 SOURIS AVE  
ESTEVAN, SK S4A 1J6  
Ph: (306) 634-3696, (855) 634-3696 Fax: (306) 634-4262

**SO# 354923**

Status  
Printed 04/25/2025 4:00:45 PM

**SERVICE ORDER**  
**CUSTOMER COPY**

User 5305 Page 3



Customer No 112913

Advisor Amber Promised 01/27/2023 5:30 PM Tag#  
Shop S1 Opened 01/27/2023 8:34 AM Location  
Priority Cashiered 03/16/2023 1:20 PM PO #

License	Odom In	Odom Out	In Service Date	Stock No
	207298	207298	07/08/2013	24BS21AA
Year Make	Model	Model Number	Colour	
2014 FORD	ESCAPE		SILVER	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FMCU9GX9EUA08019	SENCHUK FORD		04/25/2025	
Engine	1.6L L4 DIR DO	Fleet #		

Type  
Term MC

Correction followed service procedure, raised vehicle, removed drivers front tire, removed brake caliper, and outer tie rod nut. removed lower ball joint pinch bolt and removed from knuckle. removed axle nut and axle shaft assembly. removed old axle seal, cleaned mating surface and installed a new seal. reassembled all previously uninstalled components and added fluid. test drove and checked fluid level. all okay.

Request Sub-total 380.00

Request	Description	Job	CSR	Status		
QLTRF	TRANSMISSION FLUID FLUSH	7	5305	Approved		
Labour	Description	Type	Amount			
QLTRF	TRANSMISSION FLUID FLUSH	CSP	155.00			
Part	Description	Shp	Bin	Type	Price	Amount
CXT 10 LV6	ADDITIVE - OIL - FRI	4	CHEM	CSO	13.91	55.64
ENOIL	ENV FEE	4		CSO	0.05	0.20
EOILPCSK	ENV FEE	4		CSO	0.10	0.40
Technician	1991 -	Parts Total				56.24
Cause	TRANSMISSION FLUID FLUSH	Labour Total				155.00
Correction	drained and filled transmission, test drove vehicle, and rechecked fluid level. also noticed the rear main seal is leaking badly	Request Sub-total				211.24

Labour	2,491.00
Parts	1,755.80
Supplies	65.00
<b>Sub-Total</b>	<b>4,311.80</b>
GST	215.59
PST	258.71
<b>Total Invoice</b>	<b>4,786.10</b>
MC	4,786.10

TEXTING DISCLAIMER: Senchuk Ford has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply. Reply STOP to opt out.

WE PROVIDE PERSONAL & TRANSACTION INFORMATION TO FORD MOTOR CO. TO ADMINISTER TRANSACTIONS, PROVIDE REQUESTED SERVICES, IMPROVE RELATED PRODUCTS BY CONDUCTING SURVEYS & PROVIDE MARKETING MATERIAL. VISIT [WWW.FORD.CA](http://WWW.FORD.CA) FOR PRIVACY POLICY. CALL 1-800-565-FORD. IF YOU DO NOT WANT MARKETING OR SURVEY MATERIALS.

- ☐ CASH  
☐ CREDIT CARD  
☐ CHEQUE  
☐ DEDUCTIBLE

**TERMS**  
- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.  
- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.  
- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.  
- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.  
- NO REFUNDS WITHOUT THIS INVOICE.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.  
TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

X \_\_\_\_\_  
CUSTOMER SIGNATURE DATE

G.S.T# 104781737



# Senchuk

FORD SALES LTD.

306 634-3696

www.senchuk.com

118 SOURIS AVE  
ESTEVAN, SK S4A 1J6  
Ph: (306) 634-3696, (855) 634-3696 Fax: (306) 634-4262

SO# 355744

## SERVICE ORDER CUSTOMER COPY



Status  
Printed 04/25/2025 4:01:04 PM

User 5305 Page 1

Customer No 112913

HEATHER W. [REDACTED]

[REDACTED]

[REDACTED] (908) 374-1175 [REDACTED]

[REDACTED] (306) 634-3696 [REDACTED]

[REDACTED] [REDACTED]@senchuk.net

Type  
Term CHEQUES

Advisor Amber Promised 03/23/2023 5:30 PM Tag#  
Shop S1 Opened 03/23/2023 4:02 PM Location  
Priority Cashiered 04/03/2023 3:37 PM PO #

License	Odom In	Odom Out	In Service Date	Stock No
	207505	207505	07/08/2013	24BS21AA
Year Make	Model	Model Number	Colour	
2014 FORD	ESCAPE		SILVER	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FMCU9GX9EUA08019	SENCUK FORD		04/25/2025	
Engine	1.6L L4 DIR DO	Fleet #		

Request	Description	Job	CSR	Status		
96	check multiple lights on dash - hill assist, battery, traction ,abs- battery was just replaced	1	5013	Original		
Labour	Description		Type	Amount		
96	check multiple lights on dash - hill assist, battery, traction ,abs- battery was just replaced		CSP	0.00		
96	check multiple lights on dash - hill assist, battery, traction ,abs- battery was just replaced		CSP	544.00		
Part	Description	Shp	Bin	Type	Price	Amount
GL 8785	ALTERNATOR ASY	1		CSO	724.09	724.09
CORE CHARGE	CORE CHARGE GL 8785	1		CSO	35.00	35.00
C-GL 8785	CORE RETURN	-1		CSO	35.00	(35.00)
Technician	1991 -			Parts Total		724.09
	6495 -			Labour Total		544.00
Cause	check multiple lights on dash - hill assist, battery, traction ,abs- battery was just replaced, verified customer concern, hooked up IDS, had multiple codes for battery voltage under BCM,PCM,ABS. Tested the starting/charging system, only had a voltage output of 9.5v and 10.7v, found that the electrical wiring was no good. recommend replacing the alternator. also lack of power will affect power steering and all accessory features.			Request Sub-total		1,268.09
Correction	remove and replace new alternator					

Request	Description	Job	CSR	Status
96	check power steering - hard to turn	2	5013	Original
Labour	Description		Type	Amount
96	check power steering - hard to turn		CSP	0.00
Technician	1991 -			
Cause	related to line 1			

Labour	544.00
Parts	724.09
Supplies	54.40
Sub-Total	1,322.49
GST	66.12
PST	79.35
Total Invoice	1,467.96
CHEQUES	1,467.96

TEXTING DISCLAIMER: Senchuk Ford has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply. Reply STOP to opt out.

WE PROVIDE PERSONAL & TRANSACTION INFORMATION TO FORD MOTOR CO. TO ADMINISTER TRANSACTIONS, PROVIDE REQUESTED SERVICES, IMPROVE RELATED PRODUCTS BY CONDUCTING SURVEYS & PROVIDE MARKETING MATERIAL. VISIT WWW.FORD.CA FOR PRIVACY POLICY. CALL 1-800-565-FORD. IF YOU DO NOT WANT MARKETING OR SURVEY MATERIALS.

- ☐ CASH  
☐ CREDIT CARD  
☐ CHEQUE  
☐ DEDUCTIBLE

TERMS  
- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.  
- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.  
- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.  
- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.  
- NO REFUNDS WITHOUT THIS INVOICE.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.  
TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

X \_\_\_\_\_  
CUSTOMER SIGNATURE DATE

G.S.T# 104781737





**Senchuk**  
FORD SALES LTD.

306 634-3696

www.senchuk.com

118 SOURIS AVE  
ESTEVAN, SK S4A 1J6  
Ph: (306) 634-3696, (855) 634-3696 Fax: (306) 634-4262

**SO# 358792**

Status

Printed 04/25/2025 4:02:00 PM

**SERVICE ORDER**  
**CUSTOMER COPY**

User 5305 Page 1



Customer No 112913

Advisor Amber Promised 10/19/2023 5:30 PM Tag#  
Shop S1 Opened 10/19/2023 8:15 AM Location  
Priority Cashiered 11/03/2023 10:18 AM PO #

License Odom In Odom Out In Service Date Stock No  
217082 217086 07/08/2013 24BS21AA  
Year Make Model Model Number Colour  
2014 FORD ESCAPE SILVER  
Vehicle ID No Selling Dealer Extended Warranty Delivery Date  
1FMCU9GX9EUA08019 SENCHUK FORD 04/25/2025  
Engine 1.6L L4 DIR DO Fleet #

Request	Description	Job	CSR	Status		
18	COOLANT LEAK, CHECK/REPAIR/REPLACE	1	5013	Original		
Labour	Description		Type	Amount		
18	COOLANT LEAK, CHECK/REPAIR/REPLACE		CSP	320.00		
18	COOLANT LEAK, CHECK/REPAIR/REPLACE		CSP	0.00		
Part	Description	Shp	Bin	Type	Price	Amount
RH 225	CONNECTION - WATER O	1		CSO	110.76	110.76
BM5Z 8C309 A	GASKET	1		CSO	33.80	33.80
CVC 13 DLG	ANTI-FREEZE	2	CHEM	CSO	20.76	41.52
EANTILSK	ENV FEE	2		CSO	0.56	1.12
EANTICSK	ENV FEE	2		CSO	0.40	0.80
Technician	6531 -	Parts Total				188.00
	4396 -	Labour Total				320.00
Cause	COOLANT LEAK, CHECK/REPAIR/REPLACE. pressure up the cooling system. found a leak coming form the plastic coolant block the left side of the cylinder head. need to replaced and re fill the cooling system.		Request Sub-total		508.00	
Correction	removed and replaced coolant block on drivers side of engine, filled cooling system to spec, road tested and topped up coolant, all ok at this time, washed all coolant from engine as well					

Request	Description	Job	CSR	Status		
96	check for leak from washer fluid, filled it up and not spraying	2	5013	Original		
Labour	Description		Type	Amount		
96	check for leak from washer fluid, filled it up and not spraying		CSP	144.00		
96	check for leak from washer fluid, filled it up and not spraying		CSP	0.00		
Part	Description	Shp	Bin	Type	Price	Amount
CJ5Z 17618 B	RESERVOIR - WINDSHIE	1		CSO	131.23	131.23
CXC 37 L	SOLU W/WSHR	4	CHEM	CSO	1.98	7.92
Technician	6531 -	Parts Total				139.15
	4396 -	Labour Total				144.00
Cause	check for leak from washer fluid, filled it up and not spraying. found the washer fluid tank cracked. needs a new tank.	Request Sub-total				283.15
Correction	removed washer tank and installed new washer tank, filled with new fluid and tested, asystem operates well at this time,					

TEXTING DISCLAIMER: Senchuk Ford has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply. Reply STOP to opt out.

WE PROVIDE PERSONAL & TRANSACTION INFORMATION TO FORD MOTOR CO. TO ADMINISTER TRANSACTIONS, PROVIDE REQUESTED SERVICES, IMPROVE RELATED PRODUCTS BY CONDUCTING SURVEYS & PROVIDE MARKETING MATERIAL. VISIT WWW.FORD.CA FOR PRIVACY POLICY. CALL 1-800-565-FORD. IF YOU DO NOT WANT MARKETING OR SURVEY MATERIALS.

- ☐ CASH  
☐ CREDIT CARD  
☐ CHEQUE  
☐ DEDUCTIBLE
- TERMS**  
- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.  
- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.  
- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.  
- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.  
- NO REFUNDS WITHOUT THIS INVOICE.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.  
TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

X \_\_\_\_\_  
CUSTOMER SIGNATURE DATE

G.S.T# 104781737



**Senchuk**  
**FORD SALES LTD.**

306 634-3696

[www.senchuk.com](http://www.senchuk.com)

**SO# 358792**

Status

Printed 04/25/2025 4:02:00 PM

118 SOURIS AVE

ESTEVAN, SK S4A 1J6

Ph: (306) 634-3696, (855) 634-3696 Fax: (306) 634-4262

**SERVICE ORDER**  
**CUSTOMER COPY**



User 5305

Page 2

Customer No 112913

HEATER W/ FUEL INJECTOR

28 PRICES \$

ESTEVAN, SK S4A 1J6

Home (306) 634-3178 Bds

Cell (306) 421-2457 Today

Email blade@senchuk.net

Type  
Term MC

Advisor Amber Promised 10/19/2023 5:30 PM Tag#  
Shop S1 Opened 10/19/2023 8:15 AM Location  
Priority Cashiered 11/03/2023 10:18 AM PO #

License	Odom In	Odom Out	In Service Date	Stock No
	217082	217086	07/08/2013	24BS21AA
Year	Make	Model	Model Number	Colour
2014	FORD	ESCAPE		SILVER
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FMCU9GX9EUA08019	SENCUK FORD		04/25/2025	
Engine	1.6L L4 DIR DO	Fleet #		

Labour	464.00
Parts	327.15
Supplies	46.40
<b>Sub-Total</b>	<b>837.55</b>
GST	41.88
PST	50.25
<b>Total Invoice</b>	<b>929.68</b>
MC	929.68

TEXTING DISCLAIMER: Senchuk Ford has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply. Reply STOP to opt out.

WE PROVIDE PERSONAL & TRANSACTION INFORMATION TO FORD MOTOR CO. TO ADMINISTER TRANSACTIONS, PROVIDE REQUESTED SERVICES, IMPROVE RELATED PRODUCTS BY CONDUCTING SURVEYS & PROVIDE MARKETING MATERIAL. VISIT [WWW.FORD.CA](http://WWW.FORD.CA) FOR PRIVACY POLICY. CALL 1-800-565-FORD. IF YOU DO NOT WANT MARKETING OR SURVEY MATERIALS.

- ☐ CASH  
☐ CREDIT CARD  
☐ CHEQUE  
☐ DEDUCTIBLE

**TERMS**

- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.  
- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.  
- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.  
- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.  
- NO REFUNDS WITHOUT THIS INVOICE.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.  
TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

X \_\_\_\_\_  
CUSTOMER SIGNATURE DATE

G.S.T# 104781737





**Senchuk**  
**FORD SALES LTD.**

306 634-3696

[www.senchuk.com](http://www.senchuk.com)

118 SOURIS AVE  
ESTEVAN, SK S4A 1J6  
Ph: (306) 634-3696, (855) 634-3696 Fax: (306) 634-4262

**SO# 359400**

Status

Printed 04/25/2025 4:02:21 PM

**SERVICE ORDER**  
**CUSTOMER COPY**

User 5305 Page 1



Customer No 112913

Advisor Amber Promised 11/21/2023 5:30 PM Tag#  
Shop S1 Opened 11/21/2023 9:41 AM Location  
Priority Cashiered 11/29/2023 4:40 PM PO #

License Odom In Odom Out In Service Date Stock No  
218353 218353 07/08/2013 24BS21AA  
Year Make Model Model Number Colour  
2014 FORD ESCAPE SILVER  
Vehicle ID No Selling Dealer Extended Warranty Delivery Date  
1FMCU9GX9EUA08019 SENCHUK FORD 04/25/2025  
Engine 1.6L L4 DIR DO Fleet #

Request	Description	Job	CSR	Status		
96	still getting the message for low coolant - check history	1	5013	Original		
Labour	Description		Type	Amount		
96	still getting the message for low coolant		CSP	464.00		
96	still getting the message for low coolant - check history		CSP	0.00		
Part	Description	Shp	Bin	Type	Price	Amount
CV6Z 7A095 A	OIL COOLER ASY	1	SOP	CSO	144.46	144.46
5L7Z 7D285 A	SEAL - SPECIAL	2	RETURN	CSO	19.61	39.22
5L7Z 7J324 A	RING	2	RETURN	CSO	24.61	49.22
CXT 10 LV6	ADDITIVE - OIL - FRI	0.5	CHEM	CSO	13.10	6.55
ENOIL	ENV FEE	0.5		CSO	0.05	0.03
EOILPCSK	ENV FEE	0.5		CSO	0.10	0.05
Technician	6531 -	Parts Total				239.53
	4396 -	Labour Total				464.00
Cause	still getting the message for low coolant - check history. verified the customer concern. pressured up the cooling system. found a coolant leak coming from the transmission cooler. needs a new cooler.	Request Sub-total				703.53
Correction	removed and replaced oil cooler, pressure tested system found no leaks at this time, all ok, ionstalled battery tray and intska etube all ok at this time, topped up cooling system and filled transmission to spec, all ok					

Labour	464.00
Parts	239.53
Supplies	0.00
<b>Sub-Total</b>	<b>703.53</b>
GST	35.18
PST	42.21
<b>Total Invoice</b>	<b>780.92</b>
MC	780.92

TEXTING DISCLAIMER: Senchuk Ford has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply. Reply STOP to opt out.

WE PROVIDE PERSONAL & TRANSACTION INFORMATION TO FORD MOTOR CO. TO ADMINISTER TRANSACTIONS, PROVIDE REQUESTED SERVICES, IMPROVE RELATED PRODUCTS BY CONDUCTING SURVEYS & PROVIDE MARKETING MATERIAL. VISIT [WWW.FORD.CA](http://WWW.FORD.CA) FOR PRIVACY POLICY. CALL 1-800-565-FORD. IF YOU DO NOT WANT MARKETING OR SURVEY MATERIALS.

- ☐ CASH  
☐ CREDIT CARD  
☐ CHEQUE  
☐ DEDUCTIBLE

**TERMS**  
- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.  
- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.  
- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.  
- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.  
- NO REFUNDS WITHOUT THIS INVOICE.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$\_\_\_\_\_ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.  
TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

X \_\_\_\_\_  
CUSTOMER SIGNATURE DATE

G.S.T# 104781737



**Senchuk**  
**FORD SALES LTD.**

306 634-3696

[www.senchuk.com](http://www.senchuk.com)

118 SOURIS AVE  
ESTEVAN, SK S4A 1J6  
Ph: (306) 634-3696, (855) 634-3696 Fax: (306) 634-4262

**SO# 360410**

Status

Printed 04/25/2025 4:02:45 PM

**SERVICE ORDER**  
**CUSTOMER COPY**

User 5305 Page 1



Customer No 112913

Advisor Jenelle  
Shop S1  
Priority  
Promised 01/29/2024 5:30 PM  
Opened 01/29/2024 12:38 PM  
Cashiered 02/06/2024 1:08 PM  
Tag#  
Location  
PO #

License Odom In Odom Out In Service Date Stock No  
219500 219515 07/08/2013 24BS21AA  
Year Make Model Model Number Colour  
2014 FORD ESCAPE SILVER  
Vehicle ID No Selling Dealer Extended Warranty Delivery Date  
1FMCU9GX9EUA08019 SENCHUK FORD 04/25/2025  
Engine 1.6L L4 DIR DO Fleet #

Request	Description	Job	CSR	Status		
96	replace front drive cv axle and seal	1	5305	Original		
Labour	Description		Type	Amount		
96	replac efront drive cv axle and seal		CSP	330.00		
Part	Description	Shp	Bin	Type	Price	Amount
9L8Z 1177 F	SEAL	1	FR2	CSO	39.20	39.20
TX 611	SHAFT - FRONT AXLE	1		CSO	361.79	361.79
CXT 10 LV6	ADDITIVE - OIL - FRI	5	CHEM	CSO	14.45	72.25
ENOIL	ENV FEE	5		CSO	0.05	0.25
EOILPCSK	ENV FEE	5		CSO	0.10	0.50
Technician	6531 -	Parts Total				473.99
Cause	replace front drive cv axle and seal	Labour Total				330.00
Correction	followed the service procedure and replaced the left front axel bushing, seal and cv axel. drained the transmission and filled up the fluid. road test vehicle and checked the fluid level. all okay	Request Sub-total				803.99

Labour	330.00
Parts	473.99
Supplies	33.00
<b>Sub-Total</b>	<b>836.99</b>
GST	41.85
PST	50.22
<b>Total Invoice</b>	<b>929.06</b>
MC	929.06

TEXTING DISCLAIMER: Senchuk Ford has the ability to contact you via Mobile texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply. Reply STOP to opt out.

WE PROVIDE PERSONAL & TRANSACTION INFORMATION TO FORD MOTOR CO. TO ADMINISTER TRANSACTIONS, PROVIDE REQUESTED SERVICES, IMPROVE RELATED PRODUCTS BY CONDUCTING SURVEYS & PROVIDE MARKETING MATERIAL. VISIT [WWW.FORD.CA](http://WWW.FORD.CA) FOR PRIVACY POLICY. CALL 1-800-565-FORD. IF YOU DO NOT WANT MARKETING OR SURVEY MATERIALS.

- ☐ CASH  
☐ CREDIT CARD  
☐ CHEQUE  
☐ DEDUCTIBLE

**TERMS**  
- PLEASE PAY ON INVOICE. NO STATEMENT WILL BE ISSUED.  
- NO REFUNDS OR EXCHANGE ON PARTS AFTER 30 DAYS.  
- NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS, GLASS OR SPECIAL ORDERS.  
- PARTS RETURNED FOR CREDIT THAT HAVE BEEN SUPPLIED AS ORDERED ARE SUBJECT TO A 15% HANDLING CHARGE.  
- NO REFUNDS WITHOUT THIS INVOICE.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.  
TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

X \_\_\_\_\_  
CUSTOMER SIGNATURE DATE

G.S.T # 104781737