

# FARMTRONICS®

**Invoice 662938**

Date Invoiced  
6/18/2021

Remit To:  
Farmtronics Ltd.  
380 Henderson Drive  
Regina, Saskatchewan S4N 5W9

**PAID**  
06/18/2021

**Sold To**

**Ship To**

GST/HST No. 101743136

<b>S.O. No.</b>	<b>P.O. No.</b>	<b>Terms</b>	<b>Ship Via</b>	<b>Account #</b>	<b>PPD</b>	<b>COL</b>
89165		Due on receipt	Pick Up			

Item	Description	Ordered	Price Each	Shipped	Amount
FLC-	13920V2 Variable Drive Air Cart SN 01692570 Inspect, test, no faults found, all functions normal.	1	239.60	1	239.60

FARMTRONICS EQUIPMENT  
380 HENDERSON DR  
REGINA, SK S4N 5W9  
Merchant ID: 0000000003100880  
Term ID: 00698793  
21159230010

**Purchase**

MASTERCARD  
XXXXXXXXXXXX  
AID: A000000041010  
Entry Method: Chip  
Batch#: 001241  
13:28:55  
06/18/21  
Ref#: 00067732863  
Inv #: 015304 Appr Code: 07372J  
Total: \$ 251.58

Customer Copy

<b>Subtotal</b>	\$239.60
GST@5.0%	11.98
Total Tax	11.98
<b>Total</b>	\$251.58
<b>Payments/Credits</b>	-\$251.58
<b>Balance Due</b>	\$0.00



**IN  
ENT**

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit To:  
Box 280, Hwy 9 South  
#1 Rocky Mountain Way  
Yorkton, Sask. S3N 2V7  
Tel: (306) 783-8508  
Fax: (306) 786-7880

# INVOICE

26K

Ship to:  
  
Invoice to:

[Empty boxes for ship and invoice to information]

Branch YORKTON		
Date 06/24/21	Time 09:30:36 (O)	Page 01
Account No.	Phone No.	Reference No.
Ship Via	Purchase Order ?	
Credit Card No.	Salesperson L98	

## Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	
153123	3450	FLEXI-COIL TA 3450	X G-50-A000-1079442		
SEGMENT# 1 5 03513 NA	06/14/21	06/14/21			
TRAVEL					
FREIGHT					
51200013		FREIGHT		1	20.00
		SENSOR, ADX		1 M	794.37
					20.00
					794.37
					814.37
					340.00
					1154.37
13300059					
SEGMENT# 2 5 03513 NA	06/14/21	06/14/21			
CHECK CAUSE OF NO POWER TO METER MOTORS					

**COMPLAINT:**

meter motors wont turn

**CAUSE:**

hydraulic pressure switch failed and cal switch was not working

**CORRECTION:**

June 14- travel out to customers location and verify complaint that the meter motors wont turn made sure all switches are on and where they are suppose to be and they were jumped power to all meter motors to make sure that they will turn when power is applied to them and they all spun when twelve volts were applied to the motor made sure monitor configurations were right and they were cal numbers were there checked down the meter switches and was only .5 of a volt should see at least 1.5 volts to make the motors turn for power coming from the cal button was pushed checked voltage did not change when the cal button was pushed checked continuity off the circuits for tank 2 and 3 for sure followed wires checked out from remote to switch, to motor, back to remote and had continuity on both circuits front tank

CONTINUED ON PAGE 02

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full. An express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional

(signature) \_\_\_\_\_  
(date) \_\_\_\_\_

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature) \_\_\_\_\_  
(date) \_\_\_\_\_

(signature)

**ROCKY MOUNTAIN EQUIPMENT**  
 Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit To:  
 Box 280, Hwy 9 South  
 #1 Rocky Mountain Way  
 Yorkton, Sask. S3N 2V7  
 Tel: (306) 783-8508  
 Fax: (306) 786-7880

**INVOICE** IC

Ship to:  
 Invoice to:

Branch <b>YORKTON</b>		
Date 06/24/21	Time 09:30:36 (O)	Page 02
Account No.	Phone No.	Reference No.
Ship Via	Purchase Order ?	
Credit Card No.	Salesperson L98	

**Description of Work and Parts**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold ---
153123	3450	FLEXI-COIL TA	X G-50-A000-1079442		

does not spin over either but that is just triggered through the CAN system studied schematic for anything else to check pulled loom off of harness and did not see any worn or rubbed wires did a wiggle test while doing to continuity check and never lost contact back probed into remote connector to see if had more voltage at remote and it was the same diagnosed that it could have been something in the ECU(remote) that was not being triggered to get it to spin the meter motors removed remote and customer was going to take it into farmtronics to have it checked out clean up tools travel back to shop customer got ecu back and was no internal issues gathered up some more parts and went back out to unit checked continuity on all three tank circuits and had continuity on all tanks going through the meter motors had voltage coming out of ecu going to tank 3 meter motor switch but was not being triggered to turn motor had put an assist case in went through the steps that were provided from them and made sure monitor was set up correctly for width, coil numbers, and set up for a VR cart and was all set up the way it should be plugged remote back in unplugged velocity sensors and bin level sensors so only meter motors and shaft rpm was in the circuits lowered manifolds and pressurized the motor circuit flipped on switches in cab and made sure tank switches were on hit cal button (new one installed) still nothing went back to monitor and found low hyd pressure alarm on followed steps according to etim and swapped a velocity sensor and plugged into the connector for pressure sensor hit cal button and meters would turn made sure all were turning with the corresponding switches and they were shut unit down put baffles and shields into place put manifolds back there should

CONTINUED ON PAGE 03

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)

INVOICE

**ROCKY MOUNTAIN EQUIPMENT**  
 Rocky Mountain Equipment LP of a Rocky Mountain Equipment

Please Remit To:  
 Box 280, Hwy 9 South  
 #1 Rocky Mountain Way  
 Yorkton, Sask. S3N 2V7  
 Tel: (306) 783-8508  
 Fax: (306) 786-7880

Invoice to:

Blank area for customer information.

Branch YORKTON		
Date 06/24/21	Time 09:30:36 (O)	Page 03
Account No.	Phone No.	Reference No.
Ship Via	Purchase Order ?	
Credit Card No.	Salesperson L98	

**Description of Work and Parts**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
153123	3450 FLEXI-COIL TA 3450		X G-50-A000-1079442			Fold ---
d be plugged in binlevel sensors and velocity sensors fire d unit up and drove around and meters were turning and shutt ing off when commanded too and reading rate (needs to be cal ibrated yet but reading) meters now working got proper part s on order for customer and he is going to install them hims elf tank now working properly clean up tools travel back to shop complete paperwork						
	FREIGHT	1		45.00		45.00
343660A1	COVER	1		45.70		45.70
47739163	SWITCH, TOGGLE	1		288.64		288.64
51671824	SWITCH	1		7.83		7.83
	PARTS					387.17
	LABOR					1802.15
13300059	SEGMENT TOTAL==>					2189.32

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS	1201.54
LABOR	2142.15
DISPOSAL FEE	56.61
SHOP SUPPLIES	240.59
SUB TOTAL==>	3640.89
GST 797594660	182.06
TOTAL CASH/DEBIT/CHK	3822.95

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit To:  
Box 280, Hwy 9 South  
#1 Rocky Mountain Way  
Yorkton, Sask. S3N 2V7  
Tel: (306) 783-8508  
Fax: (306) 786-7880

## INVOICE

Ship to:

Invoice to:

Branch		
YORKTON		
Date	Time	Page
06/07/21	15:00:09 (O)	01
Account No.	Phone No.	Reference No.
Ship Via	Purchase Order	
	?	
Credit Card No.	Salesperson	
	688	

### Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold ---
153123	3450	FLEXI-COIL TA	X G-50-A000-1079442		
	3450				

\*\*Here at Rocky for your protection and ours we are wiping down every piece of equipment before and after we repair it.

SEGMENT# 1 C 03513 NA 05/29/21 05/29/21

REPAIR CAUSE OF POOR COMMUNICATION

COMPLAINT:

May 28/ 2021

Customer complaining of communication issue to the air cart.

CAUSE:

terminator missing

CORRECTION:

May 28/ 2021

Traced schematics, and tested continuity on wires to the cart relay to get them plugged into the proper positions but, could not find find it. Testing for power but, did not have power to energizer the alternator to start it charging. Jumped power to the post and confirmed that the alternator will charge.

There was a hydraulic issue as well as the cart fan would not run more than about 100 rpm.

JR- may 31-travel out to customers location

found unit and fired up tractor and monitor and no remotes installed on monitor

engage atom jet and fan was barely spinning

was able to rig up some fittings to hook up flow meter to the tractor

tested flow and was up to 20GPM revved up

put hoses back on for fan and revved tractor up and was

CONTINUED ON PAGE 02

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

**Please Remit To:**  
 Box 280, Hwy 9 South  
 #1 Rocky Mountain Way  
 Yorkton, Sask. S3N 2V7  
 Tel: (306) 783-8508  
 Fax: (306) 786-7880

## INVOICE

Ship to:  
  
Invoice to:

Branch YORKTON		
Date 06/07/21	Time 15:00:09 (O)	Page 02
Account No.	Phone No.	Reference No.
Ship Via	Purchase Order ?	
Credit Card No.	Salesperson 688	

### Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold ---
-------------	-----	---------	---------------	-----	----------

153123	3450	FLEXI-COIL TA	X G-50-A000-1079442		
	3450				

spinning faster but cant seed anything with no monitor  
 tested for power getting to the cart and had voltages  
 except on one pin was suppose to be twelve volts and did  
 not have it  
 checked out harness and was missing the terminator in the  
 cab  
 need that terminator to complete the circuit will not be  
 communicating without it  
 got parts located for customer as we did not have one  
 customer is going to get the parts himself and let us know  
 how he makes out

FREIGHT	FREIGHT	1	20.00		20.00
13927	TERMINAL	1 M	156.00		156.00
			PARTS		176.00
			LABOR		1065.00
13500059			SEGMENT TOTAL==>		1241.00

SEGMENT# 2 C 03513 NA	05/29/21	05/29/21	
TRAVEL - 2 TRIPS - 2 SEPARATE ISSUES			
			LABOR
13500059			839.85
			SEGMENT TOTAL==>
			839.85

SEGMENT# 3 C 03513 NA      05/29/21 06/04/21  
 REPAIR CAUSE OF NO FAN SPEED  
COMPLAINT:  
 no fan speed  
CAUSE:  
 fan motor failed, atom jet just doesnt quite have enough  
 flow to run a VR cart  
CORRECTION:

CONTINUED ON PAGE 03

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ \_\_\_\_\_ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



# ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

## INVOICE

Please Remit To:  
 Box 280, Hwy 9 South  
 #1 Rocky Mountain Way  
 Yorkton, Sask. S3N 2V7  
 Tel: (306) 783-8508  
 Fax: (306) 786-7880

Ship to:  
 Invoice to:

[Redacted]

[Redacted]

Branch <b>YORKTON</b>		
Date 06/07/21	Time 15:00:09 (0)	Page 04
Account No.	Phone No.	Reference No.
Ship Via	Purchase Order	
Credit Card No.	Salesperson 688	

### Description of Work and Parts

STK#/FLEET#	HRS	FIN/RIN	WARRANTY DATE	HRS	Fold ---
153123	3450	FLEXI-COIL TA	X G-50-A000-1079442		
	3450				
		flow to run a VR cart			
		cleaned up all tools and traveled back to shop			
				LABOR	850.00
				SEGMENT TOTAL==>	850.00

SEGMENT# 4 C CUST NA 05/29/21  
 \*\*\*\*\*SERVICE LINES\*\*\*\*\*  
 PAID BY MASTERCARD  
 CLOSED BY EM  
 JUNE 7, 2021

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS	176.00
LABOR	2754.85
SHOP SUPPLIES	200.00
SUB TOTAL==>	3130.85
GST 797594660	156.54
VISA	3287.39

MC#01640J

Land Description: Sec Twsp R M

I hereby certify the g  
 the operation of my fa

Date

ROCKY MTN EQUIP-YORKTO  
 BOX 280, HWY 9 & 10 S3N2V7  
 YORKTON SK  
 20269233  
 GW2026923301

\*\*\*\* PURCHASE \*\*\*\*  
 06-07-2021 17:57:21 M  
 Acct # \*\*\*\*\*  
 Card Type MC

Trace # 7716  
 Inv. # 8367  
 Auth # 01640J  
 CVD Resp Y

Total \$3,287.39  
 (001) APPROVED-THANK YOU

Retain this copy for your records  
 Customer copy

I hereby authorize the above work to be done at  
 above machine for purposes of testing, inspection  
 satisfactory with you and until paid in full, an expro  
 of repairs thereto. It is understood that the compo  
 placed with them for storage, sale, repair or while being tested.

(signature)

(date)

(signature)

(date)

being the total