



Vehicle Standards and Inspection

Heavy Truck Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A268590

Station #: 70243

Station Name: K & D Truck Parts Ltd

Technician #: 91795

Technician Name: Colby Lyman

Signing Officer #: 92310

Signing Officer Name: Ken Ward

Customer Details:

Name: DOWN TO EARTH FENCING

Address:

Saskatchewan,

Inspection Completed Date: 05Mar2026

Inspection Expiry Date: 31Mar2027

Vehicle Details:

VIN: 1M2AX09Y3DM016339

Odometer Reading: 520981 km

Year: 2013

Vehicle Make/Model: MACK/HEAVY VEHICLE

Plate:

Jurisdiction:

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Heavy Truck Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70243

Station Name: K & D Truck Parts Ltd

Technician #: 91795

Technician Name: Colby Lyman

Signing Officer #: 92310

Signing Officer Name: Ken Ward

Customer Details:

Name: DOWN TO EARTH FENCING

Address:

Saskatchewan

Vehicle Details:

VIN: 1M2AX09Y3DM016339

Odometer Reading: 520981 km

Year: 2013

Vehicle Make/Model: MACK HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
		x		Horn Operation (5)	CITY HORN IS INOPERTAIVE
x				Mirrors (8)	
		x		Windshield Wipers/Washers (8)	WINDSHIELD WIPERS BLADES ARE DAMAGED AND DO NOT CLEAN WINDSHIELD. -REPLACED WINDSHIELD WIPER BLADES
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	

x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	
x				Fire Extinguisher/Hazard Kit (5)	
		x		Seats/Seat Belts/SRS (8)	DRIVER SIDE SEATBELT DOES NOT RETRACT. -REPLACED DRIVER SIDE SEATBELT
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	BOTH REAR TAIL LIGHTS MORE THAN 50% BURNT OUT -REPLACED TAIL LIGHTS
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
		x		Cab/Hood Safety Catches (8)	LEFT LOWER HOOD CRACKED
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	

x				Drive Belts (1)	
---	--	--	--	-----------------	--

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	AUDIBLE AIR LEAK WHEN SERVICE APPLIED, LEFT FRONT DRIVE AXLE SLACK ADJUSTER ADJUSTING PIN MISSING -REPLACED SLACK ADJUSTER ADJUSTING PIN, AND FIXED AIR LEAK
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35 degrees • Brake Stroke: 1 1/2 in

Wheel2-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35 degrees • Brake Stroke: 1 1/2 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 24 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 24 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 23 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 23 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 23 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 24 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 21 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 21 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A268590

Inspection Completed Date: 05Mar2026

(65) Drivers Wiper rubber torn off, Pass don't wipe well + change both as per if (.25)

(54) Air leaks when brakes applied - Diag - (1)

(22) Drivers seat belt mechanism doesn't return and makes a lot of sounds when moving - Replace - 1

(31) Both rear hall lights more than 50% out - Replace both - .5

(54) LR Drive adjusting pin missing - install new and set slack - .5

Warnings

(63) no city horn - Diag/repair - (1)

notes

(7) Speedo in MPH - Oil leak at crankcase after alarm

(40) LR lower part of head cracked, sensor base of trans leaking