

**YOUNG'S  
EQUIPMENT**

Box 430 • Highway #6 South  
Raymore, SK S0A 3J0  
Phone: 306-746-2288 • Fax: 306-7464559  
www.youngs.ca

**CASE II**  
AGRICULTURE

Regina	306-565-2405
Assiniboia	306-642-5991
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch RAYMORE		
Date 05/18/22	Time 14:54:18 (O)	Page 05
Account # BARBI001	Phone # 3065692484	Inv # W06685
Ship Via		Purchase Order #
Tax ID #		
		Salesperson S87

**SERVICE INVOICE**

STK#/FLEET#

UD2034 Air Tank/Cart  
ADX3430

HRS PIN/EIN  
X CBJ0019457

WARRANTY DATE HRS

is cam 1 and tank 2 is cam 2 and so on.

A-TCK44	CAB CAM IMP KIT	1 N	192.98	192.98
FRTCP	FREIGHT-CASE	1	20.00	20.00
			PARTS	212.98
			LABOR	575.05
11008007	SEGMENT TOTAL==>			788.03

SEGMENT# 9 C INTER QC 04/29/22 04/29/22

Young's Complimentary QuickCheck Inspection

CORRECTION:

TS April 29/22- Took tractor out to yard and unfolded the drill, started looking at what needs to be done looked up parts availability on cylinder seal kits.

SEGMENT#10 C 74009 N/A 04/29/22 05/02/22

CLEAN OUT METERING VALVES

CORRECTION:

bo - may 4 - remove each of the 3 valves attached to the metering drives, disassemble and clean, clean up the spool valves as they are scratched up, verify each moves free - the center assy was installed backwards and that spool was worse then the rest, was stuck in the bore, was able to get it freed up

- reassemble and reinstall on the unit  
- remove , disassemble and clean the system filter, reinstall

9617873	O-RING	3	2.23	6.69
			PARTS	6.69
			LABOR	227.85
11008007	SEGMENT TOTAL==>			234.54

CONTINUED ON PAGE 06

\* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

\* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

\* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

\* An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

\* Estimates are for the items specifically identified in the estimate only, and are non-binding.

GST # 894516046

*Leading The Way In A Thriving Agricultural Community!*

X

Received By

**Thank You!**  
We Appreciate Your Business



**YOUNG'S  
EQUIPMENT**

Box 430 • Highway #6 South  
Raymore, SK S0A 3J0  
Phone: 306-746-2288 • Fax: 306-7464559  
www.youngs.ca

**CASE II**  
AGRICULTURE

Regina	306-565-2405
Assiniboia	306-642-5991
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch RAYMORE		
Date 05/18/22	Time 14:54:18 (O)	Page 03
Account # BARBI001	Phone # 3065692484	Inv # W06685
Ship Via		Purchase Order #
Tax ID #		
		Salesperson S87

**SERVICE INVOICE**

STK#/FLEET#

UD2034

Air Tank/Cart

ADX3430

HRS PIN/EIN

X CBJ0019457

WARRANTY DATE

HRS

of place

bo - may 7 - remove the tape holding the seal up, seal

seems solid

- reinstall the metering auger

- clean up the garbage from the lid seals

CA-229

SEAL

1 N

72.21

72.21

BLET

contact adhesiv

1

15.00

15.00

2593992

SEAL

4 N

107.64

430.56

8901

SEAL, RUBBER

1 N

208.46

208.46

PARTS

711.23

LABOR

635.50

SUBLET

15.00

11008007

SEGMENT TOTAL==>

1361.73

SEGMENT# 6 C INTER N/A

04/29/22

CHECK/FIX OIL LEAK AT FLOW CONTROL VALVE

SEGMENT# 7 C INTER N/A

04/29/22 05/02/22

CHECK ALL LIGHTS

CORRECTION:

bo - may 7 - remove the light, verify power at the harness,

found the terminals are pulled out of the wiring,

- went to get a new light, they're too far away,

- disassemble and repair the light, reinstall and verify

function

1004

BULB

1

.98

.98

432601A1

LENS

1 N

24.25

24.25

PARTS

25.23

LABOR

136.40

11008007

SEGMENT TOTAL==>

161.63

CONTINUED ON PAGE 04

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

GST # 894516046

*Leading The Way In A Thriving Agricultural Community!*

X

Received By

**Thank You!**

We Appreciate Your Business





Box 430 • Highway #6 South  
Raymore, SK S0A 3J0  
Phone: 306-746-2288 • Fax: 306-7464559  
www.youngs.ca



Regina 306-565-2405  
Assiniboia 306-642-5991  
Chamberlain 306-638-4516  
Davidson 306-567-3074  
Moose Jaw 306-694-1800  
Watrous 306-946-3387  
Weyburn 306-842-2629  
Windthorst 306-224-2110

Ship To:

Invoice To:

Branch RAYMORE		
Date 05/18/22	Time 14:54:18 (O)	Page 01
Account # BARBI001	Phone # 3065692484	Inv # W06685
Ship Via		Purchase Order #
Tax ID #		
CUSTOMER COPY		Salesperson S87

### SERVICE INVOICE

STK#/FLEET#

UD2034

Air Tank/Cart  
ADX3430

HRS PIN/EIN

X CBJ0019457

WARRANTY DATE

HRS

SEGMENT# 1 C INTER N/A

04/29/22 05/02/22

FIX/REPLACE HOSE IF NEEDED

CORRECTION:

bo - may 2 - r/r the damaged lower product hose and route better

-MAY3-R/R ANOTHER PRODUCT LINE

112BK-250

2.5" SOLID BLK

44

3.87

170.28

PARTS

170.28

LABOR

251.10

11008007

SEGMENT TOTAL==>

421.38

SEGMENT# 2 C INTER N/A

04/29/22 05/02/22

WRAP HOSES IN RUBBER OR SOMETHING TO KEEP THEM FROM RUBBING

CORRECTION:

bo - may 3 - shorten up and reroute the product runs  
- raise the cradle, cover the lower hose that will still rub in a piece of another hose  
- zip tie up, put a couple pieces of seed run overtop the the hyd/electrical cradle edges

5505-58-01

HOSE 1 1/8"

5

1.44

7.20

76-2890

14" CABLE TIE

20

.46

9.20

PARTS

16.40

LABOR

457.25

11008007

SEGMENT TOTAL==>

473.65

SEGMENT# 3 C INTER N/A

04/29/22 05/03/22

CHECK TIRE PRESSURES

CORRECTION:

bo - may 3 - top up the front tires, lower down the rear

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.  
• It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.  
• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.  
• An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.  
• Estimates are for the items specifically identified in the estimate only, and are non-binding.

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!  
We Appreciate Your Business



**YOUNG'S  
EQUIPMENT**

Box 430 • Highway #6 South  
Raymore, SK S0A 3J0  
Phone: 306-746-2288 • Fax: 306-7464559  
www.youngs.ca

**CASE II**  
AGRICULTURE

Regina	306-565-2405
Assiniboia	306-642-5991
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch RAYMORE		
Date 05/18/22	Time 14:54:18 (O)	Page 06
Account # BARBI001	Phone # 3065692484	Inv # W06685
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson 887

**SERVICE INVOICE**

STK#/FLEET#

UD2034

Air Tank/Cart

ADX3430

HRS PIN/EIN

X CBJ0019457

WARRANTY DATE

HRS

SEGMENT#11 C 74009 N/A

04/29/22 05/02/22

REPAIR BIN LEVEL SENSORS

CORRECTION:

SO May 11/22 - Used simulator to test lower sensor and found tank one and three bin full sensors were no good.

On cart and fan and checked for leaks and found spool was leaking at motor.

11008007

LABOR

302.25

SEGMENT TOTAL==>

302.25

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

PARTS 1142.81

LABOR 2813.25

SUBLET 15.00

shop supplies 200.00

SUB TOTAL==> 4171.06

GST 5% 208.59

TOTAL CREDIT CARD 4379.65

095251

XXXXXXXXXXXXXXXXXX

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

GST # 894516046

*Leading The Way In A Thriving Agricultural Community!*

X

Received By

**Thank You!**

We Appreciate Your Business



**YOUNG'S  
EQUIPMENT**

Box 430 • Highway #6 South  
Raymore, SK S0A 3J0  
Phone: 306-746-2288 • Fax: 306-7464559  
www.youngs.ca

**CASE II**  
AGRICULTURE

Regina	306-565-2405
Assiniboia	306-642-5991
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch RAYMORE		
Date 05/18/22	Time 14:54:18 (O)	Page 02
Account # BARBI001	Phone # 3065692484	Inv # W06685
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson S87

**SERVICE INVOICE**

STK#/FLEET#

UD2034

Air Tank/Cart

ADX3430

HRS PIN/EIN

X CBJ0019457

WARRANTY DATE

HRS

slightly, wrote the pressures on the rims

11008007

LABOR

80.60

SEGMENT TOTAL==>

80.60

SEGMENT# 4 C INTER N/A

04/29/22 05/03/22

GREASE

CORRECTION:

bo - may 3 - grease the unit, pull the wheel and center  
castor pivot caps off and grease in there as well

bo - may 4 - clean up tools, get more segments made for  
additional stuff the customer wants done

LABOR

147.25

11008007

SEGMENT TOTAL==>

147.25

SEGMENT# 5 C INTER N/A

04/29/22 05/02/22

CHECK ALL RUNS - RESEAL IF NEEDED

CORRECTION:

bo - may 2 - run the unit, lower the distribution, the  
lower seals should be changed

- run the fan, start checking for leaks - metering augers  
are missing, will have to wait till they show up

bo - may 3 - reinstall the metering augers, lift back up  
the distribution

bo - may 5 - lower the manifolds, remove the damaged seal  
and clean up the surface, went to install the gasket,  
there's no adhesive, chads gonna get some for tomorrow  
morning

bo - may 6 - install the new lower seal, r/r the 2 tank lid  
seals and

one tank seal, reinstall the other tank lid seal that's out

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

• It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

• An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

• Estimates are for the items specifically identified in the estimate only, and are non-binding.

GST # 894516046

*Leading The Way In A Thriving Agricultural Community!*

Received By

**Thank You!**  
We Appreciate Your Business



**YOUNG'S  
EQUIPMENT**

Box 430 • Highway #6 South  
Raymore, SK S0A 3J0  
Phone: 306-746-2288 • Fax: 306-7464559  
www.youngs.ca

**CASE II**  
AGRICULTURE

Regina	306-565-2405
Assiniboia	306-642-5991
Chamberlain	306-638-4516
Davidson	306-567-3074
Moose Jaw	306-694-1800
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch RAYMORE		
Date 05/18/22	Time 14:54:18 (O)	Page 04
Account # BARBI001	Phone # 3065692484	Inv # W06685
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson 887

**SERVICE INVOICE**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
UD2034		X CBJ0019457		
Air Tank/Cart ADX3430				

SEGMENT# 8 C INTER N/A 04/29/22 05/02/22

CHECK OPERATION OF ALL CAMERAS

CORRECTION:

bo - may 2 - operate the unit, cam 1 isn't working  
- swap harnesses at the front of the tank - cameras  
themselves work fine its the monitor or harnesses  
found a taped up portion of the front of the drill  
harness, open it up, the harness has been damaged, remove  
the insulation, no actual wire damage, tape back up  
- reposition the harness into the connector so its not  
exposed  
- found that there's a extra wire extension in the cab,  
wired cam1 to that and wire in the front cam at the tank to  
the same harness, - verify operation  
- zip tie up the front drill harness  
bo - may 5 - cam 1 was intermittent while coming into the  
shop, attempt a wiggle test - inconclusive  
- notice that cam 3 is flashing, wiggle test points to the  
damaged harness at the front of the drill, cant pinpoint a  
specific wire, it may be interference because of the  
damaged coating, tape up each wire individually, retest -  
still poor, going to have to order a harness  
bo - may 6 - order the harnesses, the single cross tillage  
isn't available, ordered the whole setup from monitor to  
tank, wasn't bad of a price  
TS May 10/22- Ran new camera harness over the drill and  
plugged cameras in to make sure cable was the issue. It was  
removed old camera harnesses, installed and ran new  
harness, tied up harness and set the cameras so that tank 1

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

X

Received By

GST # 894516046

*Leading The Way In A Thriving Agricultural Community!*

**Thank You!**  
We Appreciate Your Business