



Box 430 • Highway #6 South
Raymore, SK S0A 3J0
Phone: 306-746-2288 • Fax: 306-7464559
www.youngs.ca



Regina 306-224-2110
Assiniboia 306-694-2110
Chamberlain 306-694-2110
Davidson 306-694-2110
Moose Jaw 306-694-2110
Watrous 306-946-2110
Weyburn 306-842-2110
Windthorst 306-224-2110

Ship To:

Invoice To:

Branch RAYMORE		
Date 05/18/22	Time 14:53:53 (O)	Page 06
Account # BARBI001	Phone # 3065692484	Inv # W06684
Ship Via		Purchase Order #
Tax ID #		
		Salesperson S87

SERVICE INVOICE

STK#/FLEET#

UD2113 Air Drill
ATX400

HRS PIN/EIN
X Y8S003443

WARRANTY DATE HRS

TS- Went to each tower and inspected the blockage wiring.
If the wiring was damaged before the connector I cut the
wires off at the loom and cut loom back and put new female
pins on wires then reinstalled in the connector for sensor.
If wiring was damaged after connector on sensor side i left
it and never attempted to fix due to short wires. Customer
said he was happy if a few worked on each tower.

TERMINAL

37

8.94

330.78

PARTS

330.78

LABOR

685.10

SEGMENT TOTAL==>

1015.88

SEGMENT# 9 C 74012 QC

04/29/22

Young's Complimentary QuickCheck Inspection
Do a more detailed quick check inspection

***** WORK ORDER TOTALS *****

PARTS

7220.14

LABOR

12536.40

shop supplies

200.00

SUB TOTAL==>

19956.54

GST 5%

997.96

TOTAL CREDIT CARD

20954.50

095251

XXXXXXXXXXXXXXXXXX

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 430 • Highway #6 South
Raymore, SK S0A 3J0
Phone: 306-746-2288 • Fax: 306-746-4559
www.youngs.ca



Regina 306-224-2111
Assiniboia 306-224-2111
Chamberlain 306-224-2111
Davidson 306-224-2111
Moose Jaw 306-224-2111
Weyburn 306-224-2111
Windsor 306-224-2111

Ship To:

Invoice To:

Branch RAYMORE		
Date 05/18/22	Time 14:53:53 (O)	Page 02
Account # BARBI001	Phone # 3065692484	Inv # W06684
Ship Via		Purchase Order #
Tax ID #		
		Salesperson S87

SERVICE INVOICE

STK#/FLEET#

UD2113

Air Drill

ATX400

HRS PIN/EIN

X Y8S003443

WARRANTY DATE

HRS

-One tower had a slight leak on the top seal, removed cover and was able to clean seal and get it to stop leaking.

HS36	HOSE CLAMP	1	1.13	1.13
K112BK-250	2.5" SOLID BLK	78	3.87	301.86
V1180B-16	1" BLACK	6	1.17	7.02
	PARTS			310.01
	LABOR			1091.20
	SEGMENT TOTAL==>			1401.21

SEGMENT# 3 C 74012 N/A

04/29/22 05/03/22

CHECK ALL LIGHTS

CORRECTION:

bo - may 7 - rr both signal lights, tie up the harnesses, verify function

87564157	LIGHT, WARNIG	2 N	132.98	265.96
	PARTS			265.96
	LABOR			199.95
11008007	SEGMENT TOTAL==>			465.91

SEGMENT# 4 C 74012 N/A

04/29/22 05/03/22

CHECK TIRE PRESSURES

CORRECTION:

TS-looked up tire inflation chart on Etim under ops manual. Checked and adjusted all tires on the drill and wrote the correct psi for each tire on the rim.

TS May 5/22- Had one main tire go flat on the drill after adjusting pressures, Filled tire back up to spec, and found the valve stem was leaking a bit, tightened up valve and seemed to stop will check pressure again tomorrow to see if it went down or not.

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

• It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

• An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

• Estimates are for the items specifically identified in the estimate only, and are non-binding.

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

X

Received By

Thank You!
We Appreciate Your Business



Box 430 • Highway #6 South
Raymore, SK S0A 3J0
Phone: 306-746-2288 • Fax: 306-7464559
www.youngs.ca



Regina 306-224-2110
Assiniboia 306-224-2110
Chamberlain 306-224-2110
Davidson 306-224-2110
Moose Jaw 306-224-2110
Watrous 306-224-2110
Weyburn 306-224-2110
Windthorst 306-224-2110

Ship To:

Invoice To:

Branch RAYMORE		
Date 05/18/22	Time 14:53:53 (O)	Page 01
Account # BARBI001	Phone # 3065692484	Inv # W06684
Ship Via	Purchase Order #	
Tax ID #		
CUSTOMER COPY		Salesperson 887

SERVICE INVOICE

STK#/FLEET#

UD2113

Air Drill
ATX400

HRS PIN/EIN

X Y8S003443

WARRANTY DATE

HRS

SEGMENT# 1 C 74012 N/A

04/29/22 05/02/22

CHECK TIPS - REPLACE AS NEEDED

CORRECTION:

TS May 2/22- Lifted shanks, crawled under drill and looked at each tip, marked them then got chad to look up and

ordered needed tips

May 10/22 - moved drill inside

TS May 10/11 2022- Changed 6 tips on the RH side of drill, replaced one hose going to tip

jd may 10 22 started changing tips

jd may 11 kept changing tips also taped any rubbing hoses

helped look for air leaks

bo - may 11 - tighten up both end shank mount plates as they're loose

CCGCA0	LEFT GRN SIDEBN	7 N	189.00	1323.00
CCGCB0	RIGHT GRN SIDEB	6 N	189.00	1134.00
FRTCP	FREIGHT-CASE	1	100.00	100.00
	PARTS			2557.00
	LABOR			593.65
11008007	41304101	SEGMENT TOTAL==>		3150.65

SEGMENT# 2 C 74012 N/A

04/29/22 05/03/22

CHECK HOSES - REPLACE AS NEEDED - FIX SO THEY DONT RUB

CORRECTION:

jd may 11 22 helped tanner replace hoses and check for leaks/rubbing and pinch points

TS May 11/22- Replaced 3 main product hoses on the drill, ran the fan on air cart and checked all towers and hoses for leaks.

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

- It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
- Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
- An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
- Estimates are for the items specifically identified in the estimate only, and are non-binding.

X

Received By

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 430 • Highway #6 South
Raymore, SK S0A 3J0
Phone: 306-746-2288 • Fax: 306-746-4559
www.youngs.ca



Regina 306-
Assiniboia 306-
Chamberlain 306-6
Davidson 306-56
Moose Jaw 306-694
Watrous 306-946-5
Weyburn 306-842-26
Windthorst 306-224-211

Ship To: .

Invoice To

Branch RAYMORE		
Date 05/18/22	Time 14:53:53 (O)	Page 03
Account # BARBI001	Phone # 3065692484	Inv # W06684
Ship Via		Purchase Order #
Tax ID #		
		Salesperson S87

SERVICE INVOICE

STK#/FLEET#

UD2113

Air Drill

ATX400

HRS PIN/EIN

X Y8S003443

WARRANTY DATE

HRS

LABOR

176.70

11008007

SEGMENT TOTAL==>

176.70

SEGMENT# 5 C 74012 N/A

04/29/22 05/03/22

GREASE

CORRECTION:

6- greased drill wings, wheel hubs/ towers, and each
hank.

77014BUYUS

MP GREASE LITHM

RETAIL

4.65

3

3.99

11.97

PARTS

11.97

LABOR

217.00

11008007

SEGMENT TOTAL==>

228.97

SEGMENT# 6 C 74012 N/A

04/29/22 05/02/22

CHECK AND REPLACE PACKER BEARINGS AS NEEDED AND PACKERS

COMPLAINT:

bo - may 12 - help assemble packers, replace rubbers

CORRECTION:

TS- lifted packer wheel assembly slightly off ground with
forklift, checked bearings and spun assembly, moved across
the drill checking them all. Found them all to be good and
spun freely with no play.

jd-may 9th 22 helped scott with packers helped tanner also
with packers

SO May 9/22 - removed nuts, Used packer remove tool to
removed outer packer. Torched off bearing. Used puller
tool to remove next packer wheel. Removed rubbers off of
two packer wheels. Cleaned wheels. Used bearing grease
and installed two new rubber wheels with wheel install

CONTINUED ON PAGE 04

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

X

Received By

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 430 • Highway #6 South
Raymore, SK S0A 3J0
Phone: 306-746-2288 • Fax: 306-7464559
www.youngs.ca



Regina	306
Assiniboia	306
Chamberlain	306-6
Davidson	306-56
Moose Jaw	306-694
Watrous	306-946-3
Weyburn	306-842-26
Windthorst	306-224-2110

Ship To:

Invoice To:

Branch RAYMORE		
Date 05/18/22	Time 14:53:53 (O)	Page 05
Account # BARBI001	Phone # 3065692484	Inv # W06684
Ship Via		Purchase Order #
Tax ID #		
		Salesperson 887

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
UD2113		X Y8S003443		
Air Drill				
ATX400				

Disconnected hoses and removed pins on one shank cylinder and the other two wing cylinders. Put all three cylinders on a pallet and brought into shop.

SO May 7/22 - Removed rod bolts on shank lift cylinder. Drained oil out. Removed end cap and rods. Removed piston out of bore. Removed piston nut and cleaned up all parts.

Replaced seal and bushing on end cap. Installed on rod and piston on rod. Installed in bore and installed bolts and end cap. Tightened bolts. Used forklift to lift wing cylinder onto bench. Removed end cap and let oil drain out. Removed rod bolts. Removed end cap and piston.

Cleaned all parts and replaced seals. Installed piston end cap and bore. Installed rod bolts. Installed end cap and tightened bolts. Used forklift to move cylinder. Did the same thing for the second wing lift cylinder.

SO May 9/22 - installed opener lift cylinder. Hooked up hoses.

SO May 10/22 - installed LH wing lift cylinder on drill

EHCOIL	EHC CHARGE	40	.05	2.00
77400001US	ULTRACTION BULK	40	4.97	198.80
87403963	KIT, SEALS	2 N	351.00	702.00
9674V2	CYL KIT 4 MONAR	1 N	168.95	168.95
	PARTS			1071.75
	LABOR			1543.80
11008007	SEGMENT TOTAL==>			2615.55

SEGMENT# 8 C 74012 N/A 04/29/22 05/03/22

CHECK BLOCKAGE MONITORS

CORRECTION:

jd may 10 22 helped tanner with cameras

CONTINUED ON PAGE 06

I hereby

authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 430 • Highway #6 South
Raymore, SK S0A 3J0
Phone: 306-746-2288 • Fax: 306-7464559
www.youngs.ca



Regina	306
Assiniboia	306
Chamberlain	306-6
Davidson	306-56
Moose Jaw	306-694
Watrous	306-946-3
Weyburn	306-842-26
Windthorst	306-224-211

Ship To: .

Invoice

Branch RAYMORE		
Date 05/18/22	Time 14:53:53 (O)	Page 04
Account # BARBI001	Phone # 3065692484	Inv # W06684
Ship Via		Purchase Order #
Tax ID #		
		Salesperson 887

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
UD2113		X Y8S003443		
Air Drill				
ATX400				

tool. Installed packer. Installed spacer and cleaned shaft and put on antisieze. Installed new bearing. Had to wait for one spacer. Removed opposite end and cleaned surface. Torched off bearing. Installed new bearing and reassembled. Installed nuts and tightened down.

SO May 10/22 - removed all packer wheel assemblys. Removed 6 nuts and torched off all bearings on shaft. Found 3 bearings were installed backwards in holders.

SO May 11/22 - torched off last spacer and bearing.

Removed bearings from holders. Cleaned up tools and bay jd may 12 22 helped put packers together cleaned up floor and garbage

SO May 12 - installed the rest of packer bearings and wheels. Installed 4 new rubbers on packer wheels. Antisiezed shafts. Installed packer wheels on drill.

AABP208	PILLOW BLOCK	1 M	21.35	21.35
BEIP208	HOUSING PILLOW	1 M	30.42	30.42
FRTCP	FREIGHT-CASE	1	60.00	60.00
HAR08-03	3/16 KEY S	1	1.72	1.72
1206-07	5/8" LOCK NUT	2	1.18	2.36
6613	BEARING	19 S	70.03	1330.57
7215	TYRE/TIRE	9 M	136.25	1226.25
	PARTS			2672.67
	LABOR			8029.00
11008007	SEGMENT TOTAL==>			10701.67

SEGMENT# 7 C 74012 N/A 04/29/22 05/02/22

RESEAL CYLINDERS IF NEEDED

CORRECTION:

SO May 6/22 - Lowered shanks and wings to the ground.

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

GST # 894516046

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business