

CRESTVIEW CHRYSLER

Crestview Chrysler Dodge Jeep Ram
601 Albert Street • Regina, SK • S4R 2P4
Phone: (306) 525-5411 • Fax: (306) 359-0077
www.crestviewchrysler.ca

INVOICE ORIGINAL

Work Order

#60139

Wheaton Chevrolet Ltd.*

January 11, 2024

Svc. Adv Kells, Ryan

Cust. Ph. (306) 543-1555

Tag# 0139

Page 1 of 2

02/15/2024 11:24:47

	Year: 2016 Veh Id: 14989 Unit #: 16T474 Make: RAM License #: Model: 1500 Diesel (3.0L) Odo. In: 175,178 Colour: Pwq/pearl_white_p Odo. Out: 175,183 V.I.N.#: 1C6RR7NM9GS302233 Next Service: Date In: 01/11/2024 In Service Date: 05/06/2016 Out: 02/15/2024 Cases: 3 Ext. War - - (mo/) - D: \$0.00 Promised Time: 01/24/2024 05:00:00 PM Call When Ready: No
--	---

Case: 2 Removal & Installation ENGINE ASSEMBLY V6,3.0L Eng,4WD
Removal & Installation ENGINE ASSEMBLY ENGINE ASSEMBLY - Removal & Installation Where Skid Plate interferes add

Quantity	Description/Correction	Price	Total
10.00	68232237CB - \$T6 5W40-5W40 TURBO DIESEL	\$8.95	\$89.50
1.00	68492616AA - FILTER	\$39.00	\$39.00
1.00	05158048AI - ENGINE	14,240.00	14,240.00
3.00	68175339AC - \$ANTIFREEZ-COOLANT	\$34.45	\$103.35
		\$2,418.00	\$2,418.00

- Tech Cause: Removed long block and swapped over egr delete parts and all related components
- Tech Comments: Filled cooling system, inspected oil level and filled transmission fluid. Test drove with no issues found. Inspected for leaks on return
- Completed by Technician number:
Scot
- Core Charges - 05158048AI \$999.99 \$999.99
- Core Return - 05158048AICOR (\$999.99) (\$999.99)

Misc \$0.00 Labour \$2,418.00 Parts \$14,471.8 Prepaid Parts Amt: \$0.00 **Case Total: \$16,889.85**

Case: 3 2014-2019 DS 2014-2020 WK LOSS OF CRAN

Quantity	Description/Correction	Price	Total
		\$0.00	\$0.00

- Tech Cause: Cannot perform update truck is deleted
- Tech Comments: Cannot perform update

CRESTVIEW CHRYSLER

Crestview Chrysler Dodge Jeep Ram
601 Albert Street • Regina, SK • S4R 2P4
Phone: (306) 525-5411 • Fax: (306) 359-0077
www.crestviewchrysler.ca

INVOICE ORIGINAL
Work Order
#60139
Wheaton Chevrolet Ltd.*
January 11, 2024
Svc.Adv Kells, Ryan
Cust.Ph. (306) 543-1555
Tag# 0139

Page 2 of 2
02/15/2024 11:24:47

• Completed by Technician number:
Scot

Misc \$0.00 Labour \$0.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 **Case Total: \$0.00**

Case: 4 Added Operation: Replace battery - Tech Cause: Replaced battery - Tech Comments: Replaced battery

Quantity	Description/Correction	Price	Total
1.00	BAAH8800AB - BATTERY	\$326.00	\$326.00
		\$97.50	\$97.50

• Tech Cause: Replaced battery
• Tech Comments: Replaced battery
• Completed by Technician number:
Scot

Misc \$0.00 Labour \$97.50 Parts \$326.00 Prepaid Parts Amt: \$0.00 **Case Total: \$423.50**

Shop Supplies and Environmental Charges: \$8.80

Notes



O U T	<small>TERMS: Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order.</small> <small>Any warranties on the product sold hereby are those made by the manufacturer.</small> <small>DISCLAIMER OF WARRANTIES: The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Mopar parts warrants 24 months on defects and workmanship for parts & labour on dealer installed retail date of purchase or the installation date by installer. Any limitation contained herein does not apply where prohibited by law.</small>		Current: [Redacted] Labour: \$2,515.50 Parts: \$14,801.65 Misc: \$5.00 Sub Total: \$17,322.15 G/HST: \$866.13 PST: \$0.00 Tax Adjustment: \$0.00
	Payment Ref: [Redacted]		
	Expiry Date: [Redacted]		
	P/O#: [Redacted]		
	Date: 02/15/2024		
	Signature: _____		
	Payment Type: _____		
	Total: \$18,188.28		