



# BENNETT DUNLOP DRIVING CHANGE

770 Broad St. Regina, SK S4R 8H7  
Phone: 1-306-522-6612 • Fax: 1-306-566-8238  
Toll Free: 1-866-522-6612  
www.bennettdunlopford.com

**FILE**

Promised: 06/11/2020 4:00:00 PM

**\*\* In Progress \*\*** Printed 06/11/2020 04:59 PM



PO  
Fleet #

Cashiered Date:

Page: 1

Tag

## \* Service Invoice Customer Copy \*

SO #: B48333

<b>Customer No:</b> 91191B	<b>Advisor:</b> Cindy	<b>Invoice Date:</b> 06/11/2020	<b>Term:</b> CHARGE
<b>License No</b> 539LTG	<b>Odometer In</b> 279608	<b>Odometer Out</b> 0	<b>Delivery Date</b> 01/01/2009
<b>Year Make</b> 2009 DODGE	<b>Model</b> RAM TRUCK	<b>Model No</b>	<b>Colour</b> UNKNOWN
<b>Vehicle ID No</b> 1D3HV13TX9S758999	<b>Selling Dealer</b>	<b>SO Date</b> 06/08/2020	<b>InServ Date</b> 01/01/2009
<b>Engine Size</b> 5.7L V8 SFI OH		<b>Fleet #</b>	

### Request/Concern

Original

1 GEN

DIAG FOR FRONT END IS LOOSE, WONDERING ALL OVER THE ROAD \$65.00

Type

CSR

Amount

GEN

DIAG FOR FRONT END IS LOOSE, WONDERING ALL OVER THE ROAD \$65.00

CS

121B

65.00

Name

10026B

Est Labour 0.00

Est Parts 0.00

Cause:

26 left lower ball joint, left inner tie rod, both rear lower track bars

Request Total

65.00

### Approved

2 GEN

left lower ball joint loose

GEN

left lower ball joint loose

CS

121B

186.00

### Qty

1 343.04 SP-OR ANA MEV CMS25149 FR L LWR CNTRL ARM

CRO

RETAIL

Price

Ext

343.04

343.04

343.04

HERE IN C/O - MAY NEED TO RETURN

Name

10637B

Est Labour 0.00

Est Parts 0.00

Parts Amount

343.04

Labour Amount

186.00

Labour Discount

27.90

Cause:

left front lower ball joint loose

Request Total

501.14

Correction:

removed and replaced left front lower control arm

### Approved

### PRIVACY STATEMENT

Personal Information is collected in accordance with applicable privacy legislation and is governed by Bennett Dunlop Ford's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Customer Signature \_\_\_\_\_

Date \_\_\_\_\_

GST# R13608527





# BENNETT DUNLOP

## DRIVING CHANGE

770 Broad St. Regina, SK S4R 8H7  
Phone: 1-306-522-6612 • Fax: 1-306-566-8238  
Toll Free: 1-866-522-6612  
www.bennettdunlopford.com

Promised: 06/11/2020 4:00:00 PM

**\*\* In Progress \*\*** Printed 06/11/2020 04:59 PM



Page: 2

PO  
Fleet #

Cashiered Date:

Tag

**\* Service Invoice Customer Copy \***

SO #: B48333

<b>91191B</b>	<b>Advisor:</b> Cindy		<b>Invoice Date:</b> 06/11/2020		<b>Term:</b> CHARGE
	<b>License No</b>	<b>Odometer In</b>	<b>Odometer Out</b>	<b>Delivery Date</b>	<b>Stock No</b>
	539LTG	279608	0	01/01/2009	
	<b>Year Make</b>	<b>Model</b>	<b>Model No</b>	<b>Colour</b>	
	2009 DODGE	RAM TRUCK		UNKNOWN	
<b>Vehicle ID No</b>	<b>Selling Dealer</b>	<b>SO Date</b>	<b>InServ Date</b>	<b>Location</b>	
1D3HV13TX9S758999		06/08/2020	01/01/2009		
<b>Engine Size</b>	5.7L V8 SFI OH		<b>Fleet #</b>		

Request/Concern	Type	CSR	Amount
3 GEN left inner tie rod			
GEN left inner tie rod	CS	121B	186.00
<b>Qty</b>		<b>RETAIL</b>	<b>Price</b>
1 130.74 SP-OR ANA EV800098 INNER TIE ROD END	CRO	130.74	130.74
		<b>Ext</b>	130.74

C/O BIN

Name 10637B

Est Labour 0.00

Est Parts 0.00

Parts Amount 130.74

Labour Amount 186.00

Labour Discount 27.90

Cause: loose left inner tie rod

Request Total 288.84

Correction: removed and replaced left inner tie rod

Approved

4 TALIGN Truck Alignment			
TALIGN Truck Alignment	CS	121B	149.99

Name 10637B

Est Labour 149.99

Est Parts 0.00

Cause: aliugnemnt

Request Total 149.99

Correction: Performed truck alignment

Approved

5 GEN both front C/V axles			
GEN both front C/V axles	CS	121B	496.00

### PRIVACY STATEMENT

Personal Information is collected in accordance with applicable privacy legislation and is governed by Bennett Dunlop Ford's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Customer Signature \_\_\_\_\_ Date \_\_\_\_\_

GST# R136085527





# BENNETT DUNLOP

## DRIVING CHANGE

770 Broad St. Regina, SK S4R 8H7  
Phone: 1-306-522-6612 • Fax: 1-306-566-8238  
Toll Free: 1-866-522-6612  
www.bennettdunlopford.com

Promised: 06/11/2020 4:00:00 PM

**\*\* In Progress \*\*** Printed 06/11/2020 04:59 PM



Page: 3

PO  
Fleet #  
Tag

Cashiered Date:

### \* Service Invoice Customer Copy \*

SO #: B48333

<b>Customer No:</b> 91191B	<b>Advisor:</b> Cindy	<b>Invoice Date:</b> 06/11/2020	<b>Term:</b> CHARGE
<b>License No</b> 539LTG	<b>Odometer In</b> 279608	<b>Odometer Out</b> 0	<b>Delivery Date</b> 01/01/2009
<b>Year</b> 2009	<b>Make</b> DODGE	<b>Model</b> RAM TRUCK	<b>Model No</b> UNKNOW
<b>Vehicle ID No</b> 1D3HV13TX9S758999	<b>Selling Dealer</b> 7	<b>SO Date</b> 06/08/2020	<b>InServ Date</b> 01/01/2009
<b>Engine Size</b> 5.7L V8 SFI OH		<b>Fleet #</b>	<b>Location</b>

#### Request/Concern

Qty	Type	CSR	Amount
		<u>RETAIL</u>	<u>Price</u> <u>Ext</u>
1	189.92 SP-OR ANA 139119 CV FRT L/R AXLE SHAFT	CRO	189.92 189.92 189.92

C/O BIN

1	189.92 SP-OR ANA 139119 CV FRT L/R AXLE SHAFT	CRO	189.92 189.92 189.92
---	---	-----	----------------------

C/O BIN

Name 10637B

Est Labour 0.00

Est Parts 0.00

Parts Amount	379.84
Labour Amount	496.00
Labour Discount	74.40

Cause: both front c/v axles have torn boots - no grease left

Request Total 801.44

Correction: removed and replaced both front axles

#### Approved

6	GEN	right front axle seal ,with c/v axle		
	GEN	right front axle seal ,with c/v axle	CS	121B 31.00

Qty	Type	CSR	Amount
		<u>RETAIL</u>	<u>Price</u> <u>Ext</u>
1	71.17 SP-OR AES 710995 RF AXLE SEAL	CRO	71.17 71.17 71.17

C/O BIN

Name 10637B

Est Labour 0.00

Est Parts 0.00

Parts Amount	71.17
Labour Amount	31.00

#### PRIVACY STATEMENT

Personal Information is collected in accordance with applicable privacy legislation and is governed by Bennett Dunlop Ford's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Customer Signature \_\_\_\_\_ Date \_\_\_\_\_

GST# R136086527





# BENNETT DUNLOP

## DRIVING CHANGE

770 Broad St. Regina, SK S4R 8H7  
Phone: 1-306-522-6612 • Fax: 1-306-566-8238  
Toll Free: 1-866-522-6612  
www.bennettdunlopford.com

Promised: 06/11/2020 4:00:00 PM

**\*\* In Progress \*\*** Printed 06/11/2020 04:59 PM



PO  
Fleet #

Cashiered Date:

Page: 4

Tag

### \* Service Invoice Customer Copy \*

SO #: B48333

91191B	Advisor: Cindy	Invoice Date: 06/11/2020	Term: CHARGE
	License No 539LTG	Odometer In 279608	Odometer Out 0
	Year Make 2009 DODGE	Model RAM TRUCK	Delivery Date 01/01/2009
	Vehicle ID No 1D3HV13TX9S758999	Selling Dealer	SO Date 06/08/2020
	Engine Size 5.7L V8 SFI OH		InServ Date 01/01/2009

#### Request/Concern

**Cause:** leaking right front axle seal  
**Correction:** removed and replaced right front axle seal

Type	CSR	Amount
Labour Discount		4.65
<b>Request Total</b>		<b>97.52</b>

#### Approved

7 GEN both rear lower track bars  
GEN both rear lower track bars

CS 121B 186.00

#### Qty

Qty	Price	Ext
2	112.00	224.00

RETAIL	Price	Ext
112.00	112.00	224.00

C/O BIN

Name 10637B

Est Labour 0.00 Est Parts 0.00

Parts Amount	224.00
Labour Amount	186.00
Labour Discount	27.90

**Cause:** both rear lower track bar bushings shot  
**Correction:** removed and replaced both rear lower track bars

**Request Total 382.10**

#### Approved

9 GEN diag. engine oil leak  
GEN diag. engine oil leak

CS 121B 65.00

#### Qty

Qty	Price	Ext
1	26.91	26.91

RETAIL	Price	Ext
26.91	26.91	26.91

Name 10026B

#### PRIVACY STATEMENT

Personal Information is collected in accordance with applicable privacy legislation and is governed by Bennett Dunlop Ford's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Customer Signature \_\_\_\_\_ Date \_\_\_\_\_

GST# R136086527







# BENNETT DUNLOP DRIVING CHANGE

770 Broad St. Regina, SK S4R 8H7  
Phone: 1-306-522-6612 • Fax: 1-306-566-8238  
Toll Free: 1-866-522-6612  
www.bennettdunlopford.com

Promised: 06/11/2020 4:00:00 PM

**\*\* In Progress \*\***

Printed 06/11/2020 04:59 PM



PO  
Fleet #

Cashiered Date:

Page: 5

Tag

**\* Service Invoice Customer Copy \***

SO #: B48333

91191B	Advisor: Cindy	Invoice Date: 06/11/2020	Term: CHARGE
License No 539LTG	Odometer In 279608	Odometer Out 0	Delivery Date 01/01/2009
Year 2009	Make DODGE	Model RAM TRUCK	Stock No UNKNOWN
Vehicle ID No 1D3HV13TX9S758999	Selling Dealer	SO Date 06/08/2020	InServ Date 01/01/2009
Engine Size 5.7L V8 SFI OH		Fleet #	Location

**Request/Concern**

Est Labour 0.00

Est Parts 0.00

Type

CSR

Amount

**Cause:** added dye to engine oil wash off and road test u/v light test rear main seal leaking

**Request Total**

**91.91**

**Correction:**

**Approved**

10 GEN

diag. trans fluid leak

GEN

diag. trans fluid leak

CS

121B

65.00

**Qty**

						<u>RETAIL</u>	<u>Price</u>	<u>Ext</u>
1	25.11	B6	164 R3700	OIL DYE	CRO	25.11	25.11	25.11

**Name** 10026B

Est Labour 0.00

Est Parts 0.00

**Cause:** added dye to trans fluid, wash off road test u/v light test trans pan gasket leaking, trans cooler lines leaking

**Request Total**

**90.11**

**Correction:**

**Approved**

15 GEN

REPLACE DRIVERS FRONT 2 BROKEN WHEEL STUDS

GEN

REPLACE DRIVERS FRONT 2 BROKEN WHEEL STUDS

CS

121B

62.00

**Qty**

						<u>RETAIL</u>	<u>Price</u>	<u>Ext</u>
2	5.70	SP-OR	ANA 610389	WHEEL LUG STUD	CRO	5.70	5.70	11.40
1	14.00	SP-OR	FR	PARTS FREIGHT SERVIC	CRO	0.00	14.00	14.00
2	3.30	SP-OR	GT SD ACORN 9/16	9/16 7 SPLINE NUT	CRO	3.30	3.30	6.60

**Name** 10637B

**PRIVACY STATEMENT**

Personal Information is collected in accordance with applicable privacy legislation and is governed by Bennett Dunlop Ford's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Customer Signature \_\_\_\_\_ Date \_\_\_\_\_

GST# R136086527





# BENNETT DUNLOP

## DRIVING CHANGE

770 Broad St. Regina, SK S4R 8H7  
Phone: 1-306-522-6612 • Fax: 1-306-566-8238  
Toll Free: 1-866-522-6612  
www.bennettdunlopford.com

Promised: 06/11/2020 4:00:00 PM

**\*\* In Progress \*\*** Printed 06/11/2020 04:59 PM



PO  
Fleet #

Cashiered Date:

Page: 6

Tag

### \* Service Invoice Customer Copy \*

SO #: B48333

91191B	Advisor: Cindy	Invoice Date: 06/11/2020	Term: CHARGE
License No 539LTG	Odometer In 279608	Odometer Out 0	Delivery Date 01/01/2009
Year Make 2009 DODGE	Model RAM TRUCK	Model No	Colour UNKNOWN
Vehicle ID No 1D3HV13TX9S758999	Selling Dealer	SO Date 06/08/2020	InServ Date 01/01/2009
Engine Size 5.7L V8 SFI OH		Fleet #	Location

Request/Concern

Est Labour 0.00

Est Parts 0.00

Type	CSR	Amount
Parts Amount		32.00
Labour Amount		62.00
Labour Discount		9.30
<b>Request Total</b>		<b>84.70</b>

**Cause:** 2 broken wheel studs driver side  
**Correction:** removed and replaced 2 wheel studs

Approved

16	GEN	R&R siezed wheel speed sensor			
	GEN	R&R siezed wheel speed sensor	CS	121B	155.00

Qty

						RETAIL	Price	Ext
1	347.81	SP-OR	ANA BR930808	FR	CRO	347.81	347.81	347.81

ordered ana 7:39 intown.

Name 10637B

Est Labour 0.00

Est Parts 0.00

Parts Amount	347.81
Labour Amount	155.00
Labour Discount	23.25
<b>Request Total</b>	<b>479.56</b>

**Cause:** siezed wheel speed sensor  
**Correction:** removed and replaced right front wheel bearing (included new sensor)

Approved

17	SHUTTLE	Shuttle Ride			
	SHUTTLE	Shuttle Ride	CS	632B	0.00

Name 999B

#### PRIVACY STATEMENT

Personal Information is collected in accordance with applicable privacy legislation and is governed by Bennett Dunlop Ford's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Customer Signature \_\_\_\_\_ Date \_\_\_\_\_





# BENNETT DUNLOP

## DRIVING CHANGE

770 Broad St. Regina, SK S4R 8H7  
Phone: 1-306-522-6612 • Fax: 1-306-566-8238  
Toll Free: 1-866-522-6612  
www.bennettdunlopford.com

Promised: 06/11/2020 4:00:00 PM

**\*\* In Progress \*\*** Printed 06/11/2020 04:59 PM



PO  
Fleet #  
Tag

Cashiered Date:

Page: 7

### \* Service Invoice Customer Copy \*

SO #: B48333

Advisor: Cindy	Invoice Date: 06/11/2020	Term: CHARGE		
License No 539LTG	Odometer In 279608	Odometer Out 0	Delivery Date 01/01/2009	Stock No
Year 2009	Make DODGE	Model RAM TRUCK	Model No	Colour UNKNOWN
Vehicle ID No 1D3HV13TX9S758999	Selling Dealer	SO Date 06/08/2020	InServ Date 01/01/2009	Location
Engine Size 5.7L V8 SFI OH		Fleet #		

#### Request/Concern

Est Labour 0.00

Cause: SHUTTLE  
Correction: SHUTTLE

Est Parts 0.00

Type      CSR      Amount

Request Total      0.00

#### PRIVACY STATEMENT

Personal Information is collected in accordance with applicable privacy legislation and is governed by Bennett Dunlop Ford's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy ([www.ford.ca](http://www.ford.ca)) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Customer Signature \_\_\_\_\_ Date \_\_\_\_\_





# BENNETT DUNLOP

## DRIVING CHANGE

770 Broad St. Regina, SK S4R 8H7  
Phone: 1-306-522-6612 • Fax: 1-306-566-8238  
Toll Free: 1-866-522-6612  
www.bennettdunlopford.com

Promised: 06/11/2020 4:00:00 PM

**\*\* In Progress \*\*** Printed 06/11/2020 04:59 PM



PO  
Fleet #

Cashiered Date:

Page: 8

Tag

### \* Service Invoice Customer Copy \*

SO #: B48333

Advisor: Cindy		Invoice Date: 06/11/2020		Term: CHARGE	
License No	Odometer In	Odometer Out	Delivery Date	Stock No	
539LTG	279608	0	01/01/2009		
Year	Make	Model	Model No	Colour	
2009	DODGE	RAM TRUCK		UNKNOWN	
Vehicle ID No	Selling Dealer		SO Date	InServ Date	Location
1D3HV13TX9S758999			06/08/2020	01/01/2009	
Engine Size	5.7L V8 SFI OH		Fleet #		

Request/Concern

Type	CSR	Amount
LABOUR		\$1,646.99
PARTS		\$1,580.62
SUPPLIES		\$70.00
DISCOUNT		\$432.39
<b>SUB-TOTAL</b>		<b>\$2,865.22</b>
GST		\$143.26
PST		\$171.91
<b>TOTAL INVOICE</b>		<b>\$3,180.39</b>

\*\*\* IF YOU HAVE HAD YOUR WHEELS REMOVED DURING YOUR SERVICE THIS VISIT, PLEASE RETURN TO THE DEALERSHIP AFTER DRIVING 160 KMS TO HAVE THE LUG NUTS RE-TORQUED FOR YOUR SAFETY \*\*\*

#### Additional Work Authorization

Date/Time	Contact	Description	Add Amount	Total
06/09/2020 10:00	Phone	Queen City Excavating INC. (306) 737-3227	173.99	
06/09/2020 10:00	Phone	Queen City Excavating INC. (306) 737-3227	107.13	
06/08/2020 12:55	Phone	Queen City Excavating INC. (306) 737-3227	89.90	
06/09/2020 10:00	Phone	Queen City Excavating INC. (306) 737-3227	448.26	
06/10/2020 16:48	Phone	Queen City Excavating INC. (306) 737-3227	401.75	
06/09/2020 10:00	Phone	Queen City Excavating INC. (306) 737-3227	442.76	
06/09/2020 10:00	Phone	Queen City Excavating INC. (306) 737-3227	346.50	
06/08/2020 12:55	Phone	Queen City Excavating INC. (306) 737-3227	89.90	
06/09/2020 10:00	Phone	Queen City Excavating INC. (306) 737-3227	955.20	

#### Recommended/Deferred Services

GEN front pinion and side bearings

Def Total 1,511.75 Rec Severity

#### PRIVACY STATEMENT

Personal Information is collected in accordance with applicable privacy legislation and is governed by Bennett Dunlop Ford's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Customer Signature \_\_\_\_\_ Date \_\_\_\_\_







# BENNETT DUNLOP

## DRIVING CHANGE

770 Broad St. Regina, SK S4R 8H7  
Phone: 1-306-522-6612 • Fax: 1-306-566-8238  
Toll Free: 1-866-522-6612  
www.bennettdunlopford.com

Promised: 06/11/2020 4:00:00 PM

**\*\* In Progress \*\*** Printed 06/11/2020 04:59 PM



PO  
Fleet #

Cashiered Date:

Page: 9

Tag

**\* Service Invoice Customer Copy \***

SO #: B48333

Advisor: Cindy		Invoice Date: 06/11/2020		Term: CHARGE	
License No	Odometer In	Odometer Out	Delivery Date	Stock No	
539LTG	279608	0	01/01/2009		
Year	Make	Model	Model No	Colour	
2009	DODGE	RAM TRUCK		UNKNOWN	
Vehicle ID No	Selling Dealer		SO Date	InServ Date	Location
1D3HV13TX9S758999			06/08/2020	01/01/2009	
Engine Size	5.7L V8 SFI OH		Fleet #		

Request/Concern	Type	CSR	Amount
GEN rear main seal leaking			1,283.40
GEN trans pan gasket and filter			510.21
GEN trans oil cooler lines from trans			458.50
GEN rad leaking at tank seam			726.80
Total:			<b>4,490.66</b>

### PRIVACY STATEMENT

Personal Information is collected in accordance with applicable privacy legislation and is governed by Bennett Dunlop Ford's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy ([www.ford.ca](http://www.ford.ca)) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

Customer Signature \_\_\_\_\_ Date \_\_\_\_\_

