

CONTRACT 88717



Bob's Transmissions
700 Pembina Hwy.
Winnipeg, MB R3M 2M6
Phone: 204-475-5590 Fax: 204-475-5686
Building Relationships One Transmission at a Time

04/19/2024 10:16:02 AM
Invoice #
38276
GST #R103580678 RT0001

Suds Truck Service
Kevin
80 Clear Springs Road
Steinbach, MB

PAID

2010 Dodge Pickup R3500
Odometer In: 550567

VIN: 3D73YCL0SAG158740
Eng: 6.7L In-Line6 (408CI)

Vehicle Time In: 4/15/2024 4:16:26PM

Vehicle Time Out: 4/19/2024 10:15:53AM

Description Of Services

Transmission not working
rebuild

Check transmission, pull for rebuild

TRANSMISSION ASSEMBLY - Remove & Replace - R2500,R3500,4WD

Description		Quantity	Sale	Extended
Rebuilt 68RFE Transmission		1.00	\$4,800.00	\$4,800.00
Labor: \$816.75	Parts: \$4,800.00	Sublet: \$0.00	Subtotal: \$5,616.75	

"HOT OIL FLUSH" Transmission Cooling System

Description		Quantity	Sale	Extended
CASTROL TRANSMAX		14.00	\$11.29	\$158.06
Labor: \$73.80	Parts: \$158.06	Sublet: \$0.00	Subtotal: \$231.86	

BOB'S TRANSMISSIONS
700 PEMBINA HWY
WINNEPEG, MB R3M 2M6
204-475-5590

DEBIT SALE

REF: 00000001
Batch: 004 JPR: 301042000418
04/19/24 10:16:02
APPR CODE: 00777
Trace: 1
DEBIT/CHQ/AMOUNT
Chip

AMOUNT \$6,233.24

APPROVED - 90

Winnipeg
AD: AUGUST 27/20
TAC: 10 10 10 10 10
TAC: 10 10

to be done along with the necessary material and permission to operate the car or truck herein for the purpose of testing and/or inspection. I acknowledged on above car or truck to secure the parts is set by the parts manufacturer and labor is a first. Warranty work has to be performed in our repair.

Labor Total:	\$890.55
Parts Total:	\$4,958.06
Shop Sup.:	\$62.81
Enviro Fee:	\$25.00
Sub Total:	\$5,936.42
Tax Total:	\$296.82
Grand Total:	\$6,233.24
Balance Due:	\$0.00



Date

2f499b73-fb6d-4080-af4f-f3916402f11 (3024 x 4032)

