




Box 430 • Highway #6 South  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2288 • Fax: 306-7464559  
 www.youngs.ca



Regina 306-565-2405  
 Assiniboia 306-642-5991  
 Chamberlain 306-638-4516  
 Davidson 306-567-3074  
 Moose Jaw 306-694-1800  
 Watrous 306-946-3387  
 Weyburn 306-842-2629  
 Windthorst 306-224-2110

Ship To:

Invoice To:



Branch RAYMORE		
Date 06/29/22	Time 15:21:15 (O)	Page 02
Account # BARBI001	Phone # 3065692484	Inv # W06835
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson S87

**SERVICE INVOICE**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
007323		X JEE0074009		
		TRACTOR		
		9380		
			PARTS	452.37
			LABOR	592.10
			shop supplies	47.36
			SUB TOTAL==>	1091.83
			GST 5%	54.59
006451		XXXXXXXXXXXXXXXXXX	TOTAL CREDIT CARD	1146.42

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

- It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
- Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
- An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
- Estimates are for the items specifically identified in the estimate only, and are non-binding.

X

Received By

GST # 894516046

*Leading The Way In A Thriving Agricultural Community!*

**Thank You!**  
 We Appreciate Your Business



Box 430 • Highway #6 South  
 Raymore, SK S0A 3J0  
 Phone: 306-746-2288 • Fax: 306-7464559  
 www.youngs.ca



Regina 306-565-2405  
 Assiniboia 306-642-5991  
 Chamberlain 306-638-4516  
 Davidson 306-567-3074  
 Moose Jaw 306-694-1800  
 Watrous 306-946-3387  
 Weyburn 306-842-2629  
 Windthorst 306-224-2110

Ship To:

Branch <b>RAYMORE</b>		
Date 06/29/22	Time 15:21:15 (O)	Page 01
Account # BARBI001	Phone # 3065692484	Inv # W06835
Ship Via	Purchase Order #	
Tax ID #		
<b>CUSTOMER COPY</b>		Salesperson 887

**SERVICE INVOICE**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
007323		X JEE0074009		
TRACTOR				
9380				

SEGMENT# 1 C INTER N/A 06/01/22 06/01/22

CAB FAN NOT WORKING

CORRECTION:

TS June 1/2 2022- Removed side shield on the evap box under hood. Turned fan on and listened in all speeds, fan didnt sound very good. Tested for power in all positions, had 12v. Fan is the issue.

-Unhooked tractor from drill and brought into shop, took apart evap box and removed the pressurization fan and then the cab fan, replaced the cab fan and put pressurization fan back in, put box together and tried new fan, worked great and had way more air flow.

-Took tractor out and hooked to drill

1343938C2	RESISTOR	1	134.07	134.07
355190A1C	CORE-DISTRIBUTO	1-	63.75	63.75-
355190A1R	REMAN-DISTRIBUT	1	318.30	318.30
355190A1C	CORE-DISTRIBUTO		63.75	63.75
	PARTS			452.37
	LABOR			592.10
11008007	SEGMENT TOTAL==>			1044.47

SEGMENT# 2 C INTER QC 06/01/22 06/02/22

Young's Complimentary QuickCheck Inspection

CORRECTION:

TS June 2/22-Preformed quick check

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.  
 • It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.  
 • Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.  
 • An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.  
 • Estimates are for the items specifically identified in the estimate only, and are non-binding.

X

Received By