



BBJ FIVE STAR SERVICE INC
 BOX 26092, REGINA, SASK S4R 8R7
 TEL 306-721-0655 FAX 306-721-0250

INVOICE

Invoice No.: 53281
 Date: 11/01/2022
 Ship Date:
 Page: 1
 Re: Order No.

Sold to:



Ship to:



Business No.: 865473698RT0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			JOB #1 - COOLANT LEAK	11		
			^ PRESSURE TESTED COOLING SYSTEM & FOUND LOWER RAD HOSE 90 LEAKING			
			^ FOUND TEE FITTING OFF HEATER HOSES LEAKING			
			^ REMOVED 90 ON LOWER RAD HOSE & FOUND STEEL PART NOT ATTACHED TO RAD			
			^ REATTACHED & INSTALLED NEW 90 & CLAMPS			
			^ RECHECKED FOR LEAKS & TOPPED UP, ALL OK AFTER REPAIRS			
			PARTS			
28634	EACH	1.0	5/8 TEE	11	5.20	5.20
21891	EACH	1.0	90 DEGREE RAD HOSE	11	51.01	51.01
SSTC5-44	Each	2.0	#44 SMART SEAL TENSION CLAMP	11	6.24	12.48
SSTC5-16	Each	4.0	#16 SMART SEAL TENSION CLAMP	11	4.52	18.08
HHARCA459	Each	1.0	HOSE CONNECTOR METAL 3/4 Y	11	35.15	35.15
HH65033	Feet	1.5	HEATER HOSE 3/4" HI MILER	11	5.30	7.95
			PARTS TOTAL \$129.87			
LB4110	Each	3.0	LABOUR	11	135.00	405.00
			JOB TOTAL \$534.87			
			JOB #2 - STARTER SHORTING OUT			
			^ STARTER WORKING EVERYTIME TRIED			
			^ REPLACED STARTER MOTOR & TESTED			
			^ CLEANED CABLE ENDS AT STARTER			
			PARTS			
8200308	EACH	1.0	STARTER	11	627.50	627.50
			PARTS TOTAL \$627.50			
LB4110	Each	4.0	LABOUR	11	135.00	540.00
			JOB TOTAL \$1,167.50			
			JOB #3 - MIRROR / WINDOW SWITCH			

Terms: Net 30. Due 12/01/2022.

Comment: No returns on electrical components. Returns after 30 days are subject to a 20% restocking fee.

Continue...



BBJ FIVE STAR SERVICE INC
 BOX 26092, REGINA, SASK S4R 8R7
 TEL 306-721-0655 FAX 306-721-0250

INVOICE

Invoice No.: 53281
 Date: 11/01/2022
 Ship Date:
 Page: 2
 Re: Order No.

Sold to:



Ship to:



Business No.: 865473698RT0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
5012212R1	EACH	1.0	^ DRIVER SIDE WINDOW NOT GOING UP ^ TESTED MOTOR, OK - REPLACED WINDOW SWITCH ^ INSTALLED PREVIOUSLY ORDERED PARTS - HORN COVER, CONVEX MIRROR & MIRROR MOTOR *NOTE: PARTS PREVIOUSLY BILLED - MIRROR MOTOR, HORN PAD & MIRROR GLASS (RE INV# 53190)* PARTS L/H WINDOW SWITCH	11	697.00	697.00
LB4110	Each	2.0	PARTS TOTAL \$697.00 LABOUR JOB TOTAL \$967.00	11	135.00	270.00
SS	EACH	1.0	SHOP SUPPLIES	11	60.75	60.75
Subtotal:						2,730.12
11 - GST @ 5%, PST @ 6%						
GST						136.51
PST						163.81
GST: #865473698 PST: #1834167						

Shipped By:	Tracking Number:	Total Amount	3,030.44
Terms: Net 30. Due 12/01/2022.		Amount Paid	0.00
Comment: No returns on electrical components. Returns after 30 days are subject to a 20% restocking fee.		Amount Owing	3,030.44
Sold By:			