

Box 337 Highway 39 N. Weyburn, SK, S4H 2K1

Phone: 306-842-4686 www.southcountry.ca Moose Jaw, SK 306-692-2371 Mossbank, SK 306-354-2411 Assiniboia, SK 306-642-3366 Emerald Park, SK 306-721-5050 Weyburn, SK 306-842-4686 Southey, SK 306-726-2155 Raymore, SK 306-746-2110 Montmartre, SK 306-424-2212

1H0S680STH0795953



Invoice To Account No:

Deliver To:

SERVICE INVOICE

1H0S680STH0795953

Internal Used Stock No. 141254	Internal Used Stock No. 141254	Invoice Number:	617430
		Invoice Date	03/15/2023
		Location:	05
	ll .	Work Order Number:	215061
		Payment Type:	Account
Bus Phone:	Bus Phone:		
Prv Phone:	Prv Phone:	Page:	1 of 12
Make/Model:	Meter Serial Number:	EQ ld:	Fleet No:

1887

Service Reminders:

/SPS680 F Internal

COMPLAINT:

02 GREENLIGHT SERVICE INSPECTION COMBINE

2017 JOHN DEERE 2017 JD S680 COMBINE

CAUSE:

CORRECTION:

Labor: \$1,899.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$1,899.00

/GLOPCLEANS680 F Internal

COMPLAINT:

03 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST **INCLUDES SALES WASH CREDIT**

CAUSE:

CORRECTION:

Miscellaneous	<u>Description</u>		<u>0</u>	Quantity	Net Price	Extended Price	Taxed Ind
GLWASHDISC	GREENLIGHT WASH	HING DISCOUNT		1.00	-\$708.50	-\$708.50	N
SERVACCESS	SERVICE ACCESSO	PRIES		1.00	\$89.00	\$89.00	N
Labor: \$1,962.00	Parts: \$0.00	OL&M: \$0.00	Misc: -\$	619.50	Sub-Total:	\$1,342.50	

/120284S680 F Internal

COMPLAINT:

04 INSTALL TOOL BOX - MISSING

CAUSE:

CORRECTION:

INSTALLED TOOL BOX.



Weyburn, SK, S4H 2K1 Phone: 306-842-4686 www.southcountry.ca Moose Jaw, SK 306-692-2371 Mossbank, SK 306-354-2411 Assiniboia, SK 306-642-3366 Emerald Park, SK 306-721-5050 Weyburn, SK 306-842-4686 Southey, SK 306-726-2155 Raymore, SK 306-746-2110 Montmartre, SK 306-424-2212



Invoice To Account No:

Deliver To:

SERVICE INVOICE

Internal Used Stock No. 141254	Internal Used	Stock N	No. 141254	Invoice Number:	617430
				Invoice Date	03/15/2023
				Location:	05
				Work Order Number:	215061
				Payment Type:	Account
Bus Phone:	Bus Phone:				
Prv Phone:	Prv Phone:			Page:	2 of 12
Make/Model:	-11	Meter	Serial Number:	EQ Id:	Fleet No:
2017 JOHN DEERE 2017 JD S680 COMBIN	IE	1887	1H0S680STH0795953	1H0S680STH0795953	B

Service Reminders:

<u>PartNumber</u>	Description		Quantity	Net Price	Extended Price	Taxed Ind
RE275591	TOOLBOX		1.00	\$111.19	\$111.19	N
<u>Miscellaneous</u>	<u>Description</u>		Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSOR	RIES	1,00	\$1.96	\$1.96	N
Labor: \$32.60	Parts: \$111.19	OL&M: \$0.00	Misc: \$1.96	Sub-Total:	\$145.75	

Gen5- Internal

COMPLAINT:

05 DIAGNOSE CODE LC2 3778.03 - CHOPPER PROXIMITY SENSOR

CAUSE:

CORRECTION:

TESTED SENSOR AND WAS GOOD, CHECKED WIRING PINS AND ALL LOOKS GOOD AS WELL. CLEARED CODE AND TESTED UNIT, CODE DID NOT SHOW UP AGAIN WHILE RUNNING UNIT. SUSPECTING CHOPPER NOT DOWN ALL THE WAY OR BAD CONNECTION

Miscellaneous	<u>Description</u>			Quantity	<u>Net Price</u>	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSO	PRIES		1.00	\$9.78	\$9.78	N
Labor: \$163.00	Parts: \$0.00	OL&M: \$0.00	Misc:	\$9.78	Sub-Total:	\$172.78	

/10171220S680 F Internal

COMPLAINT:

06 FEEDER HOUSE CONVEYOR CHAIN SLATS, R&R 3

CAUSE:

CORRECTION:

LOOSENED FEEDER HOUSE BELT AND CHAIN. SPUN OVER CONVEYOR CHAIN TILL FOUND BENT SLATS. REMOVED BENT SLATS AND INSTALLED NEW ONES, MADE SURE OF PROPER DIRECTION.

<u>PartNumber</u>	Description	Quantity	Net Price	Extended Price	Taxed Ind
14M7517	LOCK NUT	12.00	\$2.23	\$26.76	N
19M7402	CAP SCREW	12.00	\$2.04	\$24.48	N
HXE24328	Slat	3.00	\$138.95	\$416.85	N



Highway 39 N. Weyburn, SK, S4H 2K1 Phone: 306-842-4686 www.southcountry.ca

306-692-2371 Moose Jaw, SK Mossbank, SK 306-354-2411 Assiniboia, SK 306-642-3366 Emerald Park, SK 306-721-5050 306-842-4686 Weyburn, SK 306-726-2155 Southey, SK 306-746-2110 Raymore, SK 306-424-2212 Montmartre, SK



SERVICE INVOICE

Invoice To Account No: Deliver To: 617430 Internal Used Stock No. 141254 Invoice Number: Internal Used Stock No. 141254 03/15/2023 Invoice Date Location: 05 215061 Work Order Number: Payment Type: Account Bus Phone: Bus Phone: 3 of 12 Prv Phone: Prv Phone: Page: Meter Serial Number: EQ ld: Fleet No:

Make/Model: 1887 1H0S680STH0795953 1H0S680STH0795953 2017 JOHN DEERE 2017 JD S680 COMBINE

Service Reminders:

Extended Price Taxed Ind Quantity Net Price Description Miscellaneous \$14.67 \$14.67 SERVICE ACCESSORIES 1.00 **SERVACCESS**

Misc: \$14.67 Sub-Total: \$727.26 Labor: \$244.50 Parts: \$468.09 OL&M: \$0.00

GEN7- Internal

COMPLAINT:

07 REMOVE AND STRAIGHTEN 2 FEED ACCELERATOR WINGS

CAUSE:

CORRECTION:

REMOVED FEED ACCELERATOR WINGS, SPLIT THE 2 WINGS APART AND STRAIGHTENED IN PRESS.

Labor: \$244.50	Parts: \$44.72 OL&M: \$0.00	Misc: \$14.67	Sub-Total: \$303.89
SERVACCESS	SERVICE ACCESSORIES	1.00	\$14.67 \$14.67 N
Miscellaneous	<u>Description</u>	Quantity	Net Price Extended Price Taxed Ind
H150316	BOLT	6.00	\$3.77 \$22.62 N
H137329	LOCK NUT	6.00	\$2.90 \$17.40 N
19M7786	SCREW	2.00	\$2.35 \$4.70 N
<u>PartNumber</u>	<u>Description</u>	Quantity	Net Price Extended Price Taxed Ind

GEN8- Internal

COMPLAINT:

08 FILL HOLE UNDER CAB

CAUSE:

CORRECTION:

FILLED HOLE UNDER CAB WITH SILICONE.

Net Price Extended Price Taxed Ind Quantity **Miscellaneous** Description \$2.45 Ν 1.00 \$2.45 SERVACCESS SERVICE ACCESSORIES Sub-Total: Misc: \$2.45 \$43.20 Parts: \$0.00 Labor: \$40.75 OL&M: \$0.00



Box 337 Highway 39 N. Weyburn, SK, S4H 2K1 Phone: 306-842-4686 www.southcountry.ca Moose Jaw, SK 306-692-2371 Mossbank, SK 306-354-2411 306-642-3366 Assiniboia, SK 306-721-5050 Emerald Park, SK Weyburn, SK 306-842-4686 306-726-2155 Southey, SK Raymore, SK 306-746-2110 Montmartre, SK 306-424-2212



Invoice To Account No:

Deliver To:

SERVICE INVOICE

Invoice To Account No:	Deliver 10.			OLIV	VIOL III	10101
Internal Used Stock No. 141254	Internal Used	Stock N	lo. 141254	Invoice Number:		617430
monar occurrent in the				Invoice Date	C	3/15/2023
				Location:		05
				Work Order Number:		215061
				Payment Type:		Account
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:			Page:		4 of 12
Make/Model:		Meter	Serial Number:	EQ ld:	Fleet No:	
2017 JOHN DEERE 2017 JD S680 COMBINE		1887	1H0S680STH0795953	1H0S680STH0795953		
2017 001111 22212 2011 02 2011						

Service Reminders:

COMPLAINT:

09 REPLACE ELECTROMAGNETIC CLUTCH RUBBER STRAP

CAUSE:

CORRECTION:

UNHOOKED CONNECTOR, REMOVED BOLT FROM STRAP AND REMOVED OLD STRAP. INSTALLED NEW STRAP. HOOKED CONNECTOR BACK UP, RE-INSTALLED BOLT AND TIGHTENED.

Labor: \$48.90	Parts: \$8.72	OL&M: \$0.00	Misc:	\$2.93	Sub-Total:	\$60.55	
SERVACCESS	SERVICE ACCESSOR	RIES		1.00	\$2.93	\$2.93	N
Miscellaneous	<u>Description</u>			Quantity	Net Price	Extended Price	Taxed Ind
H134773	STRAP			1.00	\$8.72	\$8.72	N
<u>PartNumber</u>	<u>Description</u>			Quantity	Net Price	Extended Price	Taxed Ind

/1415190S680 F Internal

COMPLAINT:

10 INSTALL FILLER PLATES IN CONCAVE - LOCATED IN CAB OR SALES SHELF

CAUSE:

CORRECTION:

INSTALLED FILLER PLATES.

Miscellaneous	<u>Description</u>			Quantity	<u>Net Price</u>	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSO	RIES		1.00	\$4.89	\$4.89	N
Labor: \$81.50	Parts: \$0.00	OL&M: \$0.00	Misc:	\$4.89	Sub-Total:	\$86.39	

GEN11- Internal

COMPLAINT:

11 REPLACE FRONT ROTOR TRI FLOW FEED RAMP, MAY HAVE TO REMOVE ROTOR

CAUSE:

CORRECTION:



Weyburn, SK, S4H 2K1 Phone: 306-842-4686 www.southcountry.ca

Moose Jaw, SK 306-692-2371 Mossbank, SK 306-354-2411 Assiniboia, SK 306-642-3366 Emerald Park, SK 306-721-5050 Weyburn, SK 306-842-4686 Southey, SK 306-726-2155 Raymore, SK 306-746-2110 Montmartre, SK 306-424-2212



Invoice To Account No:

Deliver To:

SERVICE INVOICE

	-				– –	
Internal Used Stock No. 141254	Internal Used	Stock No	o. 141254	Invoice Number:		617430
				Invoice Date		03/15/2023
				Location:		05
			11	Work Order Number:		215061
				Payment Type:		Account
Bus Phone:	Bus Phone:					
Prv Phone:	Prv Phone:			Page:		5 of 12
Make/Model:		Meter	Serial Number:	EQ ld:	Fleet No:	
2017 JOHN DEERE 2017 JD S680 COMBINE		1887	1H0S680STH0795953	3 1H0S680STH0795953		

Service Reminders:

GOT FEEDER HOUSE TOOL FROM OUTSIDE. REMOVED FEEDER HOUSE AND SHIELDS COVERING FEED ACCELERATOR. REMOVED FEED ACCELERATOR WINGS. REMOVED SHOE AUGER TRAP DOOR ARMS AND LEVER. REMOVED FRONT 1 PIECE PLATE HOLDING THE 3 FEED PLATES TOGETHER. REMOVED HARDWARE HOLDING IN BROKEN TRI-FLOW FEED RAMP. REMOVED BROKEN FEED RAMP PIECE. FOUND BROKEN TACK WELD ON FEED RAMP SUPPORT. BENT SUPPORT BACK TO SHAPE AND WELDED INTO PLACE. INSTALLED NEW FEED RAMP. TORQUED FEED RAMP HARDWARE, 15MM TO 54FT-LBS AND 18MM TO 84 FT-LBS AS PER SPEC. RE-INSTALLED SHOE AUGER TRAP DOOR ARMS AND LEVER. RE-INSTALLED THE FRONT 1 PIECE PLATE. RE-INSTALLED FEED ACCELERATOR WINGS AND WEAR STRIPS. TORQUED WINGS TO 54 FT-LBS AND WEAR STRIPS TO 79 FT-LBS AS PER SPEC. RE-INSTALLED FEEDER HOUSE. RE-CONNECTED LINES TO FEEDER HOUSE CYLINDERS. TORQUED FEEDER HOUSE BOLTS TO 550 FT-LBS AS PER SPEC. PUT FEED PLATE BACK UP IN POSITION.

<u>PartNumber</u>	<u>Description</u>	Quantity	Net Price	Extended Price	Taxed Ind
11M7028	COTTER PIN	1.00	\$0.75	\$0.75	N
24M7296	WASHER	2.00	\$1.72	\$3.44	N
H174755	BOLT	3.00	\$3.15	\$9.45	N
H203557	Housing	1.00	\$1,367.01	\$1,367.01	N
Miscellaneous	<u>Description</u>	Quantity	Net Price	Extended Price	Taxed Ind
FREIGHT	FREIGHT	1.00	\$15.00	\$15.00	N
FREIGHT	FREIGHT	1.00	\$40.00	\$40.00	N
FREIGHT	FREIGHT	1.00	\$50.00	\$50.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	\$89.00	\$89.00	N

Misc:

\$194.00

Sub-Total:

\$7,442.65

OL&M: \$0.00

/10180250AS680 F Internal

COMPLAINT:

Labor: \$5,868.00

12 CONCAVE LEVEL, ADJUST, AND CALIBRATE (WITH ACI)

Parts: \$1,380.65

CAUSE:

CORRECTION:

LEVELED, ADJUSTED AND CALIBRATED CONCAVES AS PER MANUAL.

<u>Miscellaneous</u>	<u>Description</u>			Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES			1.00	\$22.01	\$22.01	N
Labor: \$366.75	Parts: \$0.00	OL&M: \$0.00	Misc:	\$22.01	Sub-Total:	\$388.76	

/110081S680 F Internal

COMPLAINT:



Box 337 Highway 39 N. Weyburn, SK, S4H 2K1 Phone: 306-842-4686 www.southcountry.ca

306-692-2371 Moose Jaw, SK 306-354-2411 Mossbank, SK Assiniboia, SK 306-642-3366 Emerald Park, SK 306-721-5050 Weyburn, SK 306-842-4686 306-726-2155 Southey, SK Raymore, SK 306-746-2110 306-424-2212 Montmartre, SK



Invoice To Account No:	Deliver To:			SER	VICE IN	IVOICE
Internal Used Stock No. 141254	Internal Used	Stock N	lo. 141254	Invoice Number:		617430
				Invoice Date		03/15/2023
			ll l	Location:		05
				Work Order Number:		215061
	11][Payment Type:		Account
Bus Phone:	Bus Phone:		11			
Prv Phone:	Prv Phone:			Page:		6 of 12
Make/Model:		Meter	Serial Number:	EQ ld:	Fleet No:	
2017 JOHN DEERE 2017 JD S680 COMBINE		1887	1H0S680STH0795953	1H0S680STH0795953		

Service Reminders:

13 R&R SIEVE & CHAFFER TO CHECK FOR CRACKS

CAUSE:

CORRECTION:

DROPPED CHAFFER TAILBOARD DOWN. UNHOOKED CHAFFER ELEMENT ELECTRICAL CONNECTOR. FOUND CONNECTOR LOCK WAS BROKEN. REMOVED CHAFFER ELEMENT. UNHOOKED SIEVE ELECTRICAL CONNECTOR, REMOVED SIEVE ELEMENT. CHECKED FOR CRACKS AND FOUND NONE. RE-INSTALLED SIEVE ELEMENT, PLUGGED CONNECTOR BACK IN. TORQUED HARDWARE TO 27 FT-LBS, SET LOUVERS TO 5MM AND CALIBRATED. RE-INSTALLED CHAFFER ELEMENT. TORQUED HARDWARE TO 27 FT-LBS, SET LOUVERS TO 5MM AND CALIBRATED. SET MANUAL LOUVERS TO 8MM. RE-INSTALLED CHAFFER TAILBOARD.

Miscellaneous	Description			Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSO	RIES		1.00	\$29.34	\$29.34	N
Labor: \$489.00	Parts: \$0.00	OL&M: \$0.00	Misc:	\$29.34	Sub-Total:	\$518.34	

/120009S680 F Internal

COMPLAINT:

15 REPLACE CHOPPER STATIONARY KNIVES

CAUSE:

CORRECTION:

REMOVED KNIFE BANK. REMOVED OLD KNIVES AND CLEANED CHAFF OUT. INSTALLED NEW KNIVES. RE-INSTALLED KNIFE BANK.

<u>PartNumber</u>	<u>Description</u>	Quantity	Net Price Extended Price Taxed Ind
H215004	BLADE	39.00	\$16.08 \$627.12 N
Miscellaneous	Description	Quantity	Net Price Extended Price Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$7.34 \$7.34 N
Labor: \$122.25	Parts: \$627.12 OL&M: \$0.00	Misc: \$7.34	Sub-Total: \$756.71

/10172010S680 F Internal

COMPLAINT:

16 HAMMER, STRAW CHOPPER R&R, REPLACE 1 SET - RECOMMEND REPLACING ALL



Box 337 Highway 39 N. Weyburn, SK, S4H 2K1 Phone: 306-842-4686 www.southcountry.ca

306-692-2371 Moose Jaw, SK Mossbank, SK 306-354-2411 Assiniboia, SK 306-642-3366 Emerald Park, SK 306-721-5050 Weyburn, SK 306-842-4686 Southey, SK 306-726-2155 Raymore, SK 306-746-2110 Montmartre, SK 306-424-2212



Invoice To Account No:	Deliver To:			SER	VICE INVOICE
Internal Used Stock No. 141254	Internal Used	d Stock N	lo. 141254	Invoice Number:	617430
				Invoice Date	03/15/2023
				Location:	05
				Work Order Number:	215061
				Payment Type:	Account
Bus Phone:	Bus Phone:				
Prv Phone:	Prv Phone:			Page:	7 of 12
Make/Model:	41	Meter	Serial Number:	EQ ld:	Fleet No:
2017 JOHN DEERE 2017 JD S680 COMB	INF	1887	1H0S680STH0795953	1H0S680STH0795953	

Service Reminders:

CAUSE:

CORRECTION:

REMOVED CHOPPER FLOW RAMP. REMOVED AND REPLACED ALL STRAW CHOPPER HAMMERS. REPLACED 4 SETS OF BUSHINGS AS THEY WERE WORN MORE THAN THE REST. TORQUED HAMMER BOLTS TO 44 FT-LBS AS PER SPEC. REINSTALLED CHOPPER FLOW RAMP. RAN COMBINE AND PARKED

PartNumber	<u>Description</u>	Quantity	Net Price Extended Price Taxed Ind
HXE118760	Lock Nut	22.00	\$2.67 \$58.74 N
HXE119246	Cap Screw	22.00	\$5.18 \$113.96 N
HXE59496	Bushing	8.00	\$16.52 \$132.16 N
KXE10255	Knife Kit	6.00	\$367.00 \$2,202.00 N
Miscellaneous	Description	Quantity	Net Price Extended Price Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$29.34 \$29.34 N
Labor: \$489.00	Parts: \$2,506.86 OL&M: \$0.00	Misc: \$29.34	Sub-Total: \$3,025.20

/15124S680 Internal

COMPLAINT:

17 REPLACE HOPPER CANVAS - FRONT LEFT HAND

CAUSE:

CORRECTION:

REMOVED HARDWARE AND OLD CANVAS. PULLED PINS OUT OF CANVAS STRAP. REMOVED METAL BRACE PLATES FROM INSIDE OLD CANVAS, FED RATCHET STRAP THROUGH NEW CANVAS AND PULLED NEW CANVAS STRAP THROUGH. REINSTALLED BRACE PLATES IN NEW CANVAS. TIGHTENED HARDWARE. INSTALLED PINS IN CANVAS STRAP.

PartNumber	Description	Quantity	Net Price E	Extended Price Taxed Ind
AXE15328	Strap	1.00	\$184.22	\$184.22 N
AXE17816	Canvas	1.00	\$382.14	\$382.14 N
Miscellaneous	<u>Description</u>	Quantity	Net Price E	Extended Price Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$14.67	\$14.67 N
Labor: \$244.50	Parts: \$566.36 OL&M: \$0.00	Misc: \$14.67	Sub-Total:	\$825.53

/15121S680 F Internal

COMPLAINT:

18 REPLACE ROTOR GEARCASE OIL



Weyburn, SK, S4H 2K1 Phone: 306-842-4686 www.southcountry.ca Moose Jaw, SK 306-692-2371 Mossbank, SK 306-354-2411 Assiniboia, SK 306-642-3366 Emerald Park, SK 306-721-5050 Weyburn, SK 306-842-4686 Southey, SK 306-726-2155 Raymore, SK 306-746-2110 Montmartre, SK 306-424-2212



Invoice To Account No:

Deliver To:

SERVICE INVOICE

Internal Used Stock No. 141254	Internal Used	Stock No	o. 141254	Invoice Number:	617430
				Invoice Date	03/15/2023
				Location:	05
				Work Order Number:	215061
				Payment Type:	Account
Bus Phone:	Bus Phone:				
Prv Phone:	Prv Phone:		1	Page:	8 of 12
Make/Model:	1.5	Meter	Serial Number:	EQ Id:	Fleet No:
2017 JOHN DEERE 2017 JD S680 COMBINE		1887	1H0S680STH079595	3 1H0S680STH0795953	

Service Reminders:

CAUSE:

CORRECTION:

LOOSENED PLUG IN GEARCASE DRAIN. LET DRAIN OVER NIGHT. TIGHTEN PLUG. FILL WITH GEAR OIL TO FULL LINE ON DIPSTICK.

Labor: \$163.00	Parts: \$52.43 OL&M: \$0.00	Misc: \$10.78	Sub-Total: \$226.21
SERVACCESS	SERVICE ACCESSORIES	1.00	\$9.78 \$9.78 N
EF50	ENVIRO FEE	2.00	\$0.50 \$1.00 N
Miscellaneous	Description	Quantity	Net Price Extended Price Taxed Ind
TY26815	3.78L 80W90 GL-5	1.00	\$52.43 \$52.43 N
PartNumber	<u>Description</u>	Quantity	Net Price Extended Price Taxed Ind

/141887S680 Internal

COMPLAINT:

19 CLEAN DEBRIS MANAGEMENT FILTERS

CAUSE:

CORRECTION:

REMOVED FILTERS FROM HOUSING. TOOK OUTSIDE AND BLEW FILTERS OUT. WIPED FILTER HOUSING OUT AND RE-INSTALLED FILTERS.

<u>Miscellaneous</u>	<u>Description</u>			Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES			1.00	\$4.89	\$4.89	N
Labor: \$81.50	Parts: \$0.00	OL&M: \$0.00	Misc:	\$4.89	Sub-Total:	\$86.39	

/150029S680 F Internal

COMPLAINT:

20 REPLACE CAB FILTERS & CLEAN PLASTIC GRATE

CAUSE:

CORRECTION:



Highway 39 N. Weyburn, SK, S4H 2K1 Phone: 306-842-4686 www.southcountry.ca Moose Jaw, SK 306-692-2371 Mossbank, SK 306-354-2411 Assiniboia, SK 306-642-3366 Emerald Park, SK 306-721-5050 Weyburn, SK 306-842-4686 Southey, SK 306-726-2155 306-746-2110 Raymore, SK Montmartre, SK 306-424-2212



Invoice To Account No:

Deliver To:

SERVICE INVOICE

Internal Used Stock No. 141254	Internal Used	Stock N	lo. 141254	Invoice Number:	617430
				Invoice Date	03/15/2023
				Location:	05
				Work Order Number:	215061
				Payment Type:	Account
Bus Phone:	Bus Phone:				
Prv Phone:	Prv Phone:			Page:	9 of 12
Make/Model:		Meter	Serial Number:	EQ Id:	Fleet No:
2017 JOHN DEERE 2017 JD S680 COMBIN	E	1887	1H0S680STH0795953	1H0S680STH0795953	

Service Reminders:

REMOVED OLD FILTERS. CLEANED GRATE OUT. INSTALLED NEW FILTERS.

PartNumber	<u>Description</u>	Quantity	Net Price Extended Price Taxed Ind
L214634	Cab Ricirculation Air Filter	1.00	\$43.30 \$43.30 N
RE284091	AIR FILTER	1.00	\$120.53 \$120.53 N
Miscellaneous	Description	Quantity	Net Price Extended Price Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$2.93 \$2.93 N
Labor: \$48.90	Parts: \$163.83 OL&M: \$0.00	Misc: \$2.93	Sub-Total: \$215.66

/120007\$680 F Internal

COMPLAINT:

21 CLEAN ENGINE AIR FILTERS

CAUSE:

CORRECTION:

REMOVED AIR FILTERS AND TOOK OUTSIDE TO BLOW OUT. WIPED FILTER HOUSING OUT AND RE-INSTALLED FILTERS.

Miscellaneous	<u>Description</u>			Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSO	RIES		1.00	\$7.34	\$7.34	N
Labor: \$122.25	Parts: \$0.00	OL&M: \$0.00	Misc:	\$7.34	Sub-Total:	\$129.59	

/120000\$680 F Internal

COMPLAINT:

22 CHANGE ENGINE OIL AND FILTER

CAUSE:

CORRECTION:

DRAINED ENGINE OIL. CHANGED FILTER AND MARKED HOURS. FILLED WITH NEW OIL TO FULL LINE ON DIPSTICK.

<u>PartNumber</u>	Description	Quantity	Net Price	Extended Price Taxe	d Ind
RE572785	Oil Filter	1.00	\$135.79	\$135.79	N
TY26679	18.9L 15W40 PLUS 50 II	2.00	\$169.05	\$338.10	N
Miscellaneous	<u>Description</u>	Quantity	Net Price	Extended Price Taxe	d Ind
EF100	ENVIRO FEE	1.00	\$1.00	\$1.00	N



Weyburn, SK, S4H 2K1 Phone: 306-842-4686 www.southcountry.ca Moose Jaw, SK 306-692-2371 Mossbank, SK 306-354-2411 Assiniboia, SK 306-642-3366 Emerald Park, SK 306-721-5050 Weyburn, SK 306-842-4686 Southey, SK 306-726-2155 Raymore, SK 306-746-2110 Montmartre, SK 306-424-2212



Invoice To Account No:

Deliver To:

SERVICE INVOICE

2017 JOHN DEERE 20 Service Reminders:	017 JD S680 COMBINE		1887	1H0S680STH079599	53 1H0S680	STH0795953	
Make/Model:			Meter	Serial Number:	EQ ld:		leet No:
Bus Phone: Prv Phone:		Bus Phone: Prv Phone:				Page:	10 of 12
					Work Order N Paymer		215061 Account
Internal Used Stock	No. 141254	Internal Used		lo. 141254		ce Date	617430 03/15/2023 05

/120018S680 F Internal

COMPLAINT:

23 REPLACE FUEL FILTERS, CLEAN FUEL PRE-SCREEN

CAUSE:

CORRECTION:

SHUT FUEL OFF. REMOVED OLD FILTERS. REMOVED SEDIMENT BOWL AND INSTALLED ON NEW FILTER. INSTALLED NEW FILTERS, MARKED HOURS. REMOVED FUEL PRE-SCREEN AND CLEANED. RE-INSTALLED FUEL PRE-SCREEN. TURNED FUEL BACK ON.

<u>PartNumber</u>	Description	Quantity	Net Price	Extended Price	Taxed Ind
DZ112918	Filter Element	1.00	\$211.54	\$211.54	N
RE539465	Filter Elem	1.00	\$168.30	\$168.30	N
<u>Miscellaneous</u>	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	\$1.00	\$1.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	\$7.34	\$7.34	N
Labor: \$122.25	Parts: \$379.84 OL&M: \$0.00	Misc: \$8.34	Sub-Total:	\$510.43	

/1007009S680 F Internal

COMPLAINT:

24 REPLACE HYDRAULIC FILTERS

CAUSE:

CORRECTION:

REMOVED OLD HYD FILTERS. INSTALLED NEW FILTERS AND MARKED HOURS.

<u>PartNumber</u>	Description	Quantity	Net Price	Extended Price	
AH128449	Hydraulic Oil Filter	1.00	\$132.02	\$132.02	N
AN207368	HYDRAULIC F	1.00	\$174.72	\$174.72	N



Box 337 Highway 39 N. Weyburn, SK, S4H 2K1 Phone: 306-842-4686

Phone: 306-842-4686 www.southcountry.ca Moose Jaw, SK 306-692-2371 Mossbank, SK 306-354-2411 Assiniboia, SK 306-642-3366 Emerald Park, SK 306-721-5050 Weyburn, SK 306-842-4686 Southey, SK 306-726-2155 Raymore, SK 306-746-2110 Montmartre, SK 306-424-2212



Invoice To Account No:

Deliver To:

SERVICE INVOICE

Internal Used Stock No. 141254	Internal Used Stock No. 141254	Invoice Number:	617430
		Invoice Date	03/15/2023
		Location:	05
		Work Order Number:	215061
		Payment Type:	Account
Bus Phone:	Bus Phone:		
Prv Phone:	Prv Phone:	Page:	11 of 12

 Make/Model:
 Meter
 Serial Number:
 EQ Id:
 Fleet No:

 2017 JOHN DEERE 2017 JD \$680 COMBINE
 1887
 1H0\$680\$TH0795953
 1H0\$680\$TH0795953

Service Reminders:

N309233 O-RING 1.00 \$23.36 \$23.36 Ν <u>Miscellaneous</u> **Description** Quantity Net Price Extended Price Taxed Ind EF100 **ENVIRO FEE** 1.00 \$1.00 \$1.00 Ν SERVACCESS SERVICE ACCESSORIES 1.00 \$7.34 \$7.34 Ν

Labor: \$122.25 Parts: \$330.10 OL&M: \$0.00 Misc: \$8,34 Sub-Total: \$460.69

/140517S680 F Internal

COMPLAINT:

25 ADJUST ALL BELTS AND CHAINS

CAUSE:

CORRECTION:

ADJUSTED ALL BELTS AND CHAINS.

<u>Miscellaneous</u>	<u>Description</u>		Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSO	PRIES	1.00	\$9.78	\$9.78	N
Labor: \$163.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$9.78	Sub-Total:	\$172.78	

/120014S680 F Internal

COMPLAINT:

26 GREASE COMBINE

CAUSE:

CORRECTION:

GREASED COMBINE.

<u>PartNumber</u>	Description	Quantity	Net Price Extended Price Taxed Ind
TY6341	SD POLYUREA GREASE	1.00	\$9.60 \$9.60 N
Miscellaneous	Description	Quantity	Net Price Extended Price Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$9.78 \$9.78 N
Labor: \$163.00	Parts: \$9.60 OL&M: \$0.00	Misc: \$9.78	Sub-Total: \$182.38

GEN27- Internal



Weyburn, SK, S4H 2K1 Phone: 306-842-4686 www.southcountry.ca Moose Jaw, SK 306-692-2371 Mossbank, SK 306-354-2411 Assiniboia, SK 306-642-3366 Emerald Park, SK 306-721-5050 Weyburn, SK 306-842-4686 Southey, SK 306-726-2155 Raymore, SK 306-746-2110 Montmartre, SK 306-424-2212



Net Price Extended Price Taxed Ind

SERVICE INVOICE Invoice To Account No: Deliver To: Internal Used Stock No. 141254 617430 Internal Used Stock No. 141254 Invoice Number: 03/15/2023 Invoice Date Location: 05 Work Order Number: 215061 Payment Type: Account Bus Phone: Bus Phone: Prv Phone: Prv Phone: Page: 12 of 12 Make/Model: Meter Serial Number: EQ Id: Fleet No: 2017 JOHN DEERE 2017 JD S680 COMBINE 1H0S680STH0795953 1887 1H0S680STH0795953

Service Reminders:

COMPLAINT:

27 REPLACE CHAFFER ELEMENT ELECTRICAL CONNECTOR

Description

CAUSE:

CORRECTION:

<u>PartNumber</u>

CUT RUBBER SEAL OFF OF OLD CONNECTOR. REMOVED OLD CONNECTOR AS CLIP WAS BROKE. REMOVED PINS FROM CONNECTOR AND RE-INSTALLED IN NEW CONNECTOR. PUT NEW SEAL ON CONNECTOR. PLUGGED IN TO CHAFFER ELEMENT AND TESTED.

Quantity

57M15804	Elec. Connector Acces	ssory		1.00	\$17.28	\$17.28	1
57M9786	Elec. Connector			1.00	\$10.99	\$10.99	1
Miscellaneous	<u>Description</u>			Quantity	Net Price	Extended Price	Taxed In
SERVACCESS	SERVICE ACCESSOR	RIES		1.00	\$8.51_	\$8.51	
Labor: \$141.45	Parts: \$28.27	OL&M: \$0.00	Misc:	\$8.51	Sub-Total:	\$178.23	
		=0			Labor	÷13,54	6.10
Customer PO No:				Parts: \$7,151		1.67	
Tax Exempt No:					OL&M	: \$	0.00
Advisor:	AMY REICH				Misc	-\$18	5.92
					GST:	: \$	0.00
GST Registration N	lo: 897357802				PST	: \$	0.00
Sundry G/L Entries					Total	: \$20,51	1.85
Br Dpt Acct Sub	Ref Descrip	otion					
00 00 160 1	141254			-			

TERMS AND CONDITIONS

Received by:	Date:
--------------	-------