

JS : CLOSED

ate: 6/11/2025

Date: 8/14/2025 12:24:28PM



CUSTOMER	SERVICE WRITER	SERIAL #	HOURS/KMS OUT	MILEAGE2 OUT
		5995819F	0	0
	SALES TYPE	TAG NUMBER	PERMIT	TERMS
	Regular or Over the Counter			COD
	YEAR / MAKE / MODEL			TAX CODE
	2006 / TRACKER / TARGA 175			MB
	BOAT # / COVER COLOUR / COLOUR / STYLE / ENGINE MAKE / ENGINE MODEL / ENGINE SERIAL # 1 / PLATE			PROMISED DATE
	M 8439 K 23 / N/A / GREY/BLACK / SIDE CONSOLE / MERC / 90 OPT EXLPTO 2S / 1B263643 / NONE			6/11/2025

T	Req	Fill	OEM	Item	Description	Bin	Your Price	Amount W	Stat
	2.00	2.00	LAND & SEA	232-WSH1PRDP	WINDSHIELD HOLDER CLIPS 1PR/CD	232	32.00	64.00	N P
	1.00	1.00	MERC	894919	KEY 2C	8	8.00	8.00	N P
	1.00	1.00	MERC	8M0054314	PRIMER BULB	8	35.00	35.00	N P
	4.00	4.00	MERC	8M0038500	LINE-FUEL-100	32	6.00	24.00	N P
	12.00	12.00	MERC	816311T	TIE STRAP	54	1.00	12.00	N P
	1.00	1.00	MERC	888725T02	FUEL PUMP	8	821.00	821.00	N P
	1.00	1.00	MERC	8M0122423	FUEL FILTER Quick	35	61.00	61.00	N P
	1.00	1.00	MERC	856880	CLAMP	54	6.00	6.00	N P
	1.00	1.00	MERC	857005A1	DIAPHRAM KIT	21	51.00	51.00	N P
L	8.00	8.00		LABOUR	LABOUR AT SHOP RATE		140.00	1,120.00	N

Estimated

Initial:

Final:

Totals

Item	1,082.00
Fee	0.00
Unit	0.00
Labor	1,120.00
Kit	0.00
Misc	0.00
Subtotal	2,202.00
Shop Fees	112.00
Ship By Will Call	0.00
Sales Tax	277.68
Total Due	2,591.68
Total Paid	2,591.68
Change	0.00

Tracking No.

Tax Authority Details

Authority Code

PST	161.9800
GST	115.7000

Payment Details

Amount	Type	Amount	Payment
2,591.68	Credit Card	2,591.68	8/14/2025

Misc Charges

Name	Amount	Tax
Hazardous Disposal Fee	0.00	0.00
Shop Fees	112.00	13.44
Sublet	0.00	0.00
Misc. Fees	0.00	0.00
Total	112.00	13.44

Service Requested

lost keys supply new keys for both motors
remove 8 Hp Yamaha plus controls and fast idle switch

keys for big motor are # 2 C

get clips for windshield installed new clips
 drain fuel tank for big motor there was only 5 liters of fuel in the tank
 charged battery and cleaned cable ends
 installed cables proper they were hooked up wrong
 removed fuel line/primer bulb installed new primer bulb and fuel line
 cleaned mice nest from under the top cowl
 run up with shop fuel
 motor would not start
 checked fuel/air pressure fuel pressure 40 PSI and air was 80 PSI fuel should be 90 PSI
 checked injectors fuel/air good
 checked low pressure fuel pump
 removed VST tank and take it apart
 was full of junk and old fuel
 tested fuel pumps and high pressure pump is shot
 replaced high pressure fuel pump
 run up with computer and shop fuel
 found water leak under the cowl mice chew hole in the water line repaired
 motor has 200 hours
 then the water in fuel alarm came on
 checked fuel is good
 then the alarm did not come on
 there was lots of mice shit under the cowl they were chewing some wires

 if motor acts up might need a new wiring harness on the motor

 customer should river test

 steering is stiff
 needs a battery

Repair Order Recommendation

YOU WILL BE REQUIRED TO PICK UP YOUR BOAT WITHIN 14 DAYS OF BEING NOTIFIED, OR A CHARGE OF \$5.00 PER DAY FOR STORAGE WILL BE ADDED TO YOUR REPAIR ORDER.

Disclaimer:

EMISSION WAIVER: I understand that I have the right to have emission service and/or adjustments done elsewhere.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicles to secure the amount of repairs thereto. Not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond our control.

X _____