

SEPTIC SYSTEM INTEGRITY TEST

Legal Description

Park Cypress Hills Subdivision Ben Vannoch Lot 23 Block 00 Property # 151083

Lessee Information

Name(s): Ministry of Parks, Culture and Sport

Cottage Address: 145 Ben Vannoch Drive

Phone No. 306 662 5411 Email: _____

Integrity Test

I/We consent that the park proceed with an integrity test of our septic system.

This will confirm that as of (date) September 13, 2023 the tank has been filled to the top of the tank/bottom of collar per the park official's instructions and the cottage will be vacant for at least the next 24 hours.

By signing below, I/We acknowledge that the test of our septic system does not create any warranty regarding the merchantability of the system, nor does this test guarantee the performance of our septic system after the date on which it was tested; any failure of the septic system is the responsibility of the cottage owner.

 9/13/23
Lessee (Signed) Date

Lessee (Signed) Date

TO BE COMPLETED BY PARK OFFICIAL

The septic system located at the cottage address above has been tested and the following results were found:

o 1st Measurement Result 27" Date 9/11/23 Time 9:00AM

o 2nd Measurement Result 27" Date 9/13/23 Time 10:00AM

☐ Failed: Test showed a fluctuation in the amount of liquid in the tank therefore it is deemed the septic system does not meet Canadian Standards Association (CSA) and the *Provincial Park Regulations, 1991* and therefore must be repaired/removed.

☒ Passed: Test showed no fluctuation in the amount of liquid in the tank therefore the park finds the septic system listed above satisfies CSA and the *Provincial Park Regulations, 1991*. This septic system will be subject to retesting in a minimum of 5 years.

Park Official Signature 

Date 9/13/23

Revised 10/21

Saskatchewan!