



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A210494

Station #: 71877

Station Name: Kryptonite Truck & Trailer Repair

Technician #: 91119

Technician Name: Adam Ensor

Signing Officer #: 91120

Signing Officer Name: Lisa Ensor

Customer Details:

Name: 101239314 Saskatchewan Ltd

Address: PO Box 1855, Kindersley, Saskatchewan, S0L 1S0

Inspection Completed Date: 13May2025

Inspection Expiry Date: 30Nov2025 ✓

Vehicle Details:

VIN: 5KKXAT005DPBX6859 ✓

Odometer Reading: 15756 km

Year: 2013 ✓

Vehicle Make/Model: WESTERN STAR/HEAVY VEHICLE ✓

Plate: 189 LRK ✓

Jurisdiction: Saskatchewan

Unit: 44 ✓

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71877

Station Name: Kryptonite Truck & Trailer Repair

Technician #: 91119

Technician Name: Adam Ensor

Signing Officer #: 91120

Signing Officer Name: Lisa Ensor

Customer Details:

Name: 101239314 Saskatchewan Ltd

Address: PO Box 1855, Kindersley, Saskatchewan, SOL 1S0

Vehicle Details:

VIN: 5KKXAT005DPBX6859

Odometer Reading: 15756 km

Year: 2013

Vehicle Make/Model: WESTERN STAR HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 35 degrees • Brake Stroke: 1 in

Wheel2-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 35 degrees • Brake Stroke: 1 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55 degrees • Brake Stroke: 1 in

Wheel2-On : Tire Tread Depth: 20 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55 degrees • Brake Stroke: 1 in

Axle 3-Pass

Wheel1 : Tire Tread Depth: 28 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 27 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55 degrees • Brake Stroke: 1 in

Wheel3-On : Tire Tread Depth: 27 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55 degrees • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 28 mm

Brake(1): No Brake

N/A

Axle 4-Pass

Wheel1 : Tire Tread Depth: 28 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 28 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55 degrees • Brake Stroke: 1 in

Wheel3-On : Tire Tread Depth: 28 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55 degrees • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 28 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A210494

Inspection Completed Date: 13May2025