

## Edmonton Master Filter


### Order Information

Internal WO #	27899
Company Name	NRIP Logistics
Contact	Nachos
Service Level	Gold
Filter Type	DPF
Cleaning Date	27/05/2024
Technician	Alex


### Visual Inspection

<p>Pre &amp; Post Inlet Images</p>		
<p>Pre &amp; Post Outlet Images</p>		
<p>Inlet Color - When Received</p>	<p>Black</p>	

## Edmonton Master Filter

Outlet Color - When Received	Cream
Filter Passed/Failed Final Inspection?	Passed
Technician Signature	

## Testing

Note	Testing results are available for DPF and EGR cleans only. There are no satisfactory testing methods for DOCs, SCRs and OneBox systems, and we are unable to guarantee the status of the wash coats on these catalysts.
Pre & Post Flow Reading Images	
Initial Flow Bench Test (in/hg)	2.10
Final Flow Bench Test (in/hg)	1.10
Flow Green Range (in/hg)	1.1-1.6
Clean Pin Gauge Depth	10"



## Edmonton Master Filter

Location Of Tested Cells	
Light Test	Pass

### Filter Details

Filter Manufacturer	PACCAR
Filter Part #	1906311

### Pneumatic Cleaning (All Service Levels)

Number of Defective Cells (DPF Only)	0
Minutes in Pneumatic Air Cycle	20

### Ultrasonic Cleaning (Gold Service Level Only)

Minutes in Ultrasonic Process	30
-------------------------------	----

### Flushing (Gold & Silver Service Levels)

Minutes in Flushing Process	20
-----------------------------	----

### Kilning (Gold, Silver & Bronze Service Levels)

Hours in Kiln Cycle	12
Minutes in Pneumatic Air Cycle	20