

89110

03877450

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Insp.
Box 45064, Regent Postal Out
Winnipeg, MB, R2C 5C7
1-204-985-0820

Manitoba



A907600

Date Inspection Started DAY: 26 MO: 03 YR: 25	Station Number A1581819	Station Name John White Trucking	City Winnipeg
Date Inspection Completed DAY: 26 MO: 03 YR: 25	Mechanic Number M1716141	Mechanic Signature John White	Station Phone Number 204-852-9510
Inspection Expiry Date DAY: 31 MO: 03 YR: 26	Vehicle Owner Nad Express	Address 27 Brough Bay Winnipeg MB	Postal Code R3C 2E6
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number C1A1A0570 Prov. MB NSC # Odometer Reading 258132.7 Odom. Type ☒ km ☐ mi	Vehicle Identification Number 1FNAFC1XDA181A04W127160 ☒ Confirmed legible Vehicle Identification Number on vehicle	Make Ford Model Cute Van Year 2010 Unit # 04

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X	X	Section 3 - Brake Systems: <u>3H</u> 3A Defects (if any) <u>Circle Brake Type</u> <u>18-g Brake Cal Thickness All</u> <u>18-d Caliper seized left side</u>																																																																						
		Brake Inspection Type: A B C <u>D</u> E Circle appropriate letter for Internal Brake Component Inspection <table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>0.714</td> <td>0.714</td> <td>1.386</td> <td>1.405</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>0.714</td> <td>0.714</td> <td>1.395</td> <td>1.409</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	0.714	0.714	1.386	1.405			2	0.714	0.714	1.395	1.409			3							4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	0.714	0.714	1.386	1.405																																																																				
2	0.714	0.714	1.395	1.409																																																																				
3																																																																								
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X	X	Section 8 - Body: Defects (if any) <u>18-d mirror glass cracked left side</u>																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth <u>3</u></th> <th colspan="4">Air Pressure <u>PSI</u></th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>16</td> <td>19</td> <td></td> <td></td> <td>95</td> <td>95</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>20</td> <td>18</td> <td>16</td> <td>18</td> <td>95</td> <td>98</td> <td>95</td> <td>95</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth <u>3</u>				Air Pressure <u>PSI</u>				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	16	19			95	95	100	100	2	20	18	16	18	95	98	95	95	3									4									5								
Axle	Tread Depth <u>3</u>				Air Pressure <u>PSI</u>																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	16	19			95	95	100	100																																																																
2	20	18	16	18	95	98	95	95																																																																
3																																																																								
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -
 This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

FVS0022-01-(R-09/15)

PRESENT THIS COPY WHEN REGISTERING VEHICLE

Ce document peut être obtenu en français sur demande.